



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3521M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH DOOR CHANNEL	CUT	104.25	104.25
1	REAR RH DOOR CHANNEL RUBBER	CUT	45.00	45.00
1	REAR RH DOOR DELTA MOULDING	CUT	30.00	30.00
	LESS 20% DISCOUNT		-35.85	-35.85
			143.40	143.40
LABOUR				
	PANEL BEATING.		700.00	480.00
	SPRAYPAINT.		300.00	200.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	120.00	-
			1,120.00	680.00
GRAND TOTAL			1,263.40	823.40
RECOMMENDED COST OF REPAIRS (CONFIRMED)				823.40

Report Ref No. NS/INC20008011/T1tf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.