

ASS. REC. BY: Sun PinREF: NTVC NS/INC20008012/Qvf3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: SGJ 7833GPolicy No. 5029826092-12Claims No. MT/1098479-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
<u>X</u>	<u>X</u>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD6159X Yr Regn: 05/08/2015Type: M.Car / M.Cycle / Bus / Van / Lorry Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1796Colour Maroon A/C: Insured / Std / NI / NASp. Reading 403523 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN364X05766W6Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Neuton

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/07/2020 D.O.I. 05/08/2015Survey held at SMRT 3Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/8/20	LS \$1400 confirmed by email (Red 14,520.81, 91%) <u>TP</u> <u>TAX/07/20/2059</u> <u>SGJ78JJG</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 24/8/20-Typist

Report Format : TPLump Sum / I.S.I. (\$) \$1400Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6159X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Aug 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6527935
Chassis No.:	JTDKN36UX05766116
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	05 Oct 2015
First Registration Date:	05 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Oct 2023
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	04 Oct 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,439.00
COE Rebate Amount:	\$17,986.00
Total Rebate Amount:	\$21,736.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Aug 2020

OK

CL/c/s)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2020 08:16
Date Of Accident	30/07/2020 06:30
Exact Location Of Accident	SLIP ROAD FROM LENTOR AVE TOWARDS YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6159
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095484MFSH
Cover Note Number	

Driver

Name of Driver	CHIN KOK KIONG (ZENG GUOQIANG)
NRIC No	SXXXXX738A
Date Of Birth	23/04/1973
Occupation	OUTDOOR
Date Of Driving Pass	01/01/1977
Driving Experience	43 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : MR CHUNG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM LENTOR AVENUE TOWARDS YISHUN AVE 1 WITH ONE PASSENGER (MALE CHINESE) ON BOARD AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SGJ7833G HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name MR CHUNG
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGJ7833G
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver PATEL CHETAN BABUBHAI
 NRIC/Passport Number SXXXX291D

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

Lentur Ave

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :
TAX/07/20/2059

Type of Repair : Accident Repair

Vehicle Registration Number :
SHD6159X

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-12191-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 29/07/2020 10:29 PM

Vehicle Age(In Months) : 57

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	✓ X Sur
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	✓ X Sur

Total Spare Part Cost 8,163.56

Surveyor Total 622.02

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 6,530.85

Final Sur Total 497.62

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT BIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Check	✓ X Svc
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Check	✓ X Svc
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Check	✓ X Svc
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.02	Replace	✓ / SCR
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	✓ X Svc

Total Spare Part Cost 8,163.56

Surveyor Total 622.02

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 6,530.85

Final Sur Total 497.62

SMRT Recommendation												Surveyor Approval		Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	✓ X R
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓ X SMC
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ / Nec
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	✓ X SMC
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	✓ X SMC

Total Spare Part Cost

8,163.56

Surveyor Total

622.02

Lump Sum Discount (%)

20.00

Lump Sum Dis (%)

20

Final Spare Part Cost

6,530.85

Final Sur Total

497.62

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Not Given ✓ X Svc.
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	0	0	Not Given ✓ X Svc
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Given ✓ X Svc
Total Spare Part Cost											Surveyor Total		
8,163.56											622.02		
Lump Sum Discount (%)											Lump Sum Dis (%)		
20.00											20		
Final Spare Part Cost											Final Sur Total		
6,530.85											497.62		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	845.00	200	
Total:			845.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	0	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
5	Main	TO RESPRAY REAR SPOILER	180.00	0	
6	Main	TO RESPRAY REAR PANEL	180.00	0	
7	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
8	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
9	Main	TO RESPRAY REAR FENDER RH	378.00	0	
10	Main	TO RESPRAY BATTERY PANEL	180.00	0	
Total:			2,394.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
7	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
8	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,145.00	50.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	6,530.85	497.62
Total Labour Cost	845.00	200.00
Total Spray Painting	2,394.00	200.00
Other	1,145.00	50.00
Overall Total	10,914.85	947.62
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	10,900.00	950.00
Surveyor Approved Amount		950.00
No of Repair Days*	6	2 <i>2 days</i>
Remarks	-	L/S, after paint photo.
Surveyor Name		Sun Pin (LKK)

30/07/2020

https://vacsweb.smit.com.sg/estimation.aspx

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save Clear

Survey Date

30/07/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: