

ESTIMATE

Date : 03/08/2020
To : AIG ASIA PACIFIC INSURANCE PTE. LTD.
Attn. : *Not Notified*
Office / Mobile : *4888 8*
Email Address : *Persony After Paint Bp 3 days*
From : MOTORVIVA PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GBG1420D
Model : 263.216.1 (695 GREY METALLIC)
Chassis No : ZFA26300006F25019
Engine No : 263A50007907900
Quotation No. : 114873
Ref. No. : GBE/SVC/SALES-AMK31
D.O.A. : 30/07/2020
Policy No. : 20-MS006827-R01
Claim Type : TP CLAIM - AIG
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER	1	875.00	0	875.00	875.00 ✓
2		REAR BUMPER RETAINER LH	1	35.00	0	35.00	35.00 X
3		REAR BUMPER RETAINER RH	1	35.00	0	35.00	35.00 X
4		REAR BUMPER STEP	1	175.00	0	175.00	175.00 ✓
5		REAR BUMPER REINFORCEMENT	1	478.00	0	478.00	478.00 ✓
6		REAR BUMPER END PANEL	1	579.00	0	579.00	579.00 ?
7		REAR BUMPER TOW COVER	1	30.00	0	30.00	30.00 X

PARTS TOTAL : 2,207.00

SPECIAL NETT ITEMS

1	REAR BUMPER CLIPS (SET)	1	50.00 ✓
2	REVERSE SENSOR	1	300.00

PARTS TOTAL: 350.00

LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	1200.00
2	TO TRANSFER, CHECK, RECONNECT ALL NECESSARY WIRING SYSTEM AND FUNCTIONALLY	100.00
3	TO REMOVE AND REPLACE REVERSE SENSOR	150.00
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1050.00

LABOUR TOTAL : 2,500.00

SUB-TOTAL : 5,057.00

GST @ 7% for \$ 5,057.00 353.99

GRAND TOTAL (S\$) : 5,410.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



IVECO

