

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sim, Priscilla-LK

Date: 06 Aug 2020

Preliminary Advice

Vehicle No	: SLU6424T	Accident Date	: 30/07/2020
Make	: SUBARU XV	Policy No.	: 1700088029
Assignment Date	: 04/08/2020	Excess	: S\$0.00
Date of Inspection	: 04/08/2020	Est. Duration of Repair	: 0
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident. The chassis frame affected due to collision.

Repairer's Estimate (Gross)	:S\$	76,762.90
Revised Amount	:S\$	27,287.00
Check Items (Estimated)	:S\$	44,999.80
Total	:S\$	72,286.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	102,300.00 as at Oct 2017
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	45,525.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	56,775.00
Margin for Repair (Pre-Accident Value)	:S\$	26,475.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PLEASE BE INFORMED THAT THE NEW CAR PRICES \$102,300.00 WAS AS AT OCT 2017.