

# Estimate

Date 08 / 03 / 2020

001 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
57702FL310	BUMPER FACE-FRONT / CRU.	FIG-590 57704	1	446.40
57711FL0109P	BACK BEAM COMPLETE-FRONT / BT	FIG-590 57711	1	346.00
57705FL040	ENERGY ABSORBER-FRONT BUMPER / CR4	FIG-590 57705	1	60.00
57705FL001	ENERGY ABSORBER-UPPER / CR4	FIG-590 57705B	1	65.90
57705FL080	ENERGY ABSORBER-LOWER / CR4.	FIG-590 57705C	1	38.00
57731FL150	COVER-UPPER / CR4	FIG-590 57730	1	22.70
57707FL060	BRACKET-BUMPER, FRONT LOWER / CRU.	FIG-590 57707AE	1	36.00
57735FL000	SEAL-FRONT BUMPER / Nec.	FIG-590 57735A	1	21.60
57722FL100	PLATE-BUMPER, FRONT / DD	FIG-590 57751F	1	28.80
57731FL130	COVER-FRONT BUMPER / Mis.	FIG-590 57731	1	5.00
57731FL110	COVER-INTAKE, FRONT / CR4	FIG-590 57731M	1	51.70
57707FL000	BRACKET-FRONT BUMPER CORNER, RI / CR4	FIG-590 57707AF	1	36.00
57707FL010	BRACKET-FRONT BUMPER CORNER, LE / CR4	FIG-590 57707AG	1	36.00
57707FL040	BRACKET-FRONT BUMPER SIDE, RIGH / CR4	FIG-590 57707F	1	7.20
57707FL050	BRACKET-FRONT BUMPER SIDE, LEFT / CRU.	FIG-590 57707G	1	7.20
57731FL082	COVER-FOG LIGHT, RIGHT / Mis.	FIG-590 84953N	1	46.30
Page-Total				1,254.80

Memo
------

Grand Total
67,989.90

Tel
-----

# Estimate

Date 08 / 03 / 2020

002 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
57731FL092	COVER-FOG LIGHT, LEFT <i>X SVC.</i>	FIG-590 849530	1	46.30
53029FL0819P	PANEL COMPLETE-RADIATOR <i>/ BT</i>	FIG-505 53010	1	376.80
51231FL0209P	FRAME COMPLETE-RADIATOR, LOWER <i>?</i>	FIG-505 51231G	1	92.30
51609FL0409P	WHEEL APRON SUB COMPLETE-RIGHT <i>?</i>	FIG-505 51610F	1	540.00
51609FL0509P	WHEEL APRON SUB COMPLETE-LEFT <i>?</i>	FIG-505 51610G	1	540.00
51620FL2529P	FRAME SIDE COMPLETE-RIGHT <i>?</i>	FIG- 51231A ITCA	1	486.00
51620FL2629P	FRAME SIDE COMPLETE-LEFT <i>?</i>	FIG- 51231B ITCA	1	486.00
91123FL170	MOLDING-FRONT GRILLERING <i>/ CRU</i>	FIG-911 91123F	1	129.60
91123FL130	MOLDING-FRONT GRILLE RIGHT <i>/ CRU</i>	FIG-911 91123C	1	112.00
91123FL140	MOLDING-FRONT GRILLE LEFT <i>/ CRU</i>	FIG-911 91123D	1	112.00
91123FL100	MOLDING-FRONT GRILLEBAR <i>/ CRU</i>	FIG-911 91123E	1	86.20
91122FL100	FRONT GRILLE-BASE <i>/ CRU</i>	FIG-911 91122B	1	172.20
93013VA090	ORNAMENT <i>/ Nec.</i>	FIG-919 91174	1	64.80
84002FL100	LAMP ASSEMBLY-HEAD RIGHT <i>?</i>	FIG-840 84001A	1	2,520.00
84002FL110	LAMP ASSEMBLY-HEAD LEFT <i>/ CRU.</i>	FIG-840 84001B	1	2,520.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT <i>/ CRU.</i>	FIG-845 84501B	<i>1</i>	544.00
Page-Total				8,828.20

Memo
------

Grand Total
67,989.90

Tel
-----

# Estimate

Date 08 / 03 / 2020

003 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
57229FL0109P	HOOD COMPLETE-FRONT / DO.	FIG-550 57220	1	1,072.80
57310FL030	LOCK ASSEMBLY-FRONT HOOD / Jqm	FIG-550 57310	1	72.70
57311FL010	STRIKER-FRONT HOOD / BT.	FIG-550 57311	1	28.80
57260FL0209P	HINGE COMPLETE-FRONT HOOD, RIGHT / BT	FIG-550 57260	1	37.90
57260FL0309P	HINGE COMPLETE-FRONT HOOD, LEFT / BT.	FIG-550 57260A	1	37.90
57256FL000	COVER-FRONT FENDER, RIGHT / CR4	FIG-550 57256H	1	18.00
57256FL010	COVER-FRONT FENDER, LEFT / SCR	FIG-550 57256I	1	18.00
90815FL410	INSULATOR-FRONT HOOD / Nec.	FIG-956 90815B	1	64.80
86636FL040NN	COVER ASSEMBLY-LAMP WASHER NOZ ZLE, RIGHT / Def.	FIG-877 86636NA	1	54.00
86636FL050NN	COVER ASSEMBLY-LAMP WASHER NOZ ZLE, LEFT / Mis.	FIG-877 866360A	1	54.00
86636FL000	NOZZLE-LAMP WASHER, RIGHT / ?	FIG-877 86636N	1	82.10
86636FL010	NOZZLE-LAMP WASHER, LEFT / CR4	FIG-877 866360	1	82.10
86655FL100	HOSE ASSEMBLY-HEAD LAMP WASHER / CR4	FIG-877 86655JA	1	54.00
57120FL0609P	FENDER COMPLETE-FRONT, RIGHT / CR4	FIG-540 57110	1	207.60
57120FL0709P	FENDER COMPLETE-FRONT, LEFT / CR4.	FIG-540 57110A	1	207.60
59110FL040	MUD GUARD, FRONT RIGHT / X svc	FIG-541 59110B	1	108.00
Page-Total				2,200.30

Memo

Grand Total
67,989.90

Tel
-----

# Estimate

Date 08 / 03 / 2020

004 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
59110FL050	MUD GUARD, FRONT LEFT <i>X Svc.</i>	FIG-541 59110C	1	108.00
60009FL0409P	PANEL ASSEMBLY-FRONT DOOR, RIGH <i>X R.</i> T	FIG-605 60010	1	920.00
61280FL020	WEATHER STRIP-DOOR, OUT RH <i>X Svc</i>	FIG-605 61280	1	107.70
61032FL020	LATCH & ACTUATOR ASSEMBLY-FRON <i>X Svc</i> T, RIGHT	FIG-607 61176F	1	216.00
61160FL042WW	HANDLE-DOOR, OUTER <i>X Svc.</i>	FIG-607 61160E	1	252.00
90422FL000	TAPE-FRONT DOOR, RIGHT <i>X Svc</i>	FIG-905 90422X	1	10.80
90422FL020	TAPE-FRONT DOOR SASH RIGHT <i>X Svc</i>	FIG-905 90422A	1	10.80
63511FL000	WEATHER STRIP-FRONT DOOR, RIGHT <i>X Svc</i>	FIG-901 63511	1	144.00
63527FL001	RUN CHANNEL-FRONT DOOR, RIGHT <i>X Svc</i>	FIG-901 61234A	1	75.60
63571FL001	WEATHER STRIP-BODY SIDE, FLANGE <i>X Svc</i> FRONT RH	FIG-901 63571	1	108.00
60009FL0509P	PANEL ASSEMBLY-FRONT DOOR, LEFT <i>X R.</i>	FIG-605 60010A	1	920.00
61280FL030	WEATHER STRIP-DOOR, OUT LH <i>X Svc</i>	FIG-605 61280A	1	107.70
61032FL031	LATCH & ACTUATOR ASSEMBLY-FRON ? T, LEFT	FIG-607 61176G	1	216.00
90422FL010	TAPE-FRONT DOOR, LEFT <i>X Svc</i>	FIG-905 90422Y	1	10.80
90422FL030	TAPE-FRONT DOOR SASH LEFT <i>X Svc</i>	FIG-905 90422B	1	10.80
63511FL010	WEATHER STRIP-FRONT DOOR, LEFT <i>X Svc</i>	FIG-901 63511A	1	144.00
<b>Page-Total</b>				<b>3,362.20</b>

Memo

<b>Grand Total</b>
<b>67,989.90</b>

Tel
-----

# Estimate

Date 08 / 03 / 2020

005 / 008

Name	QUOTATION FOR SLU6424T	Tel (Home)	G24 GT3BKGC JF1GT3KC5JG025834
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	
		Body Model	
		Vin-Code	

Part Number	Part Code Name	Part Code	Q'ty	Price
63527FL011	RUN CHANNEL-FRONT DOOR, LEFT <i>Xsvc</i>	FIG-901 61234B	1	75.60
63571FL011	WEATHER STRIP-BODY SIDE, FLANGE FRONT LH <i>Xsvc</i>	FIG-901 63571A	1	108.00
86631FL050	TANK-WASHER FRONT <i>/CR4</i>	FIG-875 86631	1	68.40
86611FL000	MOTOR & PUMP ASSEMBLY-WASHER ?	FIG-875 86611	1	78.20
86611FL010	MOTOR & PUMP ASSEMBLY-WASHER ?	FIG-875 86611	1	91.80
86611AL100	MOTOR & PUMP ASSEMBLY-WASHER ?	FIG-877 86611	1	194.40
82122AG001	TRAY-BATTERY <i>/CR4</i>	FIG-820 82122	1	8.00
82182AG001	HOLDER-BATTERY FIX <i>/BT</i>	FIG-820 82182	1	14.40
82123SA003	COVER-BATTERY <i>/CR4</i>	FIG-820 82123	1	28.80
<i>X</i> 82161AG001 <i>NS</i>	ROD-BATTERY FIX (NO STOCK) <i>/BT</i>	FIG-820 82161	1	4.40
<i>X</i> 82161AG012 <i>NS</i>	ROD BATTERY FIX (NO STOCK) <i>/BT</i>	FIG-820 82161	1	4.40
45111FL011	RADIATOR ASSEMBLY <i>/CR4</i>	FIG-450 45111	1	540.00
45121FL010	FAN-RIGHT ?	FIG-450 45121A	1	46.50
45122FL000	SHROUD-RADIATOR ?	FIG-450 45122	1	98.00
45131FG003	MOTOR ASSEMBLY ?	FIG-450 45131	1	272.00
45161FL000	HOSE-RADIATOR INLET ?	FIG-450 45162G	1	32.60
Page-Total				1.665.50

Memo
------

Grand Total
67,989.90

Tel
-----

# Estimate

Date 08 / 03 / 2020

006 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
45161FL040	HOSE-RADIATOR OUTLET ?	FIG-450 45162H	1	28.80
73210FL000	CONDENSER ASSEMBLY ?	FIG-730 73210	1	579.40
73233FL000	AIR GUIDE /def	FIG-730 73233	1	18.00
73233FL010	AIR GUIDE /def	FIG-730 73233	1	18.00
73424FL000	HOSE ASSEMBLY-PRESSURE DISCHAG E ?	FIG-730 73421A	1	162.00
73425FL000	HOSE ASSEMBLY-PRESSURE SUCTION ?	FIG-730 73422B	1	162.00
73431FL000	PIPE-EVAPORATOR, COOLING ?	FIG-730 73431T	1	169.20
73111FL040	COMPRESSOR ASSEMBLY ?	FIG-732 73111	1	1,500.00
45121FL000	FAN-LEFT ?	FIG-450 45121B	1	46.50
45131FL000	MOTOR ASSEMBLY ?	FIG-450 45131	1	259.20
66049FL020	PANEL COMPLETE-INSTRUMENT ?	FIG-660 66020	1	604.80
66226FJ001	CUSHION-INSTRUMENT PANEL ?	FIG-660 66226H	1	7.20
98211FL010VH	AIR BAG MODULE ASSEMBLY-DRIVER /Nec	FIG-343 98211	1	1,800.00
98271FL010	AIR BAG MODULE ASSEMBLY-PASSENGER /Nec	FIG-343 98271	1	1,836.00
98301FL010VH	AIR BAG MODULE ASSEMBLY-KNEE /Nec.	FIG-343 98301	1	1,800.00
98221FL140	CONTROL UNIT-AIR BAG /Nec	FIG-343 98221	1	1,292.40
Page-Total				10,283.50

Memo

Grand Total
67,989.90

Tel
-----

# Estimate

Date 08 / 03 / 2020

007 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
98231FL010	SENSOR ASSEMBLY-AIR BAG FRONT /Nec.	FIG-343 98231C	2	360.00
83196FJ020	STEERING ROLL CONNECTOR /Nec	FIG-832 98261	1	438.60
27549AL000	SENSOR-STEERING ANGLE /Nec.	FIG-832 27582	1	544.00
10100CG700	ENGINE ASSEMBLY ?	FIG-001 10100	1	19,080.00
N-S 81406FL150	(NO MORE AVAILABLE JPN) ?	FIG-810 81400	1	3,261.60
	HARNES-BULKHEAD ?			
15208AA160	OIL FILTER COMPLETE ?	FIG-032 15208	1	14.40
34110FL031	STEERING GEAR BOX ASSEMBLY, EP ?	FIG- 34110A	1	2,757.60
	S ?	ITCA		
X 13108AA181	COVER ASSEMBLY-CHAIN ?	FIG-022 13108	1	907.20
N-S	(NO STOCK)			
64622FL200ME	SEAT BELT-OUTER, FRONT RIGHT /Jam	FIG-645 64620A	1	621.00
64622FL210ME	SEAT BELT-OUTER, FRONT LEFT /Jam	FIG-645 64620B	1	621.00
94012FL100ME	TRIM PANEL-B PILLAR UPPER, RIGH T /def	FIG-940 94012B	1	46.80
94012FL110ME	TRIM PANEL-B PILLAR UPPER, LEFT /def	FIG-940 94012C	1	46.80
94015FL100ME	TRIM PANEL-D PILLAR UPPER, RIGH T /def	FIG-940 94015	1	46.80
94015FL110ME	TRIM PANEL-D PILLAR UPPER, LEFT /def	FIG-940 94015A	1	46.80
94022FL000VH	TRIM PANEL-B PILLAR LOWER, RIGH T /def	FIG-940 94022	1	67.10
94022FL010VH	TRIM PANEL-B PILLAR LOWER, LEFT /def	FIG-940 94022A	1	67.10
Page-Total				28,926.80

Memo

Grand Total
67,989.90

Tel
-----

# Estimate

Date 08 / 03 / 2020

008 / 008

<b>Name</b>	QUOTATION FOR SLU6424T	<b>Tel (Home)</b>	
<b>Address</b>		<b>Tel (Office)</b>	
<b>E-Mail</b>		<b>Tel (Portable)</b>	
		<b>Fax</b>	
		<b>Model Name</b>	G24
		<b>Body Model</b>	GT3BKGC
		<b>Vin-Code</b>	JF1GT3KC5JG025834

Part Number	Part Code Name	Part Code	Q'ty	Price
94027FL021VH	TRIM PANEL-REAR QUARTER, RIGHT / Def	FIG-943 94025	1	223.60
94027FL031VH	TRIM PANEL-REAR QUARTER, LEFT / Def	FIG-943 94025A	1	243.40
10103AC830	SHORT BLOCK ENGINE ASSEMBLY ?	FIG-001 10103	1	5,040.00
10105AB770	GASKET AND SEAL KIT-ENGINE ?	FIG-001 10105	1	504.00
11018AA770	HEAD AND VALVE SET-CYLINDER (NO STOCK) ?	FIG-001 11018	1	1,728.00
11019AA720	HEAD AND VALVE SET-CYLINDER (NO STOCK) ?	FIG-001 11019	1	1,728.00
64660FL320VH	SEAT BELT-OUTER REAR RIGHT / Jam	FIG-646 64660	1	432.00
64660FL330VH	SEAT BELT-OUTER REAR LEFT / Jam	FIG-646 64660A	1	432.00
98237FL040	SENSOR-SIDE AIR BAG / Nec	FIG-343 98235D	2	360.00
98237FL030	SENSOR-SIDE AIR BAG / Nec	FIG-343 98235D	4	633.60
98237SG030	SENSOR-AIR BAG / Nec	FIG-343 98235E	1	144.00
			<b>Page-Total</b>	11,468.60
			<b>Sub-Total</b>	67,989.90
<div style="border: 1px solid black; padding: 5px;"> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div>			<b>Total</b>	67,989.90
			<b>Tax</b>	0.00
			<b>Grand Total</b>	67,989.90

Acknowledged by Repairer: _____ Signature: _____ Date: _____	Memo
--	------

<b>Grand Total</b>
67,989.90

Tel
-----

**MotorImage**

19 Lorong 8 Toa Payoh  
Singapore 319255

Repair day - 16 days.  
P/P.  
betula pui  
Sun Pin (446)  
06/08/2020

OD  
REV  
Excess: TBA



**ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR**

REG NO: SLU6424T	MODEL : SUBARU XV 1.6I-S AWD CVT
REF NO:INS/IC/CHI/0138/2020	YEAR: 09-DEC-2017
ENGINE NO: FB16YC00046	CHASSIS NO: JF1GT3KC5JG025834
DOA: 30/07/2020	TOA: 0800HRS
TYPE OF CLAIM: OD REC	INS COMPANY:AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRT BUMPER,FRT BONNET,FRT RH & LH FENDER,FRT RH DOOR & SUPPORT PANEL	\$2000.00 1,500.
2.	RESPRAY FRT BUMPER,FRT BONNET,FRT RH & LH FENDER,FRT RH DOOR & SUPPORT PANEL	\$1600.00 /
3.	DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIR	\$684.00 ?
4.	REMOVE & REFIX EXHAUST	\$114.00 /
5.	REMOVE & REIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR	\$171.00 /
6.	TRANSFER DOOR RH FRT MECHANISM	\$142.00 X
7.	WHEEL ALIGNMENT	\$171.00 /
8.	MECHANICAL REPAIR- ALTERNATOR,COMPRESSOR,STEERING PUMP	\$171.00 /
9.	REMOVE & REFIX WIRE HARNESS	\$228.00 /
10.	REMOVE & REFIX DASHBOARD	\$342.00 /
11.	REMOVE & REFIX SEAT BELT,MODULE & RESET	\$380.00 /
12.	REMOVE & REPLACE DRIVER & PASSENGER AIRBAG & RESET	\$427.00 ?
13.	FAULT DIAGNOSTIC	\$235.00 /
14.	COOLING SYSTEM PRESSURE TEST	\$85.00 /
15.	REMOVE & REINSTALL ENGINE TO FACILITATE REPAIR	\$342.00 /
16.	TO CONDUCT CAR 'O' TRONIC CHASSIS ALIGNMENT & MEASUREMENT	\$1000.00 750
17.	TO CONDUCT FRONT LIGHTING TEST	\$56.00 /
18.	TO SUPPLY & INSTALL FRONT SENSOR- 4 EYES	\$400.00 /
19.	SUNDRIES	\$100.00 X
20.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$125.00 /
	<b>Total Labour</b>	<b>\$8773.00</b>

1 dy -250  
p - 20

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	
HP / EMAIL:	/
BEFORE PAINT:	
DAYS GIVEN:	