

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 05 Aug 2020

**Preliminary Advice**

Vehicle No	: SLU6424T	Accident Date	: 30/07/2020
Make	: SUBARU XV	Policy No.	: 1700088029
Assignment Date	: 04/08/2020	Excess	: S\$0.00
Date of Inspection	: 04/08/2020	Est. Duration of Repair	: 0
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	45,525.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,475.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PLAESE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIRS.