

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 557J**AAD2007-117***Not Authoised
L/Smp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

03 AUG 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 557J

VF1ABL15AUC278108

RENAULT

LATITUDE

29.7.2020

CHINA TAIPING

20/06/2014

		PART		LIST	
1	DOOR PANEL FRT LH	\$		<i>Bn</i> 2,844.66	✓
1	DOOR REGULATOR FRT LH	\$		<i>Dis</i> 501.40	✓
1	DOOR REGULATOR MOTOR FRT LH	\$		<i>Tr</i> 758.10	✓
1	DOOR REGULATOR GUIDE FRT LH	\$		<i>Dis</i> 69.00	✓
1	DOOR WEATHERSTRIP FRT LH	\$		<i>Sn</i> 316.00	X
1	DOOR SEAL FRONT LH	\$		<i>Sn</i> 69.60	X
1	DOOR SEAL LOWER FRT LH	\$		<i>Sn</i> 93.90	X
1	DOOR SEAL FRT LH	\$		<i>Sn</i> 63.10	✓
1	DOOR HINGE UPPER FRT LH	\$		<i>R</i> 274.50	X
1	DOOR HINGE LOWER FRT LH	\$		<i>R</i> 300.55	X
1	DOOR CHECK FRT LH	\$		<i>Sn</i> 90.90	X
1	DOOR LOCK FRT LH	\$		<i>Sn</i> 453.80	✓
1	DOOR GLASS FRT LH	\$		<i>Shatters</i> 394.00	✓
1	DOOR MOULDING BLACK FRT LH	\$		<i>Sn</i> 100.50	✓
1	DOOR FINISHER FRT LH	\$		<i>Sn</i> 258.90	X
1	DOOR FINISHER CLIP KIT FRT LH	\$		<i>Sn</i> 94.00	X
1	DOOR CASING FRT LH	\$		<i>Dis</i> 1,509.06	✓
1	DOOR GLASS RUNNER SEAL FRONT LH	\$		<i>Sn</i> 332.00	X
1	DOOR HANDLE OUTER FRONT LH	\$		<i>Bn</i> 169.50	✓
1	DOOR HANDLE CAP FRONT LH	\$		<i>Dis</i> 17.30	✓
1	DOOR HANDLE SEAL FRT LH	\$		<i>Sn</i> 1.60	✓
1	DOOR HANDLE COVER FRT LH	\$		<i>Sn</i> 6.10	✓
1	DOOR HANDLE MODULE FRT LH L70Y	\$		<i>Sn</i> 133.40	X
1	DOOR WAIST SEAL OUTER FRT LH (Door Chrome)	\$		<i>Bn</i> 92.20	✓
1	DOOR WAIST SEAL INNER FRT LH	\$		<i>Sn</i> 86.30	X
1	DOOR MIRROR ASSY LH	\$		<i>Bn</i> 1,483.40	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 557J

AAD2007-117

- 1 DOOR MIRROR GLASS LH
- 1 DOOR MIRROR BACK COVER FRT LH
- 1 DOOR MIRROR LAMP LH
- 1 DOOR FINISHER INNER FRT LH
- 1 DOOR FINISHER BRACKET INNER FRT LH
- 1 DOOR HARNESS WIRE LH
- 1 DOOR HINGE OUTER PILLAR PANEL FRT LH
- 1 DOOR HINGE INNER PILLAR PANEL FRT LH
- 1 VEHICLE HARNESS PASS ROOM
- 1 ROCKER PANEL INNER GARNISH LH
- 1 ROCKER PANEL OUTER LH
- 1 DOOR PANEL REAR LH
- 1 DOOR HINGE UPPER REAR LH L70Y
- 1 DOOR HINGE LOWER REAR LH L70Y
- 1 DOOR CHECK REAR LH
- 1 DOOR REGULATOR REAR LH L70Y
- 1 DOOR REGULATOR MOTOR REAR LH L70Y
- 1 DOOR WEATHERSTRIP REAR LH
- 1 DOOR GLASS RUNNER SEAL REAR LH
- 1 DOOR MOULDING BLACK REAR LH
- 1 DOOR WAIST SEAL OUTER REAR LH
- 1 CENTRE PILLAR OUTER
- 1 CENTER PILLAR INNER
- 1 CENTER PILLAR REINFORCEMENT
- 1 CENTER PILLAR INNER GARNISH - TOP
- 1 CENTER PILLAR INNER GARNISH- LOWER
- 1 FENDER PANEL FRT LH
- 1 WHEELARCH FRT LH

\$	<i>nn</i>	151.70	X
\$	<i>nn</i>	128.70	X
\$	<i>nn</i>	134.10	X
\$	<i>sn</i>	197.10	}
\$	<i>sn</i>	31.90	
\$	<i>sn</i>	2,670.00	
\$	<i>n</i>	2,896.14	
\$	<i>n</i>	1,542.15	
\$	<i>sn</i>	2,170.90	}
\$	<i>sn</i>	466.51	
\$	<i>n</i>	1,184.99	
\$	<i>sn</i>	2,844.66	✓
\$	<i>n</i>	241.60	X
\$	<i>n</i>	169.90	X
\$	<i>sn</i>	114.90	X
\$	<i>sn</i>	450.60	X
\$	<i>sn</i>	657.10	X
\$	<i>sn</i>	311.60	50/100
\$	<i>sn</i>	320.90	X
\$	<i>n</i>	100.50	✓
\$	<i>sn</i>	169.60	}
\$	<i>n</i>	880.14	
\$	<i>n</i>	907.76	
\$	<i>n</i>	1,176.15	
\$	<i>sn</i>	168.82	
\$	<i>sn</i>	365.99	}
\$	<i>n</i>	437.10	
\$	<i>sn</i>	191.40	
TOTAL		\$	31,596.68
10%		\$	3,159.67
		\$	28,437.01

Special Nett

- 1 FRONT DOOR STICKER 'Trans-Cab'

\$ *nn* 80.00 *60/100*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 557J

AAD2007-117

1	FRONT DOOR STICKER 'Classic'	\$	80.00	15sn
1	REAR DOOR STICKER '6555-3333'	\$	100.00	60sn
1	LH SIDE RENAULT TYRE 215/60/16	\$	330.00	}
1	LH SIDE RENAULT TYRE RIM	\$	380.00	
1	FRONT WINDSCREEN MOULDING	\$	200.00	
2	WINDSCREEN SEALANT	\$	150.00	
1	FRONTWINDSCREEN INNER SPONGE SEAL	\$	130.00	
1	DOOR CHECK BOLT	\$	45.00	
1	DOOR CHECK NUT	\$	45.00	
1	DOOR GUIDE SCREW	\$	45.00	
1	DOOR HINGE BOLT	\$	45.00	
1	DOOR HINGE NUT LH	\$	45.00	
1	DOOR LOCK SCREW	\$	55.00	}
1	DOOR SEAL CLIP LH	\$	55.00	
1	DOOR MOULDING CLIP	\$	65.00	
1	ROCKER PANEL CLIP	\$	55.00	
1	DOOR CASING CLIP	\$	200.00	
2	Seam Sealant	\$	65.00	
1	WHEELARCH CLIP FRT LH	\$		
TOTAL		\$	2,215.00	

TOTAL PARTS \$ 30,652.01**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 601

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,000.00 5001

Putty and spray painting of the affected portion.

\$ 3,000.00 6601

To transfer of Front door fittings, attachment and perform water seepage test.

\$ 170.00 601

Trans-cab Auto Services Pte Ltd**AAD2007-117**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 557J

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>'</i> 170.00	<i>601</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To pull and jack out body pillar and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 440.00	<i>X</i>
Towing Fees	\$	150.00	<i>501</i>
To rust-proofing and apply undercoat of the affected areas.	\$	<i>nn</i> 250.00	<i>to 601</i>
TOTAL	\$	8,670.00	
Over All Total	\$	39,322.01	

LUMP SUM (REPAIR DAY)**25 DAYS***4 days*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: