

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
8 Kaki Bukit Ave 4 #08-45/46
[Premier@Kaki Bukit S\(415875\)](mailto:Premier@KakiBukitS(415875))
Tel : 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 4-Aug-20
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SJC2045Z
ADDRESS	:	MODEL / MAKE	: TOYOTA ESTIMA
TEL. NO.	:	CHASSIS NO.	: ACR50-0053904
OWNER INSURANCE	: NTUC	ACCIDENT DETAIL	
POLICY NO.	: 5106969023-01	DATE	: 1-Aug-20
		TIME	: 15:20hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT WIPER GARNISH RH <i>Defect</i>	1	\$ 25.60	\$ 25.60
2	FRONT FENDER RH <i>Dented</i>	1	\$ 685.90	\$ 685.90
3	FRONT FENDER LOWER GARNISH RH <i>New</i>	1	\$ 78.50	\$ 78.50
4	FRONT FENDER INNER SHIELD RH <i>torn</i>	1	\$ 270.70	\$ 270.70
5	FRONT FENDER BRACKET RH <i>Best</i>	1	\$ 56.40	\$ 56.40
6	FRONT HEADLAMP RH <i>cracked</i>	1	\$ 1,000.90	\$ 1,000.90
7	FRONT HEADLAMP LOWER BRACKET RH <i>see n</i>	1	\$ 44.50	\$ 44.50
8	FRONT GRILLE <i>cracked</i>	1	\$ 435.10	\$ 435.10
9	FRONT GRILLE LOGO EMBLEM <i>see n</i>	1	\$ 75.20	\$ 75.20
10	FRONT BUMPER <i>Defect</i>	1	\$ 545.90	\$ 545.90
11	FRONT BUMPER FOG LAMP RH <i>cracked</i>	1	\$ 425.70	\$ 425.70
12	FRONT BUMPER FOG LAMP GARNISH RH <i>Defect</i>	1	\$ 100.50	\$ 100.50
13	FRONT BUMPER LOWER CENTER GRILLE <i>see n</i>	1	\$ 120.30	\$ 120.30
14	FRONT BUMPER TOW HOOK COVER RH <i>see n</i>	1	\$ 22.10	\$ 22.10
15	FRONT BUMPER LOWER UNDER COVER RH <i>see n</i>	1	\$ 223.70	\$ 223.70
16	FRONT BUMPER SIDE RETAINER LH/RH <i>RH only</i>	2	\$ 95.30	\$ 190.60
17	FRONT BUMPER TOP BEAM <i>3 New</i>	1	\$ 138.90	\$ 138.90
18	FRONT BUMPER INNER SPONGE	1	\$ 80.50	\$ 80.50
19	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 410.70	\$ 410.70
20	WASHER TANK <i>Defect</i>	1	\$ 176.60	\$ 176.60

✓
✓
+
✓
✓
✓
+ 389
✓
✓
+ 269.70
✓
+
+
+ 95.30
+
+
✓

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
21	FRONT SUSPENSION SHOCK ABSORBER RH	1	\$ 500.90	\$ 500.90
22	FRONT SUSPENSION KNUCKLE ARM RH	1	\$ 585.70	\$ 585.70
23	FRONT SUSPENSION KNUCKLE ARM BEARING RH	1	\$ 579.40	\$ 579.40
24	FRONT SUSPENSION LOWER ARM RH	1	\$ 815.10	\$ 815.10
25	FRONT SUSPENSION LOWER BALL JOINT RH	1	\$ 225.30	\$ 225.30
26	FRONT SUSPENSION STABILISER BAR LINK RH	1	\$ 165.70	\$ 165.70
TOTAL PRICE				\$ 7,980.40
LESS -25%				\$ (1,995.10)
SUB TOTAL PRICE				<u>\$ 5,985.30</u>

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT WIPER GARNISH CLIPS SET RH	1	\$ 20.00	\$ 20.00
2	FRONT FENDER LOWER GARNISH CLIPS SET RH	1	\$ 20.00	\$ 20.00
3	FRONT FENDER INNER SHIELD CLIPS SET RH	1	\$ 60.00	\$ 60.00
4	FRONT HEADLAMP CLIPS SET RH	1	\$ 20.00	\$ 20.00
5	FRONT GRILLE CLIPS SET	1	\$ 40.00	\$ 40.00
6	FRONT BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00
7	FRONT BUMPER PARKING SENSOR SET	1	\$ 280.00	\$ 280.00
8	FRONT BUMPER LOWER UNDER COVER CLIPS SET	1	\$ 60.00	\$ 60.00

TOTAL

100

\$ 580.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 6,565.30
TOTAL LABOUR COST	:	\$ 4,120.00
TOTAL REPAIR COST	:	<u>\$ 10,685.30</u>

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR LUMP SUM
DATE / TIME OF SURVEY	:	
SURVEYED BY / FROM	:	
CONTACT NUMBER	:	
FAX NUMBER	:	
EMAIL ADDRESS	:	
DATE / TIME OF RE-SURVEY	:	
EXCESS	:	

Adrian L
04/08/20
L/S.

QUOTATION SUMMARY

PAGE 04

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	500	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,600.00	600	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 100.00	60	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	40	
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 280.00	X.	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	80	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X.	

TOTAL

\$ 4,120.00

1410

total: 4586.80

L/S 3650.

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: