

Denise Tay (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Thursday, 6 August 2020 10:41 AM
To: Denise Tay (LKKAuto)
Subject: Re: AUDIT CHECK

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Denise,

Audit check done for YN3541R, found parts prices need verification, market value too high and recommend roof panel to repair instead of replace. I already spoken to Rasul.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 6 August 2020 9:18 AM
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: AUDIT CHECK

Hi Simon,

Audit check

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6271-0351 | email: sur@lkkauto.com | fax: 6271-8802

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)