

Appendix B

Tel: 68676919 Fax: 62626950, 68676903

Vehicle No. : YN3541R
Make & Model : MITSUBISHI

Submit By : : Wong Chee Wei
Year of Manufacture : 2011

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Parts

Vehicle No. : YN3541R Submit By : Wong Chee Wei

Make & Model : MITSUBISHI FM65FM1RDEA Year Manufacture : 2011

Chassis No. : FM65FMA00244 Engine No. : 6M60159921

OD

S/Order

S/No	Part Description	Qty	Cost Price		Nett Price	List Price	S- Nett Price	Disposition By Surveyor
			original	OEM				
1	BONNET <i>bt</i> ✓	1	\$1,900.00 ✓				\$990.00	
2	BONNET SEAL <i>new</i> ✓	1	\$86.00 ✓					
3	BONNET LHS HINGE <i>X Svc</i>	1	\$85.00					
4	BONNET RHS HINGE <i>X Svc</i>	1	\$85.00					
5	ROOF TOP PANEL <i>bt - Repair</i>	1	\$2,350.00					
6	ROOF TOP LINING CLIP <i>new</i> ✓	20	\$100.00 ✓					
7	FRONT WINDSCREEN <i>con</i> ✓	1	\$1,650.00 ✓					
8	FR WINDSCREEN RUBBER <i>new</i> ✓	1	\$550.00 ✓					
9	FRONT BUMPER <i>repair</i>	1	\$750.00					
10	RHS WIPER ARM <i>SCA</i> ✓	1	\$150.00 ✓					
11	RHS WIPER BLADE <i>X Svc</i>	1	\$80.00					
12	LHS WIPER ARM <i>X Svc</i>	1	\$150.00					
13	LHS WIPER BLADE <i>X Svc</i>	1	\$80.00					
14	RHS CORNER PANEL <i>bt. repair</i>	1	\$850.00					
15	LHS CORNER PANEL <i>bt</i> ✓	1	\$850.00 ✓					
16	FR NO.PLATE <i>bt</i> ✓	1					\$45.00	✓
17	I U BRACKET <i>new</i> ✓	1					\$26.00	✓
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ACCIDENT REPAIR ESTIMATES


Our Ref:

Type of Claim : ☒ Own Damage
☐ 3rd Party
☐ Windscreen

Ins Company : AWAC
Excess : TBA
Date of Accident : 29/07/2020
Suggested Days of Repair : 6 DAY

Vehicle No. : YN3541R
Make & Model : MITSUBISHI / FM65FM1RDEA
Year of Manufacture : 2011
Chassis No. : FM65FMA00244
Engine No. : 6M60159921
Policy No. : BVFCSB0013691900
Time of Accident : 10.05 A.M

In-house Vehicle Assessor

Name : Wong Chee Wei
Signature : 
Contact No : 68676919
HP : 97239882

Repair Estimates

Parts (a) Cost / List Price Items \$9,716.00
Plus/Less 10 % \$971.60
(b) Nett Price Items
Less %
(c) Special Nett Items \$71.00
Total Parts Cost (Appendix A) \$10,758.60
Labour (Appendix B) \$3,600.00
Total Repair Cost \$14,358.60

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Name of Surveyor : Rasul
Company : LKK Auto
Survey conducted on : 05/08/2020 at 1155hrs

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.
(b) Recommended Days of Repair : 6 days
(c) Resurvey : Required Not Required
(d) Excess : \$ TBA
(e) Signature of surveyor :  Date: 05/08/2020

Reay after repair