

ASS. REC. BY:

REF: CS3/CTI20008034/Evf3

Special Instruction:

Surveyor: STEVE

ASSIGNMENT (Office)

From (Person): Cecilia Low of CTI Date/Time: 04 Aug 2020 14:27

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 498R Insured: SLB 9596K

at Workshop m/s Everdawn Auto Service Tel: 63851171

of 8 Kaki Bukit Ave 4, #01-02 Premier @ Kaki Bukit

Policy No: DMPCSNW00036682002 Claim No: SNM20D202702

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 01/08/2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 4-8-20 3.16P.M Person Contacted: IRENE Vehicle  IN  OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJL 498R- X
	SLB 9596K- X
11/8/20	Submit PRS, repair range \$4,000-\$5,000 (5 days)