

Not Authored
Resurvey B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9410A

AAD2008-003

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

05 AUG 2020

SHD 9410A

JTDKB3FU503081140

TOYOTA

PRIUS

2.8.2020

III

18-06-19

PART

- 1 FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER, ENERGY
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2
- 1 COVER, ENGINE UNDER, NO.1
- 1 EXTENSION, FRONT BUMPER, RH
- 1 FRONT LED LAMP (LOWER) RH
- 1 FRONT HEADLAMP RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
- 1 MOTOR, HEADLAMP LEVELING, RH
- 1 FRONT FENDER RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
- 1 FRONT BONNET
- 1 HINGE ASSY, HOOD, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 INLET SUB ASSY, WASHER
- 1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER

LIST

\$	Bu	516.00	✓
\$	SL	103.40	X
\$	Dir	80.10	✓
\$	R	716.60	X
\$	R	246.10	X
\$	SL	132.70	} X
\$	SL	79.60	
\$	SL	29.30	
\$	SL	241.90	
\$	SL	472.40	
\$	SL	120.10	}
\$	SL	951.40	
\$	CM	2,637.60	✓
\$	SL	960.50	X
\$	SL	487.50	X
\$	Bz	977.80	✓
\$	Dir	206.70	✓
\$	rm	54.60	X
\$	SL	100.40	X
\$	R	983.10	} X
\$	R	58.90	
\$	SL	346.00	
\$	SL	170.10	
\$	SL	90.80	
\$	SL	219.10	}
\$	SL	67.00	
\$	SL	292.40	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

AAD2008-003

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9410A

1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	Sm	594.80	X
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	N	1,300.70	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	N	97.50	X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	N	110.60	X
1	CHECK ASSY, FRONT DOOR	\$	Sm	183.80	X
1	RIGHT SIDE VIEW MIRROR	\$	Br	1,436.60	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	Ne	13.30	—
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	N	43.50	—
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	N	26.30	—
1	WIRE, FRONT DOOR, RH	\$	Sm	532.80	X
1	PILLAR, FRONT BODY, UPPER OUTER RH	\$	Sm	381.60	X
1	SUPPORT, RADIATOR, UPPER RH	\$	Sm	78.90	X
1	HUB SUB-ASSY, FRONT AXLE, RH	\$		668.90	?
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$		760.10	?
1	KNUCKLE, STEERING, RH	\$		663.40	?
1	ABSORBER ASSY, SHOCK, FRONT RH	\$		438.30	?
1	SHAFT ASSY, FRONT DRIVE, RH	\$	N	1,379.50	X
TOTAL		\$		20,052.70	
25%		\$		5,013.18	
		\$		15,039.53	

Special Nett

1	FRONT WHEEL RIM	\$	N	1,879.40	✓
1	FRONT WHEEL RIM COVER	\$	Sm	211.50	X
1	FRONT TYRE 195/65/15	\$	Sm	350.00	X
1SET	CLIP, FRONT FENDER LINER	\$	N	65.00	✓
1	FRONT NUMBER PLATE WITH MOULDING	\$	Sm	200.00	X
1SET	BUMPER CLIP FRT	\$	N	75.00	✓
1SET	FRONT BUMPER RETAINER CLIP	\$	N	65.00	X
1SET	ROCKER PANEL MOULDING CLIP	\$	N	65.00	X
1	FRONT DOOR STICKER 'TRANS-CAB'	\$	N	100.00	605N
TOTAL		\$		3,010.90	

TOTAL PARTS \$ 18,050.43

AAD2008-003

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9410A

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	50d
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	4 170.00	X
To transfer of door fittings, attachments and perform water seepage test.	\$	4 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	6d
To transfer of tire, rim and on wheel balancing.	\$	170.00	2d
Putty And Spray Painting Of The Affected Portion.	\$	2,800.00	72d
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	3d
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	4 380.00	?
To pull and jack out body pillar and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	4 380.00	X

AAD2008-003

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9410A

To check ABS and brake efficiency, final checking and testing. \$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *201*

TOTAL \$ **8,820.00**

Over All Total \$ **26,870.43**

(PART-BY-PART) Repair Days

20 days

3 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: