

Not Authored  
Presurvey B4 paint

**Trans-cab Auto Services Pte Ltd**

AAD2008-003

No. 2 Ang Mo Kio Street 63 Singapore 569111  
Tel No. : 6287 6666 Fax No. : 6257 1330  
CO./GST Reg. No. 201019626G  
**SHD 9410A**

Vehicle No.:  
Chassis No.:  
Vehicle Make: 05 AUG 2020  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHD 9410A**  
JTDKB3FU503081140  
TOYOTA  
PRIUS  
2.8.2020  
III  
18-06-19

PART	LIST	Price	Status
1 FRONT BUMPER	\$ Bu	516.00	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ Su	103.40	X
1 FRONT BUMPER SIDE RETAINER RH	\$ Di	80.10	✓
1 REINFORCEMENT, FRONT BUMPER	\$ R	716.60	X
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$ R	246.10	X
1 ABSORBER, FRONT BUMPER, LOWER	\$ Su	132.70	} X
1 ABSORBER, FRONT BUMPER, ENERGY	\$ Su	79.60	
1 COVER, FRONT BUMPER HOLE, RH	\$ Su	29.30	
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ Su	241.90	
1 COVER, ENGINE UNDER, NO.1	\$ Su	472.40	
1 EXTENSION, FRONT BUMPER, RH	\$ Su	120.10	} X
1 FRONT LED LAMP (LOWER) RH	\$ Su	951.40	
1 FRONT HEADLAMP RH	\$ CM	2,637.60	✓
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ Su	960.50	X
1 MOTOR, HEADLAMP LEVELING, RH	\$ Su	487.50	X
1 FRONT FENDER RH	\$ B	977.80	✓
1 LINER, FRONT FENDER, RH	\$ Di	206.70	✓
1 FRONT FENDER EMBLEM RH	\$ su	54.60	X
1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$ su	100.40	X
1 FRONT BONNET	\$ R	983.10	} X
1 HINGE ASSY, HOOD, RH	\$ R	58.90	
1 GRILLE SUB-ASSY, RADIATOR	\$ Su	346.00	
1 GRILLE, RADIATOR, LOWER NO.1	\$ Su	170.10	
1 EMBLEM ASSY, RADIATOR GRILLE	\$ Su	90.80	
1 JAR ASSY, WINDSHIELD WASHER	\$ Su	219.10	} X
1 INLET SUB ASSY, WASHER	\$ Su	67.00	
1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$ Su	292.40	

**Trans-cab Auto Services Pte Ltd**  
No. 2 Ang Mo Kio Street 63 Singapore 569111

AAD2008-003

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9410A**

1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	Sm	594.80	X
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	N	1,300.70	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	N	97.50	X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	N	110.60	X
1	CHECK ASSY, FRONT DOOR	\$	Sm	183.80	X
1	RIGHT SIDE VIEW MIRROR	\$	Br	1,436.60	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	Nc	13.30	—
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	N	43.50	—
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	Nc	26.30	—
1	WIRE, FRONT DOOR, RH	\$	Sm	532.80	X
1	PILLAR, FRONT BODY, UPPER OUTER RH	\$	Sm	381.60	X
1	SUPPORT, RADIATOR, UPPER RH	\$	Sm	78.90	X
1	HUB SUB-ASSY, FRONT AXLE, RH	\$	SVC	668.90	X
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	SVC	760.10	X
1	KNUCKLE, STEERING, RH	\$	SVC	663.40	X
1	ABSORBER ASSY, SHOCK, FRONT RH	\$	SVC	438.30	X
1	SHAFT ASSY, FRONT DRIVE, RH	\$	N	1,379.50	X
<b>TOTAL</b>		<b>\$</b>		<b>20,052.70</b>	
25%		<b>\$</b>		<b>5,013.18</b>	
		<b>\$</b>		<b>15,039.53</b>	

**Special Nett**

1	FRONT WHEEL RIM	\$	Nc	1,879.40	✓
1	FRONT WHEEL RIM COVER	\$	Sm	211.50	X
1	FRONT TYRE 195/65/15	\$	Sm	350.00	X
1SET	CLIP, FRONT FENDER LINER	\$	Nc	65.00	✓
1	FRONT NUMBER PLATE WITH MOULDING	\$	Sm	200.00	X
1SET	BUMPER CLIP FRT	\$	Nc	75.00	✓
1SET	FRONT BUMPER RETAINER CLIP	\$	Nc	65.00	X
1SET	ROCKER PANEL MOULDING CLIP	\$	Nc	65.00	X
1	FRONT DOOR STICKER 'TRANS-CAB'	\$	Nc	100.00	605N
<b>TOTAL</b>		<b>\$</b>		<b>3,010.90</b>	

**TOTAL PARTS \$ 18,050.43**

**AAD2008-003**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9410A

**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	50d
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	↳ 170.00	X
To transfer of door fittings, attachments and perform water seepage test.	\$	↳ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↳ 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	6d
To transfer of tire, rim and on wheel balancing.	\$	170.00	2d
Putty And Spray Painting Of The Affected Portion.	\$	2,800.00	72d
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↳ 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	3d
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	↳ 380.00	X NN
To pull and jack out body pillar and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	↳ 380.00	X

AAD2008-003

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9410A

To check ABS and brake efficiency, final checking and testing.	\$	<i>na</i>	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
<b>TOTAL</b>	<b>\$</b>		<b>8,820.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>26,870.43</b>	

(PART-BY-PART) Repair Days

*20 days*  
*3 days*

**For Official Use**

Prepared By : \_\_\_\_\_  
(Accident Dept)

Verify By : \_\_\_\_\_  
(Accident Workshop)

Checked By : \_\_\_\_\_  
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: