

ASS. REC. BY:

Steve

REF:

CC4/KC120008042/da3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mazda 6

c.c.

1998

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

14239

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JM66L 1072K 03/2788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

225/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

28/7/20

D.O.I. _____

11/8/20

Survey held at

Tens Eurokars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-96K

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Photos _____

Others _____

TOTAL



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

444
1146-1000

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Yeo Hao Jie Kenny ADDRESS : Blk 168 Hougang Ave 1 #10-1409 Singapore 530168 TEL : 96902734		WIP : 32419 EXCESS : DATE : 29-Jul-20	
VEH NO :	SMM4765C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1072K0312288	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 6	DATE REG.:	28-Jun-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	FRONT BUMPER	1		\$ 1,026.50	
2	RETAINER LHS	1		\$ 14.70	
3	GROMMET, FRONT BUMPER	2		\$ 5.80	
4	RIVET, FRONT BUMPER	4		\$ 18.00	
5	FASTENER, FRONT BUMPER	2		\$ 6.00	
6	RIVET, FRONT BUMPER	8		\$ 32.00	
7	PROTECTOR LHS, CHROME	1		\$ 65.80	
8	COVER LHS, CHROME	1		\$ 20.50	
9	RIVET, LICENCE PLATE HOLE	2		\$ 15.20	
10	CHROME LHS	1		\$ 251.40	
11	RIVET, CHROME	6		\$ 55.20	
12	RIVET, GRILLE TOP	8		\$ 32.00	
13	RIVET, GRILLE TOP	4		\$ 32.00	
14	HEADLAMP LHS	1		\$ 4,758.60	
15	RIVET, HEADLAMP	1		\$ 3.50	
16	CLIP, HEADLAMP	3		\$ 12.00	
17	PROTECTOR LH, HEADLAMP	1		\$ 102.40	
18	FENDER LHS	1		\$ 383.70	
19	STAY LHS, FRONT FENDER	1		\$ 48.30	
20	FASTENER, MUDGUARD	15		\$ 45.00	
TOTAL PARTS				\$ 6,928.60	
TOTAL PARTS COST				\$ 6,928.60	
Labour Description					
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,650.00

	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER LH. 639	639	\$ 1,575.00
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS. 700	✓ NETT	\$ 330.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 120	✓	\$ 250.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. X		\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 180		\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES. 20	✓ NETT	\$ 100.00

Steve CLKK) WIL AML
 8322 8813 3 days
 P/P
 Ry Bel sy
 11/8/20, 10-15am

TOTAL LABOUR	\$ -	\$ 4,505.00
TOTAL PARTS	\$ -	\$ 6,928.60
TOTAL	\$ -	\$ 11,433.60
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
 WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
 PRICE AS WELL AS LABOUR CHARGES.

 Authorised Signature

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: