

ANNEX A

REPAIR DETAILS

Recommended Parts

No.	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount	
1	1	Rear lower floor panel	dented	\$ 2,830.00	\$ 2,830.00	1700 ✓
		Less 30%		\$ 849.00	\$ 849.00	1700 -30% 1190
				\$ 1,981.00	\$ 1,981.00	
2	1	Rear left taillamp	bent	\$ 372.00	\$ 372.00	X SVC
3	1	Rear left taillamp bracket	bent/necessary	\$ 114.00	\$ 114.00	X SVC
4	1	Rear right taillamp	cracked	\$ 372.00	\$ 372.00	✓ BR
5	1	Rear right taillamp bracket	bent/necessary	\$ 114.00	\$ 114.00	✓ BT
6	1	Rear no plate lamp	bent	\$ 88.00	\$ 88.00	X SVC
7	1	Rear no plate support bracket	bent	\$ 128.00	\$ 128.00	X SVC
8	2	Rear tailgate left rubber stopper	necessary	\$ 28.00	\$ 28.00	X SVC
9	2	Rear tailgate right rubber stopper	necessary	\$ 28.00	\$ 28.00	X SVC
10	1	Rear right hook	bent	\$ 195.00	\$ 195.00	X SVC
		Less 10%		\$ 143.90	\$ 143.90	486 -10% 437.40
				\$ 1,295.10	\$ 1,295.10	
<u>Special Nett Items</u>						
1	1	Rear left cabin door assy	dented	\$ 1,650.00	\$ 1,650.00	1500 ✓
2	1	Rear right cabin door assy	dented	\$ 1,650.00	\$ 1,650.00	1500 ✓
3	1	Rear left cabin door lock	bent	\$ 250.00	\$ 250.00	180 ✓
4	2	Rear right cabin door lock	bent	\$ 250.00	\$ 250.00	180 ✓
5	1	Rear left cabin door '70km/h' sticker	necessary	\$ 30.00	\$ 30.00	✓
6	1	Rear right cabin door sta emblem	necessary	\$ 30.00	\$ 30.00	✓
7	1	Rear towing bar	bent	\$ 650.00	\$ 650.00	X SVC
8	3	Rear tailgate left lower lock hinge	bent	\$ 388.00	\$ 388.00	X SVC
9	3	Rear tailgate right lower lock hinge	bent	\$ 388.00	\$ 388.00	X SVC
10	1	Rear left lock rod	bent	\$ 450.00	\$ 450.00	350 ✓
11	1	Rear right lock rod	bent	\$ 450.00	\$ 450.00	350 ✓
12	1	Rear no plate	bent	\$ 80.00	\$ 80.00	X SVC
				\$ 6,266.00	\$ 6,266.00	
<b>Total parts</b>				<b>\$ 9,542.10</b>	<b>\$ 9,542.10</b>	

4120

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear affected area, rear floor panel and replace rear damaged parts.	\$ 1,200.00	\$ 1,000.00 <i>600/</i>
2	To putty and spray painting rear portion.	\$ 1,200.00	\$ 1,000.00 <i>200/</i>
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00 <i>/</i>
4	To remove and install rear cabin door lock mechanism.	\$ 80.00	\$ 60.00 <i>50/</i>
5	To apply anti rust proofing to rear affected area.	\$ 140.00	\$ 120.00 <i>30/</i>
6	To remove and install both rear cabin door assy to facilitate the repair.	\$ 600.00	\$ 500.00 <i>400/</i>
		<u>\$ 3,270.00</u>	<u>\$ 2,710.00</u> <i>1310</i>

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 9,542.10	\$ 9,542.10
Total labour :	\$ 3,270.00	\$ 2,710.00
<b>Total repair cost :</b>	<b>\$ 12,812.10</b>	<b>\$ 12,252.10</b>

Adjusted Repair Cost (Lump Sum Repair)

\$ 9,800.00

*(1) P - 1190*  
*(2) P - 437.40*  
*NI - 4120*  
*L - 1310*  
  
*7057.40*  
  
*7 repair days* *L/S - 5645.92*  
*= 5650*

