

ANNEX A

REPAIR DETAILS

Recommended Parts

No.	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount	
1	1	Rear lower floor panel	dented	\$ 2,830.00	\$ 2,830.00	X R
				\$ 2,830.00	\$ 2,830.00	
		Less 30%		\$ 849.00	\$ 849.00	
				\$ 1,981.00	\$ 1,981.00	
2	1	Rear left taillamp	bent	\$ 372.00	\$ 372.00	X SVC
3	1	Rear left taillamp bracket	bent/necessary	\$ 114.00	\$ 114.00	X SVC
4	1	Rear right taillamp	cracked	\$ 372.00	\$ 372.00	✓ BR
5	1	Rear right taillamp bracket	bent/necessary	\$ 114.00	\$ 114.00	✓ BT
6	1	Rear no plate lamp	bent	\$ 88.00	\$ 88.00	X SVC
7	1	Rear no plate support bracket	bent	\$ 128.00	\$ 128.00	X SVC
8	2	Rear tailgate left rubber stopper	necessary	\$ 28.00	\$ 28.00	X SVC
9	2	Rear tailgate right rubber stopper	necessary	\$ 28.00	\$ 28.00	X SVC
10	1	Rear right hook	bent	\$ 195.00	\$ 195.00	X SVC
				\$ 1,439.00	\$ 1,439.00	
		Less 10%		\$ 143.90	\$ 143.90	
				\$ 1,295.10	\$ 1,295.10	
						486 -10% 437.40 ✓
		<u>Special Nett Items</u>				
1	1	Rear left cabin door assy	dented	\$ 1,650.00	\$ 1,650.00	1200 ✓
2	1	Rear right cabin door assy	dented	\$ 1,650.00	\$ 1,650.00	1200 ✓
3	1	Rear left cabin door lock	bent	\$ 250.00	\$ 250.00	180 ✓
4	2	Rear right cabin door lock	bent	\$ 250.00	\$ 250.00	180 ✓
5	1	Rear left cabin door '70km/h' sticker	necessary	\$ 30.00	\$ 30.00	✓
6	1	Rear right cabin door sta emblem	necessary	\$ 30.00	\$ 30.00	✓
7	1	Rear towing bar	bent	\$ 650.00	\$ 650.00	X SVC
8	3	Rear tailgate left lower lock hinge	bent	\$ 388.00	\$ 388.00	240 ✓
9	3	Rear tailgate right lower lock hinge	bent	\$ 388.00	\$ 388.00	240 ✓
10	1	Rear left lock rod	bent	\$ 450.00	\$ 450.00	350 ✓
11	1	Rear right lock rod	bent	\$ 450.00	\$ 450.00	350 ✓
12	1	Rear no plate	bent	\$ 80.00	\$ 80.00	X SVC
				\$ 6,266.00	\$ 6,266.00	
		Total parts		\$ 9,542.10	\$ 9,542.10	

4000 ✓

ANNEX B

REPAIR DETAILS

Recommended Labour

No.	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear affected area, rear floor panel and replace rear damaged parts.	\$ 1,200.00	\$ 1,000.00 <i>900/</i>
2	To putty and spray painting rear portion.	\$ 1,200.00	\$ 1,000.00 <i>200/</i>
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00 <i>/</i>
4	To remove and install rear cabin door lock mechanism.	\$ 80.00	\$ 60.00 <i>50/</i>
5	To apply anti rust proofing to rear affected area.	\$ 140.00	\$ 120.00 <i>30/</i>
6	To remove and install both rear cabin door assy to facilitate the repair.	\$ 600.00	\$ 500.00 <i>400/</i>
		<u>\$ 3,270.00</u>	<u>\$ 2,710.00</u>

1610

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 9,542.10	\$ 9,542.10
Total labour :	\$ 3,270.00	\$ 2,710.00
Total repair cost :	<u>\$ 12,812.10</u>	<u>\$ 12,252.10</u>

Adjusted Repair Cost (Lump Sum Repair) \$ 9,800.00

P - 437-49
NI - 4000
L - 1610
6047-40

7 repair days

L/S - 4837-92
= 4850