



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

Ref : CS/LAW20008044/Eqf3e2

GREAT EASTERN GENERAL INSURANCE (M) BHD  
C/O TAN KOK QUAN PARTNERSHIP  
1 WALLICH STREET #07-02GUOCO TOWER,  
SINGAPORE 078881

Date : 20-08-2020



Code : LAW

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	JSM 7	<b>Veh. Inspected</b>	GW 1756S
<b>Policy No.</b>	CF.MKC.so.0260.20-ge(m)	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	V9126417	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	STELLA OW	<b>Assign Date</b>	04/08/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	NISSAN CABSTAR	<b>c.c</b>	3153
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2003
<b>Chassis No.</b>	JN1SF4F23Z0850297	<b>Colour</b>	SILVER
<b>Odometer</b>	105721	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15	BRIDGESTONE	4 mm
<b>L/H Front Tyre</b>	195 R15	BRIDGESTONE	4 mm
<b>R/H Rear Tyre</b>	195 R15	BRIDGESTONE	4 mm
<b>L/H Rear Tyre</b>	195 R15	BRIDGESTONE	4 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	14/03/2019	<b>Inspection Date</b>	14/08/2020
<b>Survey held at</b>	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**