

First Capital Insurance Ltd
 6 Raffles Quay
 Singapore 048580

Vehicle number	SMP9698P
Make / Model	MERCEDES/S350
Chassis number	WDD2211562A197403
Accident date	30 July 2020
Reference	2008-01

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR FENDER RH	3500.00 <i>Rp</i>
1	REAR DOOR PANEL RH	2550.00 <i>bl</i>
1	REAR DOOR PROTECTOR RH	290.00 <i>mtw</i>
		6340.00
	Less 10%	634.00
	Subtotal	5706.00
	Balance C/F	5706.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	5706.00
1	JOINT SEALANT	120.00 <i>X</i>
1	WINDSCREEN SEALANT	120.00 <i>X</i>
1 SET	DOOR INNER TRIM CLIP	30.00 <i>X</i>
	Subtotal	270.00
	Balance C/F	5976.00
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	5976.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 <i>X</i>
2	REMOVE AND REFIT REAR LINING, TRIM AND GANRISH	120.00 <i>X</i>
3	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	150.00 <i>X</i>
4	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO REAR	200.00 <i>60.</i>
5	PANEL BEATING ON AFFECTED AREAS	1000.00 <i>500</i>
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 <i>500.</i>
7	APPLY ANTI RUST ON AFFECTED AREAS	90.00 <i>30.</i>
	Subtotal	2420.00
	Grand total	8396.00

Tanpin 97495749
wp 03-04 days
unp 5/8/20
Resurvey after repair
Tanpin & 11 hands on.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: