



CAS GARAGE PTE LTD

(Reg No: 20182806/M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address: NO 8, SHENTON WAY, #24-01
AXA TOWER, S(068811)

Xiao Tong

Telephone: 68804888 Fax: 68804740 Email: motor.survey@axa.com.sg

Make/ Model : MAZDA 5 DOOR WAGON SUNROOF

Date: 03.08.2020

Chassis No : JM6CW1071G0123799

Vehicle No: SLC9155U

Date/Time of Accide 28.07.2020/ 1140

Date of Reg: 30.05.2016

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BUMPER <i>Rebrand</i>	1	\$ 769.80		\$ ✓ 769.80
2	FRONT BUMPER RETAINERS <i>Neu</i>	2	\$ 78.60		\$ ✓ 157.20
3	FRONT BUMPER REFORCEMENT <i>Neu</i>	1	\$ 485.60		\$ + 485.60
4	FRONT BUMPER SPONGE <i>Cutted</i>	1	\$ 185.90		\$ ✓ 185.90
5	FRONT BUMPER LOGO <i>Neu</i>	1	\$ 85.70		\$ ✓ 85.70
6	FRONT FENDER INNER COWLING <i>Neu</i>	2	\$ 156.20		\$ + 312.40
7	FRONT GRILLE ASSY <i>cut</i>	1	\$ 698.70		\$ ✓ 698.70
8	FRONT BUMPER TOWING COVER <i>Neu</i>	1	\$ 58.90		\$ + 58.90
9	FRONT BUMPER LOWER GRILLE <i>Neu</i>	1	\$ 185.60		\$ + 185.60
10	FRONT ENGINE UNDERCOVER <i>Neu</i>	1	\$ 225.80		\$ + 225.80
11	FRONT SUPPORT PANEL <i>cutted</i>	1	\$ 658.20		\$ ✓ 658.20
12	FRONT SUPPORT PANEL TOP GARNISH <i>Neu</i>	1	\$ 198.70		\$ + 198.70
13	FRONT RADIATOR BRACE PANEL <i>Neu</i>	1	\$ 98.50		\$ + 98.50
14	FRONT HEADLAMPS <i>LH cutted</i>	2	\$ 1,650.80	1411	\$ 3301.60 1650.80
15	FRONT HEADLAMPS LOWER BRACKETS <i>cutted</i>	2	\$ 98.70		\$ 197.40 98.70
16	FRONT FOGLAMPS <i>2 neu</i>	2	\$ 256.80		\$ + 513.60
17	FRONT FOGLAMPS COVER <i>Neu</i>	2	\$ 168.90		\$ + 337.80
Total List Price Cost					\$ 8,314.20
PART DISCOUNT 20%					\$ 6,651.36

4065.20

3252.16

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING <i>nk</i>	1SET	\$ 50.00	\$ 50.00 <i>x</i> 50.00
2	FRONT BUMPER CLIPS <i>nk</i>	1 SET	\$ 30.00	\$ 30.00 <i>✓</i> 30.00
3	FRONT RADIATOR GRILLE CLIPS <i>nk</i>	1 SET	\$ 30.00	\$ 30.00 <i>20</i> 30.00
4	FRONT ENGINE UNDERCOVER CLIPS <i>nk</i>	1 SET	\$ 30.00	\$ 30.00 <i>x</i> 30.00
5	FRONT HEADLAMPS CLIPS <i>nk</i>	2 SETS	\$ 30.00	\$ 60.00 <i>20</i> 60.00
6	FRONT FENDER INNER COWLING CLIPS <i>nk</i>	2 SETS	\$ 30.00	\$ 60.00 <i>x</i> 60.00
7	SUPPORT PANEL TOP GARNISH CLIPS <i>nk</i>	1 SET	\$ 30.00	\$ 30.00 <i>x</i> 30.00
Total Special Nett Items				\$ 290.00

Labour Works/ Panel Beating Related Works		Quotation
Job Scope		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS		\$ 1,200.00 <i>600</i>
Spray Painting		
Job Scope		
TO RESPRAY AFFECTED AREAS		\$ 1,200.00 <i>250</i>
Others Cost (Accident Repair Related Expenses)		
Job Scope		
TO TUFFCOAT AFFECTED AREA		\$ 200.00 <i>x</i> 200.00
TO CONDUCT WIRING CHECK ON FRONT HEADLAMPS AND SETTLING		\$ 150.00 <i>30</i> 150.00
TO REMOVE / REFIT CONDENSER AND TOP UP AIR CON GAS		\$ 80.00 <i>x</i> 80.00
Total Others Cost		\$ 430.00
GRAND TOTAL		\$ 9,771.36

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allan@casgarage.sg
 Fax: +65 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 9282.16
2/s: 3.4K ✓

Adrian Lj
2/s 04/08/20
030 days

960

70