

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 43737

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0530/2020/NS
Date : 01-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : **FBA 66 G**

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

Hi Adrian,

10 days - ok - Jy - 18 Dec 20

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr Tan Kee Sin
Address : 7 Springside Place
Singapore 786410
Telephone : HP +65 98530071
Type of Claim : Own Damage Claim
Policy No. : 2100469178-04
Vehicle No : **SGQ 313 A**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Apr-16
Engine No : CVN 003173
Chassis No : WAUZZZF4XGA024898
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jul-20
Place of Accident : Transit Rd And Sembawang Rd Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGQ 313 A

S/n	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N	\$ 280.00		
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headliat washer assv.	S/N	\$ 360.00	\$	280.00
3	To remove and transfer lhs headlight control unit and power module.	S/N	\$ 350.00	\$	250.00
4	To remove and renew aircon condenser, addiotional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carrv out vacuum and reeas.	S/N	\$ 1,200.00	\$	1,200.00
5	To dismantle and reinstall lhs front door panel trim. To remove and reinstall lhs wing mirror	S/N	\$ 350.00		
6	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash managemnt components. Reinstall all		\$ 4,900.00	\$	2,250.00
7	To respray front bumper, lhs front fender, bonnet, hinges and lhs front door.		\$ 4,200.00	\$	1,650.00
8	To carry out wheel alignment check.	S/N	\$ 240.00		
9	Supplementary		\$ 300.00	\$	300.00
10	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 12,372.00	\$	6,122.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,111.00	\$ 1,688.80
2	FRONT BUMPER FIXING PARTS	\$ 282.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 70.00	\$ 27.84
4	FRONT BUMPER GRILLE - CENTRE	\$ 194.00	\$ 154.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 208.00	\$ 166.00
6	FRONT BUMPER AIR GUIDE - LH	\$ 62.00	\$ 49.52
7	RADIATOR GRILLE	\$ 1,799.00	\$ 1,439.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 361.00	\$ 288.80
9	FRONT BUMPER CARRIER	\$ 795.00	\$ 635.60
10	FRONT BUMPER BRACKET - LH	\$ 225.00	\$ 180.00
11	FRONT BUMPER GUIDE SECTION - LH	\$ 36.00	
12	FRONT BUMPER COVER	\$ 126.00	\$ 100.40
13	FRONT BUMPER FOAM FILLER PIECE	\$ 123.00	\$ 98.40
14	CAUTION SIGN STICKER	NEC \$ 14.00	\$ 10.80
15	AIRCON STICKER	NEC \$ 8.00	\$ 5.68
16	LOCK CARRIER BRACKET	\$ 136.00	\$ 108.40
17	LOCK CARRIER BRACKET SUPPORT - LH / RH	2 \$ 56.00	\$ 44.48
18	HORN - LH HIGH TONE	\$ 124.00	\$ 99.20
19	SPRING SHACKLE	\$ 29.00	\$ 22.56
20	FRONT FENDER - LH	\$ 758.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 7,517.00	\$ 5,120.48

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 5,120.48
21	FRONT FENDER ATTACHMENT PARTS		\$ 200.00	
22	FRONT FENDER CLOSING ELEMENT - LH		\$ 49.00	
23	FRONT FENDER BRACKET - LH		\$ 35.00	
24	DEFORMATION ELEMENT BRACKET - LH		\$ 49.00	
25	FRONT FENDER BRACE		\$ 117.00	
26	WHEEL HOUSING LINER - LH		\$ 237.00	
27	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 90.00	
28	WHEEL SPOILER		\$ 73.00	\$ 57.76
29	WHEE SPOILER TRIM - LH		\$ 35.00	\$ 27.36
30	STONE CHIP GUARD		\$ 50.00	\$ 40.72
31	BONNET		\$ 2,763.00	\$ 2,210.40
32	BONNET ATTACHMENT PARTS		\$ 121.00	
33	BONNET LID HINGE - LH / RH	2	\$ 602.00	
34	BONNET IMPACT PROTECTION - CENTRE		\$ 27.00	\$ 21.52
35	BONNET IMPACT PROTECTION - LH		\$ 28.00	\$ 21.84
36	BONNET IMPACT PROTECTION - RH		\$ 27.00	\$ 21.52
37	TOP FENDER LEDGE COVER - UPPER		\$ 31.00	
38	TOP FENDER LEDGE COVER - LOWER		\$ 23.00	
39	BONNET GAS FILLED STRUT	4	\$ 470.00	
40	BONNET STRIKER - LH / RH	2	\$ 100.00	\$ 39.44
SUB TOTAL SPARE PARTS CHARGES			\$ 5,127.00	\$ 7,561.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6941 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
				\$ 7,561.04
		<i>off</i>		
41	BONNET LID LOCK	2	\$ 423.00	
42	BONNET BOWDEN CABLE - CENTRE		\$ 57.00	
43	BONNET BOWDEN CABLE		\$ 57.00	
44	BONNET RELEASE LEVER		\$ 13.00	
45	LED HEADLIGHT - LH		\$ 7,693.00	\$ 6,154.40
46	MAIN LIGHT ELECTRONICS POWER MODULE		\$ 739.00	\$ 591.20
47	LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 742.00	
48	HEADLIGHT HOSE - LH		\$ 36.00	
49	HEADLAMP REPAIR KIT - LH		\$ 130.00	\$ 104.00
50	COMPENSATING PIECE		\$ 40.00	\$ 31.52
51	COMPENSATING PIECE		\$ 40.00	\$ 31.52
52	COMPENSATING PIECE		\$ 40.00	\$ 31.68
53	LIFT CYLINDER		\$ 208.00	\$ 166.00
54	LIFT CYLINDER CORRUGATED PIPE		\$ 92.00	
55	LOCK CARRIER		\$ 1,004.00	\$ 803.20
56	COOLANT REGULATOR SUPPORT		\$ 38.00	\$ 30.00
57	AIRCON CONDENSER		\$ 615.00	\$ 492.00
58	REFRIGERANT LINE		\$ 165.00	\$ 131.60
59	REFRIGERANT LINE		\$ 336.00	\$ 268.40
60	RADIATOR		\$ 647.00	\$ 517.60
SUB TOTAL SPARE PARTS CHARGES			\$ 13,115.00	\$ 16,914.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 16,914.16
61	RADIATOR RUBBER BUSH - LOWER	2	\$ 18.00	\$ 13.76
62	RADIATOR RUBBER BUSH - LOWER	2	\$ 24.00	\$ 19.20
63	ADDITIONAL RADIATOR		\$ 505.00	\$ 404.00
64	READY MIX COOLANT		\$ 91.00	\$ 72.32
65	RADIATOR FAN RING		\$ 242.00	\$ 193.60
66	RADIATOR FAN		\$ 1,896.00	
67	RADIATOR AIR GUIDE		\$ 28.00	\$ 22.08
68	RADIATOR AIR GUIDE - LH		\$ 12.00	\$ 9.36
69	RADIATOR AIR GUIDE - UPPER		\$ 16.00	\$ 12.72
70	RADIATOR AIR GUIDE - LOWER		\$ 22.00	\$ 17.04
71	AIR INTAKE AIR DUCT - RH		\$ 22.00	\$ 17.04
72	AIR INTAKE AIR GUIDE		\$ 53.00	
73	NOISE INSULATION		\$ 566.00	\$ 452.40
74	RADIATOR COOLANT HOSE		\$ 51.00	
75	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
76	SUPPLEMENTARY		\$ 1,060.00	\$ 846.40
77	SUNDRIES		\$ 350.00	\$ 128.24
TOTAL SPARE PARTS CHARGES			\$ 30,775.00	\$ 19,182.32
TOTAL LABOUR CHARGES			\$ 12,372.00	\$ 6,122.00
GRAND TOTAL			\$ 43,147.00	\$ 25,304.32

All charges are not inclusive of GST.
Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. PA/TP/0530/2020/NS Date 14-Aug-20 Service Advisor Glory Tan Pages 1 of 1 Regn No SQG 313 A Model No Audi A4 Sedan 1.4 TFSI S
--	--

Quantity	Description	Unit Price	Amount
Parts			
1	Temperature sensor bracket	\$ 18.00	\$ 14.40
2	Refrigerant pipe	\$ 517.00	\$ 413.20
3	Horn socket LHS	\$ 20.00	\$ 15.76
4	Radiator air guide RHS	\$ 28.00	\$ 22.08
5	Wheel spoiler RHS	\$ 73.00	\$ 57.76
6	Coolant hose quick release coupling lower	\$ 159.00	\$ 127.20
7	Refrigerant line	\$ 245.00	\$ 196.00
TOTAL		\$ 1,060.00	\$ 846.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. PA/TP/0530/2020/NS Date 14-Aug-20 Service Advisor Glory Tan Pages 1 of 1 Regn No SQQ 313 A Model No Audi A4 Sedan 1.4 TFSI S
--	--

Quantity	Description	Unit Price	Amount
Labours			
1	To remove and renew aircond refrigerant pipe. (from aircond compressor and aircon condenser to cut off point)	s/n \$ 300.00	\$ 300.00
TOTAL		<u>\$ 300.00</u>	\$ 300.00

For Premium Automobiles Pte Ltd

Authorised Signature