

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 43737

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0530/2020/NS
Date : 1-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : **FBA 66 G**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Kee Sin
Address : 7 Springside Place
Singapore 786410
Telephone : HP +65 98530071
Type of Claim : Own Damage Claim
Policy No. : 2100469178-04
Vehicle No : **SGQ 313 A**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Apr-16
Engine No : CVN 003173
Chassis No : WAUZZZF4XGA024898
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jul-20
Place of Accident : Transit Rd And Sembawang Rd Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGQ 313 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow vehicle from accident scene.	S/N	\$ 280.00	X
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N	\$ 360.00	280.
3	To remove and transfer lhs headlight control unit and power module.	S/N	\$ 350.00	250
4	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	✓
5	To dismantle and reinstall lhs front door panel trim. To remove and reinstall lhs wing mirror Assy.	S/N	\$ 350.00	X.
6	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 4,900.00	2250
7	To respray front bumper, lhs front fender, bonnet, hinges and lhs front door.		\$ 4,200.00	1650
8	To carry out wheel alignment check.	S/N	\$ 240.00	X.
9	To carry out diagnostic check.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES			: <u>\$ 12,072.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Distorted</i>	\$	2,111.00 ✓	1688.80
2	FRONT BUMPER FIXING PARTS <i>Not NEC</i>	\$	282.00 ✗	
3	FRONT BUMPER SECURING STRIP <i>Damaged</i>	2 \$	70.00 ✓	27.84
4	FRONT BUMPER GRILLE - CENTRE <i>could</i>	\$	194.00 ✓	154.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>tom</i>	\$	208.00 ✓	166.00
6	FRONT BUMPER AIR GUIDE - LH <i>Distorted</i>	\$	62.00 ✓	49.52
7	RADIATOR GRILLE <i>could</i>	\$	1,799.00 ✓	1439.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>missing</i>	\$	361.00 ✓	288.80
9	FRONT BUMPER CARRIER <i>Best</i>	\$	795.00 ✓	635.60
10	FRONT BUMPER BRACKET - LH <i>Damaged</i>	\$	225.00 ✓	180.00
11	FRONT BUMPER GUIDE SECTION - LH <i>Distorted item</i>	\$	36.00 ✗	
12	FRONT BUMPER COVER <i>could</i>	\$	126.00 ✓	100.40
13	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$	123.00 ✓	98.40
14	CAUTION SIGN STICKER ?	NEC \$	14.00 ✓	10.80
15	AIRCON STICKER <i>1pc</i>	NEC \$	8.00 ✓	5.68
16	LOCK CARRIER BRACKET <i>could</i>	\$	136.00 ✓	108.40
17	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>Damaged</i>	2 \$	56.00 ✓	44.48
18	HORN - LH HIGH TONE <i>could</i>	\$	124.00 ✓	99.20
19	SPRING SHACKLE <i>Best</i>	\$	29.00 ✓	22.56
20	FRONT FENDER - LH <i>Repair</i>	\$	758.00 ✗	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,517.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER ATTACHMENT PARTS	\$ 200.00	*
22	FRONT FENDER CLOSING ELEMENT - LH	\$ 49.00	*
23	FRONT FENDER BRACKET - LH	\$ 35.00	*
24	DEFORMATION ELEMENT BRACKET - LH	\$ 49.00	*
25	FRONT FENDER BRACE	\$ 117.00	*
26	WHEEL HOUSING LINER - LH <i>Not New</i>	\$ 237.00	*
27	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>	\$ 90.00	*
28	WHEEL SPOILER <i>crubd</i>	\$ 73.00	✓ 57.76
29	WHEE SPOILER TRIM - LH <i>missy</i>	\$ 35.00	✓ 27.36
30	STONE CHIP GUARD <i>new</i>	\$ 50.00	✓ 40.73
31	BONNET <i>Dented</i>	\$ 2,763.00	✓ 2210.40
32	BONNET ATTACHMENT PARTS <i>Not New</i>	\$ 121.00	*
33	BONNET LID HINGE - LH / RH <i>Not New</i>	2 \$ 602.00	+
34	BONNET IMPACT PROTECTION - CENTRE	\$ 27.00	✓ 21.52
35	BONNET IMPACT PROTECTION - LH	\$ 28.00	✓ 21.84
36	BONNET IMPACT PROTECTION - RH	\$ 27.00	✓ 21.52
37	TOP FENDER LEDGE COVER - UPPER	\$ 31.00	*
38	TOP FENDER LEDGE COVER - LOWER	\$ 23.00	*
39	BONNET GAS FILLED STRUT	4 \$ 470.00	*
40	BONNET STRIKER - LH / RH <i>LH Bent</i>	2 \$ 100.00	✓ 39.44
SUB TOTAL SPARE PARTS CHARGES		\$ 5,127.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	BONNET LID LOCK <i>new</i>	2 \$	423.00 <i>f</i>
42	BONNET BOWDEN CABLE - CENTRE	\$	57.00 <i>f</i>
43	BONNET BOWDEN CABLE	\$	57.00 <i>f</i>
44	BONNET RELEASE LEVER	\$	13.00 <i>x</i>
45	LED HEADLIGHT - LH <i>cracked</i>	\$	7,693.00 ✓ 6154.40
46	MAIN LIGHT ELECTRONICS POWER MODULE <i>Damaged</i>	\$	739.00 ? 591.20
47	LIGHT CONTROL SYSTEM CONTROL UNIT <i>Fire New</i>	\$	742.00 ?
48	HEADLIGHT HOSE - LH <i>new</i>	\$	36.00 <i>x</i>
49	HEADLAMP REPAIR KIT - LH <i>Damaged</i>	\$	130.00 ? 104.00
50	COMPENSATING PIECE ?	\$	40.00 ? 31.52
51	COMPENSATING PIECE <i>Damaged</i>	\$	40.00 ? 31.52
52	COMPENSATING PIECE	\$	40.00 ? 31.68
53	LIFT CYLINDER <i>Cracked</i>	\$	208.00 ? 166.00
54	LIFT CYLINDER CORRUGATED PIPE <i>new</i>	\$	92.00 <i>x</i>
55	LOCK CARRIER <i>Cracked</i>	\$	1,004.00 ✓ 803.20
56	COOLANT REGULATOR SUPPORT <i>Dmg</i>	\$	38.00 ? 30.00
57	AIRCON CONDENSER <i>Punctured</i>	\$	615.00 ✓ 492.00
58	REFRIGERANT LINE <i>Best</i>	\$	165.00 ? 131.60
59	REFRIGERANT LINE <i>Best</i>	\$	336.00 ? 268.40
60	RADIATOR <i>Best</i>	\$	647.00 ✓ 517.60
SUB TOTAL SPARE PARTS CHARGES		:	\$ 13,115.00

photo

photo

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGQ 313 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
61	RADIATOR RUBBER BUSH - LOWER <i>new</i>	2 \$	18.00 ✓ 13.76
62	RADIATOR RUBBER BUSH - LOWER <i>new</i>	2 \$	24.00 ✓ 19.20
<i>Photo</i> 63	ADDITIONAL RADIATOR <i>Dented</i>	\$	505.00 ✓ 404.00
64	READY MIX COOLANT <i>new</i>	\$	91.00 ✓ 72.32
65	RADIATOR FAN RING <i>could</i>	\$	242.00 ✓ 193.60
66	RADIATOR FAN <i>new</i>	\$	1,896.00 X
67	RADIATOR AIR GUIDE <i>Dented</i>	\$	28.00 ✓ 22.08
68	RADIATOR AIR GUIDE - LH <i>could</i>	\$	12.00 ✓ 9.36
69	RADIATOR AIR GUIDE - UPPER <i>Dented</i>	\$	16.00 ✓ 12.72
70	RADIATOR AIR GUIDE - LOWER <i>Dented</i>	\$	22.00 ✓ 17.04
71	AIR INTAKE AIR DUCT - RH <i>Dented</i>	\$	22.00 ✓ 17.04
72	AIR INTAKE AIR GUIDE <i>new</i>	\$	53.00 X
73	NOISE INSULATION <i>could</i>	\$	566.00 ✓ 452.40
74	RADIATOR COOLANT HOSE <i>new</i>	\$	51.00 X
75	FRONT NO PLATE <i>Dented</i>	S/N \$	60.00 ✓ 60.00
76	SUNDRIES <i>new</i>	\$	350.00 ✓ 128.24
TOTAL SPARE PARTS CHARGES		:	\$ 29,715.00
TOTAL LABOUR CHARGES		:	\$ 12,072.00
GRAND TOTAL		:	\$ 41,787.00

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 04/08/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 09 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd	Estimate No.	PA/TP/0530/2020/NS
78 Shenton Way	Date	14-Aug-20
#07-16 AIG Building	Service Advisor	Glory Tan
Singapore 079120	Pages	1 of 1
Attn: Mr. Adrian Ling - Motor Claims Dept	Regn No	SGQ 313 A
Tel: 6841 0055 - Fax: 6256 4315	Model No	Audi A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	Temperature sensor bracket <i>md</i>	\$ 18.00	\$ 14.40 ✓
2	Refrigerant pipe <i>Best</i>	\$ 517.00	\$ 413.20 ✓
3	Horn socket LHS <i>md</i>	\$ 20.00	\$ 15.76 ✓
4	Radiator air guide RHS <i>Best</i>	\$ 28.00	\$ 22.08 ✓
5	Wheel spoiler RHS <i>tom</i>	\$ 73.00	\$ 57.76 ✓
6	Coolant hose quick release coupling lower <i>md</i>	\$ 159.00	\$ 127.20 ✓
7	Refrigerant line <i>Best</i>	\$ 245.00	\$ 196.00 ✓
TOTAL		\$ 1,060.00	\$ 846.40

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/TP/0530/2020/NS

Date

14-Aug-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SGQ 313 A

Model No

Audi A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To remove and renew aircond refrigerant pipe. (from aircond compressor and aircon condenser to cut off point)	s/n \$ 300.00	\$ 300.00 ✓

TOTAL

\$ 300.00

\$

300.00

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]

Authorised Signature