

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 43628

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0531/2020/TF
Date	:	3-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mrs Kathuria Sweety
Address	:	33 Greenleaf Road Singapore 279333
Telephone	:	(HP) +65 98309076
Type of Claim	:	Own Damage Claims
Policy No.	:	1900013841-01
Vehicle No	:	SMH 8014 L
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	8/2/2019
Engine No	:	CVK 075900
Chassis No	:	WAUZZZF51KA024273
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Jul-20
Place of Accident	:	33 Greenleaf Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 8014 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	✓ ✓
2	To renew 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	✗
3	To install solar film for 1/4 glass.	S/N	\$ 400.00	✗
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	✗
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	✗
6	To dismantle rear bumper, rear lid and lhs sill panel trim. Cut out and weld lhs rear fender. To renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 7,200.00	500 -
7	To respray rear bumper, rear lid, lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$ 6,800.00	1100 ✓
8	To renew lhs rear exhaust silencer and align to position.	S/N	\$ 480.00	✗
9	To carry out diagnostic check.	S/N	\$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 18,532.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 8014 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Defound</i>	\$ 2,504.00	✓ 2003-20
2	REAR BUMPER FIXING PARTS <i>see in</i>	\$ 163.00	+
3	REAR BUMPER SECURING STRIP <i>new</i>	\$ 220.00	?
4	REAR BUMPER CHROME TRIM <i>? cracked</i>	\$ 1,005.00	? 804
5	REAR BUMPER REFLECTOR - LH <i>cut</i>	\$ 41.00	✓ 32.24
6	TAIL LIGHT - LH <i>crackd.</i>	\$ 1,129.00	✓ 903.20
7	TAIL LIGHT TRIM - LH <i>new</i>	\$ 30.00	+
8	TAIL LIGHT - LH <i>2 new</i>	\$ 1,008.00	+
9	TAIL LIGHT TRIM - RH	\$ 30.00	+
10	REAR BUMPER CARRIER <i>new</i>	\$ 886.00	?
11	REAR BUMPER CARRIER SEAL <i>new</i>	2 \$ 28.00	?
12	REAR BUMPER GUIDE SECTION - LH / RH <i>2 new</i>	2 \$ 44.00	+
13	REAR BUMPER GUIDE SECTION - LH	\$ 44.00	+
14	REAR PARKING AID SENSOR - INNER/OUTER <i>new 2</i>	TBC	?
15	BOOT LID CONTROL UNIT <i>new</i>	\$ 399.00	+
16	AERIAL RETAINER - LH <i>new</i>	\$ 25.00	+
17	TELEPHONE AERIAL <i>new</i>	\$ 169.00	+
18	VENT TRIM <i>new</i>	\$ 66.00	+
19	REAR FENDER - LH <i>Regis</i>	\$ 2,472.00	+
20	SIDE WINDOW - LH <i>new</i>	\$ 709.00	+
SUB TOTAL SPARE PARTS CHARGES		\$ 10,972.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 8014 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	REAR SILENCER - LH	\$ 873.00	X
22	REAR SILENCER DUAL CLIP	\$ 48.00	X
23	REAR SILENCER BRACKET	\$ 41.00	X
24	EXHAUST TAILPIPES TRIM	TBC	X
25	PACKING ADHESIVE	2 \$ 36.00	+
26	AUDI EMBLEM	\$ 138.00	+
27	A5 INSCRIPTION	\$ 95.00	+
28	SILL PANEL TRIM ATTACHMENT PARTS	\$ 129.00	+
29	SILL PANEL TRIM ADHESIVE TAPES	\$ 210.00	+
30	1/4 GLASS SEALANT	S/N \$ 100.00	+
31	METAL FILLER POWDER	S/N \$ 280.00	+
32	STONE CHIP	S/N \$ 180.00	+ ✓ 180
33	CAVITY WAX	S/N \$ 140.00	+ ✓ 140
34	ACRYLIC SEALANT	S/N \$ 180.00	+ ✓ 180
35	SUNDRIES	\$ 300.00	? 13.84
TOTAL SPARE PARTS CHARGES		\$ 13,722.00	
TOTAL LABOUR CHARGES		: \$ 18,532.00	
GRAND TOTAL		\$ 32,254.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Ling

Surveyed Date

:

04/08/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 04 Days. 9 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0531/2020/TF

Date

12-Aug-20

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SMH 8014 L

Model No

Audi A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Tail lamp panel LHS <i>bt ✓</i>	\$ 162.00	<i>129.20</i>
2	Rear bumper wiring set <i>ct ✓</i>	\$ 664.00	<i>530.80</i>

Labours

1	To dislodge and reinstall rear wire harness for lights, batter manager, fuse and relay trays, electrical and audio components.	s/n \$ 480.00	<i>✓</i>
2	To cut out and weld lhs tail lamp panel. To repair lhs rear fender.	\$ 3,600.00 <i>1500 (3 days)</i>	<i>✓</i>
3	To respray lhs tail lamp panel and rear end panelling. To carry out stone chip treatment and joint sealant works.	\$ 1,600.00 <i>1100 (2 days)</i>	<i>✓</i>

TOTAL

\$ 6,506.00

For Premium Automobiles Pte Ltd

Authorised Signature

Paul
12/08/2020
EXTRA 5 days
Subject to
insurance approval

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 43628

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0531/2020/TF
Date : 3-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

9 days - ok - Jy - 3 Nov 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mrs Kathuria Sweety
Address : 33 Greenleaf Road
Singapore 279333
Telephone : (HP) +65 98309076
Type of Claim : Own Damage Claims
Policy No. : 1900013841-01
Vehicle No : **SMH 8014 L**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : 8/2/2019
Engine No : CVK 075900
Chassis No : WAUZZZF51KA024273
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Jul-20
Place of Accident : 33 Greenleaf Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 8014 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To renew 1/4 glass to facilitate fender renewal.	S/N \$	300.00	
3	To install solar film for 1/4 glass.	S/N \$	400.00	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	
6	To dismantle rear bumper, rear lid and lhs sill panel trim. Cut out and weld lhs rear fender. To renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$	7,200.00	\$ 500.00
7	To respray rear bumper, rear lid, lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	6,800.00	\$ 1,100.00
8	To renew lhs rear exhaust silencer and align to position.	S/N \$	480.00	
9	Supplementary	\$	5,680.00	\$ 3,080.00
10	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 24,212.00	\$ 5,232.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 8014 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,504.00	\$ 2,003.20
2	REAR BUMPER FIXING PARTS	\$ 163.00	
3	REAR BUMPER SECURING STRIP	\$ 220.00	
4	REAR BUMPER CHROME TRIM	\$ 1,005.00	\$ 804.00
5	REAR BUMPER REFLECTOR - LH	\$ 41.00	\$ 32.24
6	TAIL LIGHT - LH	\$ 1,129.00	\$ 903.20
7	TAIL LIGHT TRIM - LH	\$ 30.00	
8	TAIL LIGHT - LH	\$ 1,008.00	
9	TAIL LIGHT TRIM - RH	\$ 30.00	
10	REAR BUMPER CARRIER	\$ 886.00	
11	REAR BUMPER CARRIER SEAL	2 \$ 28.00	
12	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 44.00	
13	REAR BUMPER GUIDE SECTION - LH	\$ 44.00	
14	REAR PARKING AID SENSOR - INNER/OUTER	2 TBC	
15	BOOT LID CONTROL UNIT	\$ 399.00	
16	AERIAL RETAINER - LH	\$ 25.00	
17	TELEPHONE AERIAL	\$ 169.00	
18	VENT TRIM	\$ 66.00	
19	REAR FENDER - LH	\$ 2,472.00	
20	SIDE WINDOW - LH	\$ 709.00	
SUB TOTAL SPARE PARTS CHARGES		<u>\$ 10,972.00</u>	<u>\$ 3,742.64</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 8014 L

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			S/Nett	Remarks
		c/f		\$ 3,742.64
21	REAR SILENCER - LH		\$ 873.00	
22	REAR SILENCER DUAL CLIP		\$ 48.00	
23	REAR SILENCER BRACKET		\$ 41.00	
24	EXHAUST TAILPIPES TRIM		TBC	
25	PACKING ADHESIVE	2	\$ 36.00	
26	AUDI EMBLEM		\$ 138.00	
27	A5 INSCRIPTION		\$ 95.00	
28	SILL PANEL TRIM ATTACHMENT PARTS		\$ 129.00	
29	SILL PANEL TRIM ADHESIVE TAPES		\$ 210.00	
30	1/4 GLASS SEALANT	S/N	\$ 100.00	
31	METAL FILLER POWDER	S/N	\$ 280.00	
32	STONE CHIP	S/N	\$ 180.00	\$ 180.00
33	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
34	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
35	SUPPLEMENTARY		\$ 826.00	\$ 660.00
36	SUNDRIES		\$ 300.00	\$ 13.84
TOTAL SPARE PARTS CHARGES			\$ 14,548.00	\$ 4,916.48
TOTAL LABOUR CHARGES			\$ 24,212.00	\$ 5,232.00
GRAND TOTAL			\$ 38,760.00	\$ 10,148.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0531/2020/TF
12-Aug-20
Glory Tan
1 OF 1
SMH 8014 L
Audi A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Tail lamp panel LHS	\$ 162.00	\$ 129.20
2	Rear bumper wiring set	\$ 664.00	\$ 530.80
			\$ 660.00
Labours			
1	To dislodge and reinstall rear wire harness for lights, batter manager, f use and relay trays, electrical and audio components.	s/n \$ 480.00	\$ 480.00
2	To cut out and weld lhs tail lamp panel. To repair lhs rear fender.	\$ 3,600.00	\$ 1,500.00
3	To respray lhs tail lamp panel and rear end panelling. To carry out stone chip treatment and joint sealant works.	\$ 1,600.00	\$ 1,100.00
TOTAL		\$ 6,506.00	\$3,740.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant