

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 43628

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0531/2020/TF
Date : 3-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mrs Kathuria Sweety
Address : 33 Greenleaf Road
Singapore 279333
Telephone : (HP) +65 98309076
Type of Claim : Own Damage Claims
Policy No. : 1900013841-01
Vehicle No : **SMH 8014 L**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : 8/2/2019
Engine No : CVK 075900
Chassis No : WAUZZZF51KA024273
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Jul-20
Place of Accident : 33 Greenleaf Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 8014 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	✓
2	To renew 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00	✗
3	To install solar film for 1/4 glass.	S/N	\$ 400.00	✗
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	✗
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	✗
6	To dismantle rear bumper, rear lid and lhs sill panel trim. Cut out and weld lhs rear fender. To renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 7,200.00 500	✓
7	To respray rear bumper, rear lid, lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$ 6,800.00 1100	
8	To renew lhs rear exhaust silencer and align to position.	S/N	\$ 480.00	✗
9	To carry out diagnostic check.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 18,532.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 8014 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Deland</i>	\$ 2,504.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 163.00	+
3	REAR BUMPER SECURING STRIP ?	\$ 220.00	?
4	REAR BUMPER CHROME TRIM ?	\$ 1,005.00	?
5	REAR BUMPER REFLECTOR - LH <i>at</i>	\$ 41.00	✓
6	TAIL LIGHT - LH <i>could.</i>	\$ 1,129.00	✓
7	TAIL LIGHT TRIM - LH <i>new</i>	\$ 30.00	+
8	TAIL LIGHT - LH <i>2 new</i>	\$ 1,008.00	+
9	TAIL LIGHT TRIM - RH	\$ 30.00	+
10	REAR BUMPER CARRIER ?	\$ 886.00	?
11	REAR BUMPER CARRIER SEAL ?	2 \$ 28.00	?
12	REAR BUMPER GUIDE SECTION - LH / RH <i>2 new</i>	2 \$ 44.00	+
13	REAR BUMPER GUIDE SECTION - LH <i>new</i>	\$ 44.00	+
14	REAR PARKING AID SENSOR - INNER/OUTER	2 TBC	?
15	BOOT LID CONTROL UNIT <i>new</i>	\$ 399.00	+
16	AERIAL RETAINER - LH <i>new</i>	\$ 25.00	+
17	TELEPHONE AERIAL <i>new</i>	\$ 169.00	+
18	VENT TRIM <i>new</i>	\$ 66.00	+
19	REAR FENDER - LH <i>new</i>	\$ 2,472.00	+
20	SIDE WINDOW - LH <i>new</i>	\$ 709.00	+
SUB TOTAL SPARE PARTS CHARGES		\$ 10,972.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 8014 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	REAR SILENCER - LH	\$	873.00 ✓
22	REAR SILENCER DUAL CLIP	\$	48.00 ✓
23	REAR SILENCER BRACKET	\$	41.00 ✓
24	EXHAUST TAILPIPES TRIM		TBC ✓
25	PACKING ADHESIVE	2 \$	36.00 ✓
26	AUDI EMBLEM	\$	138.00 ✓
27	A5 INSCRIPTION	\$	95.00 ✓
28	SILL PANEL TRIM ATTACHMENT PARTS	\$	129.00 ✓
29	SILL PANEL TRIM ADHESIVE TAPES	\$	210.00 ✓
30	1/4 GLASS SEALANT	S/N \$	100.00 ✓
31	METAL FILLER POWDER	S/N \$	280.00 ✓
32	STONE CHIP	S/N \$	180.00 ✓
33	CAVITY WAX	S/N \$	140.00 ✓
34	ACRYLIC SEALANT	S/N \$	180.00 ✓
35	SUNDRIES	\$	300.00 ✓
TOTAL SPARE PARTS CHARGES		\$	13,722.00
TOTAL LABOUR CHARGES		:	\$ 18,532.00
GRAND TOTAL		\$	32,254.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Name : Adnan Ling
Surveyed Date : 04/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant