

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904039G
GST Reg. M2-0088864-2

Estimate

04/08/2020

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1 138681

Veh # :- SGS1130T

Veh Model :- VOLVO XC90

Estimate# :- CK420858

Claim # :-

ACC. Date :- 29/07/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
	SIDE GARNISH, SIDE COVER AND OTHER ATTACHMENT PARTS			
				11,825.28
	TO RUST PROOF AFFECTED AREAS			60.00
		1546		40 98.00
	TO REMOVE & REFIX REAR EXHAUST BOX, PIPE, HEAT SHIELD AND OTHER ATTACHMENT PARTS			13,425.28
		206		80.00
	LABOUR TOTAL S\$			2,170.00

45 - 10,700

6 days 10,740.22

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

GST @ 7 %

AMOUNT DUE S\$

20,677.68

1,447.44

22,125.12

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
hp 90010068

6 days
L/S

05/08/2020
@1440

Resy after repair



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088984-2

Estimate

04/08/2020

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909.

Page # :- 1

Veh # :- SGS1130T

Veh Model :- VOLVO XC90

Estimate# :- CK420858

Claim # :-

ACC. Date :- 29/07/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No. Description

Qty U.Price Amounts S\$

LIST ITEMS :

1. REAR BOOT *de*
2. REAR BOOT LOGO *de*
3. REAR BOOT EMBLEM "XC" *de*
4. REAR BOOT EMBLEM "90" *de*
5. REAR BOOT EMBLEM "T5" *de*
6. REAR BOOT EMBLEM "AWD" *de*
7. REAR BOOT LOCK *cut*
8. REAR BOOT RUBBER *cut*
9. REAR WINDSCREEN MOULDING *de*
10. REAR LAMP LH *cut*
11. REAR BUMPER TOP *de*
12. REAR BUMPER LOWER *de*
13. REAR BUMPER LOWER SPOILER *de*
14. REAR BUMPER REFLECTOR L+R *de*
15. REAR BUMPER SENSOR *de*
16. REAR BUMPER WIRE *cut*
17. REAR BUMPER SPONGE *cut*
18. REAR BUMPER REINFORCEMENT *cut*
19. REAR BUMPER BRACKET L+R *cut*
20. REAR BUMPER LOWER RETAINER *cut*
21. REAR BUMPER RIVET *cut*
22. REAR EXHAUST BOX *cut*
23. REAR EXHAUST TAIL PIPE *cut*
24. REAR EXHAUST HEAT SHIELD *cut*
- 25.

LIST TOTAL S\$

10% DISCOUNT S\$

SPECIAL NET ITEMS :

1. REAR WINDSCREEN SEALANT

SPECIAL NET TOTAL S\$

LABOUR :

TO CUT & WELD END PANEL, TO REPAIR REAR PANEL
REAR FLOOR PANEL, TO REMOVE & REFIX DAMAGED
PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS
AREAS.

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX REAR WINDSCREEN GLASS

TO REMOVE & REFIX REAR BOOT MACHANISM, CHECK
& TEST WIPER MOTOR AND CENTRE LOCKING SYSTEM

TO REMOVE & REFIX REAR LAGGAGE COMPARTMENT

1	PC	4,144.70	4,144.70
1	PC	140.80	140.80
1	PC	114.30	114.30
1	PC	114.30	114.30
1	PC	114.30	114.30
1	PC	98.30	98.30
1	PC	440.00	440.00
1	PC	369.00	369.00
1	PC	217.00	217.00
1	PC	655.70	655.70
1	PC	2,550.50	2,550.50
1	PC	2,550.50	2,550.50
1	PC	1,750.00	1,750.00
2	PC	199.70	399.40
2	PC	398.20	796.40
4	PC	99.20	396.80
1	PC	966.10	966.10
1	PC	189.20	189.20
1	PC	1,750.60	1,750.60
2	PC	87.20	174.40
2	PC	27.60	55.20
10	PC	10.80	108.00
1	PC	950.10	950.10
2	PC	398.50	797.00
1	PC	620.60	620.60

20,475.20

-2,047.52

18,427.68

1 PC

80.00

80.00

80.00

600 840.00

600 850.00

120 180.00

40 80.00