LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Ben Tang Date: 04 Sep 2020

Preliminary Advice

Insured Vehicle No : SGX2429A

TP Vehicle No : SML2390T Accident Date : 01/08/2020 : TOYOTA NOAH HYBRID **Assignment Date** : 04/09/2020 Make

: 05/08/2020 Est. Duration of Repair Date of Inspection : 3

Inspection At : RICO 60 AUTO SERVICES PTE LTD (HQ)

8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front LH portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 62.024.00

Revised Amount 6,850.00 lump sum :S\$

Check Items (Estimated) :S\$ 0.00 Total :S\$ 6,850.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Survey on WP (x)