



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2005902
INV Date 27/08/2020
Reference CS/SMO20008068/Uvf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SBT 6877T
Insured Veh. SLD 8015S
Claim No. CMTD2002277/GPL
Policy No.
Accident Date 03/08/2020
Inspection Date 05/08/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20008068/Uvf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-08-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 8015S	Veh. Inspected	SBT 6877T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002277/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDGG20W90J003595	Colour	ORANGE
Odometer	84094	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2020	Inspection Date	05/08/2020
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBT 6877T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP (RH)	NOT NECESSARY	549.20	-
1	REAR BUMPER	DEFORMED / TORN	1,377.00	566.20
8	REAR BUMPER CLIPS @\$8.90	NECESSARY	71.20	50.00
2	REAR BUMPER SIDE ATTACHMENT @\$58.40	O/S BENT	116.80	58.40
1	REAR BUMPER SPLASH SHIELD (RH)	NOT NECESSARY	121.00	-
1	REAR BUMPER BRACKET (RH)	NOT NECESSARY	111.20	-
1	REAR END PANEL	DENTED	581.40	581.40
1	REAR PANEL INNER GARNISH	NOT NECESSARY	244.90	-
1	REAR FENDER INNER BOARD	NOT NECESSARY	780.00	-
5	REAR FENDER INNER BOARD CLIP @\$12.90	NOT NECESSARY	64.50	-
1	REVERSE SENSOR WITH CONTROL UNIT ORIGINAL	SHORTED	350.00	330.13
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	893.00	-
	LESS 25% DISCOUNT		-1,315.05	-396.53
			3,945.15	1,189.60
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO APPLY UNDERSEALING ON AFFECTED AREA.		120.00	30.00
	TO REMOVE/REFIX REVERSE SENSOR WITH CONTROL UNIT.		120.00	50.00
	TO REMOVE AND REFIX TRIM,GARNISH,UPHOLSTERY AND ETC.		220.00	60.00
	TO REPLACE NEW PARTS,CUT,WELD,KNOCK,AND ETC.INCLUSIVE OF THE REPAIR OF REAR FENDER (RH).		1,100.00	680.00
	TO RESPRAY ON AFFECTED AREAS.		880.00	600.00
	-		-	-
	-		-	-
	-		-	-
			2,490.00	1,440.00
	GRAND TOTAL		6,435.15	2,629.60

Report Ref No. CS/SMO20008068/Uvf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CS/SMO20008068/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBT 6877T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBT 6877T

RE-INSPECTION

