

Finalize form

ComfortDelgro Engineering Pte Ltd
45 Pandan Road S (609286)
Tel : 68676919 Fax : 62626950

**Amended
Finalization Form**

Bill To :	<u>ERGO INS</u>	Vehicle No. :	<u>GBB7361C</u>
Attention :	<u>Mr Rasul</u>		<u>DOA @ 28.07.2020</u>
A. Spare parts			
List Price		: \$	<u>6,170.18</u>
<u>10%</u> Discount / Plus		: \$	<u>-617.01</u>
			<u>5,553.17</u>
B. Nett Price		: \$	<u></u>
<u></u> Discount / Plus		: \$	<u>-</u>
C. Special Nett		: \$	<u>1,035.00</u>
D. Labour		: \$	<u>1,350.00</u>
	Finalized Total :	: \$	<u>7,938.17</u>
E. Lump Sum (less <u>20</u> %)		: \$	<u>-1,587.63</u>
		: \$	<u>6,350.53</u>
F. Less Excess		: \$	<u></u>
	Total Amount :	: \$	<u>6,300.00</u>

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm & revert by fax. Thanks

Submitted By / Date : Wong Chee Wei / 18.08.2020

Confirmed By / Date :

Spare Parts

Vehicle No. : **GBB7361C** Submit By : **C. W WONG**
 Make & Model : **FIAT DOBLO 1.3MJTD** Year Manufacture : **2009**
 Chassis No. : **ZFA22300005694695** Engine No. : **199A20003217779**

TP**S/Order**

S/No.	Part Description	Qty	Original Cost Price	Nett Price	List Price	S- Nett Price	Disposition By Surveyor
1	LHS REAR TAIL GATE <i>lt/</i>	1			\$1,831.41 ✓		
2	REAR TAIL GATE WEATHERSTRIP - PN-1 <i>ne/</i>	1			\$292.41 ✓		
3	REAR TAIL GATE SIDE SEAL - PN-2 <i>ne/</i>	1			\$328.51 ✓		
4	LHS REAR TAIL GATE LOCK UPPER <i>XX SVC</i>	1			\$166.35		
5	LHS REAR TAIL GATE LOCK LOWER <i>cm/</i>	1			\$166.35 ✓		
6	LHS REAR TAIL GATE TRIM COVER <i>cm/</i>	1			\$250.20 ✓		
7	3RD BRAKE LAMP <i>X X SVC</i>	1			\$102.00		
8	LHS LISENCE PLATE LAMP <i>? X SVC</i>	1			\$49.88		
9	RHS LISENCE PLATE LAMP <i>? X SVC</i>	1			\$49.88		
10	WIPER NOZLE JET <i>X X SVC</i>	1			\$23.40		
11	LHS TAIL LAMP <i>cm/</i>	1			\$280.02 ✓		
12	LHS TAIL LAMP GARNISH <i>cm/</i>	1			\$352.20 ✓		
13	RHS REAR TAIL GATE - PN - 1 <i>lt/</i>	1			\$1,718.36 ✓		
14	RHS REAR TAIL GATE LOCK UPPER - PN-8 <i>X X SVC</i>	1			\$167.96		
15	RHS REAR TAIL GATE LOCK LOWER - PN - 9 <i>X X SVC</i>	1			\$166.35		
16	RHS TAIL GATE OUTER HANDLE - PN - 12 <i>X X SVC</i>	1			\$213.31		
17	STICKER COMPANY DECAL - BACK , LHS & RHS REAR <i>ne/</i>	1				\$1,200.00	900
18	STICKER - 70 KM/H <i>ne/</i>	1				\$10.00 ✓	
19	STICKER - 5 PAX (BLACK) <i>ne/</i>	1				\$10.00 ✓	
20	REAR NUMBER PLATE <i>ser/</i>	1				\$45.00 <i>38</i>	
21	WINDSCREEN SEALANT <i>ne/</i>	1				\$40.00 ✓	
22	REAR WINDSCREEN INNER SEAL <i>ne/</i>	1				\$40.00 ✓	
23	REAR BUMPER - PN-7 <i>de/</i>	1			\$281.20 ✓		
24	REAR BUMPER LHS GARNISH - PN-6 <i>cm/</i>	1			\$241.68 ✓		
25	REAR BUMPER RHS GARNISH <i>X X SVC</i>	1			\$241.68		
26	REAR BUMPER RHS REFLECTOR - PN- 10 <i>ml/</i>	1			\$37.62 ✓		
27	REAR BUMPER LHS REFLECTOR <i>X CRACK</i>	1			\$37.62 ✓		
28	LHS REAR BUMPER SENSOR <i>? X SVC</i>	1			\$352.00		
29	RHS REAR BUMPER SENSOR <i>? X SVC</i>	1			\$352.00		
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)
Tel: 68676919 Fax: 62626950.68676903

Labour

Submit By : : **C. W WONG**

Year of Manufacture : 2009

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel:68676919 Fax: 62626950

Appendix A

Spare PartsVehicle No. : **GBB7361C** Submit By : **C. W WONG**Make & Model : **FIAT DOBLO 1.3MJTD** Year Manufacture : **2009**Chassis No. : **ZFA22300005694695** Engine No. :**Supplementary****Cost / List**

S/No.	Part Description	Qty	Cost Price	List Price	Disposition by Surveyor
1	REAR REINFORCEMENT bent	1		\$352.60	
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			
24		1			
25		1			
26		1			
27		1			
28		1			
29		1			
30		1			

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☐ Own Damage
☒ 3rd Party
☐ Windscreen

Vehicle No. : **GBB7361C**
Make & Model : **FIAT / DOBLO 1.3MJTD**
Year of Manufacture : **2009**
Chassis No. : **ZFA22300005694695**
Engine No. : **199A20003217779**
Policy No. :
Time of Accident : **16.15 P.M**

Ins Company : **ERGO INS**
Excess :
Date of Accident : **28/07/2020**
Suggested Days of Repair : **10 Day**

In-house Vehicle Assessor

Repair Estimates

Name : **C. W WONG**
Signature :
Contact No : **68676919 Or 97239882**

Parts (a) Cost Price Items **\$7,813.59**
Less 10 % **\$(781.35)**
(b) Nett Price Items
Less %
(c) Special Nett Items **\$1,345.00**
Total Parts Cost (Appendix A) **\$8,377.24**
Labour (Appendix B) **\$2,380.00**
Total Repair Cost **\$10,757.24**

The above total will be subjected to 7% G.S.T.

Name of Surveyor : **Rasul - 4p 90010068**
Company : **LKK**
Survey conducted on : **05/08/2020** at **12 10**

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : **5** day(s)

(c) Resurvey : **Required** / Not Required

(d) Excess : \$

(e) Signature of surveyor : **Ru**

Date: **05/08/2020**

Ready after repair