

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: To: M/s MSIG Insurance (Singapore) Pte Ltd

Address: 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

Business Reg. No.: 201626438D

6744 0777

6744 2377

Estimate Quotation


Quotation No	Aug 001/2020
Date	03/08/20
Vehicle No	SLD8132L
Make / Model	Toyota Wish

Xiao Chen

JTDGJ20W905001842

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper <i>Rebond</i>		\$ 795.00 <i>588</i>
2 pcs	rear bumper side retainer <i>re</i>	\$ 97.00	\$ 194.00 <i>✓</i>
1 set	rear bumper clips <i>re</i>		\$ 50.00 <i>30</i>
2 pcs	rear bumper bracket <i>re</i>	\$ 95.00	\$ 190.00 <i>✓</i>
1 set	rear bumper reverse sensor <i>Dayd</i>		\$ 200.00 <i>✓</i>
2 pcs	rear bumper reflector <i>re</i>	\$ 97.00	\$ 194.00 <i>✓</i>
1 pc	rear end panel <i>Dented</i>		\$ 670.00 <i>585</i>
1 pc	rear end panel top garnish <i>cracked</i>		\$ 368.00 <i>295</i>
1 set	rear end panel top garnish clip <i>re</i>		\$ 50.00 <i>10</i>
1 pc	tailgate "TOYOTA" emblem <i>re</i>		\$ 78.00 <i>✓</i>
1 pc	tailgate <i>Dented</i>		\$ 1,768.00 <i>1272</i>
1 pc	tailgate inner lock (top) <i>Dayd</i>		\$ 491.00 <i>361</i>
1 pc	tailgate inner lock (lower) <i>re</i>		\$ 135.00 <i>✓</i>
1 pc	tailgate windstrip <i>re</i>		\$ 421.00 <i>344</i>
1 pc	tailgate chrome handle (outer) <i>re</i>		\$ 378.00 <i>✓</i>
2 pcs	tailgate reflector lamp <i>re</i>	\$ 385.00	\$ 770.00 <i>✓</i>
2 pcs	tail lamp <i>re</i>	\$ 654.00	\$ 1,308.00 <i>408</i>
1 set	tailgate inner trim board clip <i>re</i>		\$ 50.00 <i>✓</i>
1 pc	tailgate inner trim board <i>re</i>		\$ 493.00 <i>✓</i>
1 pc	tailgate glass moulding <i>re</i>		\$ 365.00 <i>178</i>
1 pc	tailgate glass sealant <i>re</i>		\$ 80.00 <i>60(SN)</i>
1 pc	rear number plate <i>re</i>		\$ 60.00 <i>✓</i>
1 pc	rear end panel sealant <i>re</i>		\$ 100.00 <i>60(SN)</i>
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,000.00 <i>800</i>
2	to putty and spray painting on affected area		\$ 1,200.00 <i>800</i>
3	anti rust		\$ 100.00 <i>80</i>
4	wiring check		\$ 80.00 <i>30</i>
5	R&R tailgate glass		\$ 150.00 <i>120</i>
6	R&R reverse sensor		\$ 80.00 <i>50</i>
	<i>Rand R video recorder</i>		\$ 100.00 <i>50</i>
	<i>Rand R upholstery</i>		\$ 150.00 <i>80</i>
	<i>Rand R Tailgate fittings</i>		\$ 150.00 <i>80</i>
	Subtotal:		\$ 11,718.00

BEST SOLUTION AUTOCARE PTE LTD



Authorised Signature

Total: 5617.25
HS: 4.5K 07 Days

ASK