

*Not Authorized
11 Day @ 3800ph
Running After Paint*

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be surveyed
 • No illegal modification(s) is allowed
 • Third party survey is on a "Without Prejudice" basis
 • Parts prices are subject to confirmation
 • To display damaged part(s) during resurvey
 • To resurvey before/after spray painting
 • The Repairer of the following:
 LKK Auto Consultants hence notify

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel: 6266 9511 Fax : 6266 9512

Vehicle No: SMJ6179Y and
 Vehicle Model: Honda Freed

Acknowledged by Repairer
 Signature:
 Date:

Estimate Repair Cost

No.	Qty	Parts List Items		
1	1	Front bumper		
2	2	Front bumper retainers		
3	2	Front bumper brackets		
4	1	Front bumper reinforcement		
5	1 set	Front bumper clips		
6	1	Side mirror assy RH <i>854</i>		
7	1	Front fender RH		
8	1	Front fender inner shield RH		
9	1	Front shock absorber RH <i>325</i>		
10	1	Front lower arm RH		
11	1	Front knuckle arm RH		
12	1	Front knuckle arm bearing RH		
13	1	Front wheel rim RH		
14	1	Sliding door RH		
15	1	Rear fender RH		
			<i>208</i>	
			Total	\$ 6,984.50

urgent 18hr
also 18hr
 \$ 900.60 ✓
 \$ 39.00 ✓
 \$ 70.20 X
 \$ 409.50 X
 \$ 40.00 ✓
 \$ 1,004.30 ✓
 \$ 546.20 ✓
 \$ 95.60 X
 \$ 351.10 ✓
 \$ 243.80 ✓
 \$ 360.80 ✓
 \$ 136.50 ✓
 \$ 261.60 ✓
 \$ 1,179.80 X
 \$ 1,345.50 X
 Total \$ 6,984.50

Parts Special Nett Items

16	1	Front tyre RH		
				\$ 200.00 X
				\$ 200.00
			Total Parts	\$ 7,184.50

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,800.00	<i>600</i>
2	To putty and respray painting on affected areas.	\$ 1,500.00	<i>1000</i>
3	To remove, replace fenders and door fittings to facilitate repair.	\$ 400.00	<i>X</i>
4	To remove, replace front shock absorber, lower arm and knuckle arm.	\$ 300.00	<i>200</i>
5	To remove, replace front tyre and wheel rim.	\$ 100.00	<i>200</i>
6	To check wiring and lightings.	\$ 80.00	<i>200</i>
		Total Labour	\$ 4,180.00
		Total Parts and Labour	\$ 11,364.50