

ASS. REC. BY:

REF: MSG/ 2000 8074/KV

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Veh No: SMS 61794 Yr Regn: 03, 19

Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Traller or Wagon

To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s Henry Yap Seng

Make: Honda Freed c.c. 1496

of \_\_\_\_\_

Colour: M. Grey A/C: Insured / Std / Nil / NA

Insured: \_\_\_\_\_

Sp. Reading: 140881 T/Radio: Insured / Std / Nil / NA

Policy No. \_\_\_\_\_

Eng/No: \_\_\_\_\_

Claims No. \_\_\_\_\_

C/No: GB7 107985

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

(Client's Record)

Steering: In order / Jammed / Leaked / Burnt or

Make of Veh: \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or

(Policy Condition)

Modi: Nil S/Rlm / STD A/Rlm or

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: Windforce 185/65R15

Bal. or Market Value: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or APlus

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

Front R/Bal. 0 mm Rear R/Bal. 0 mm  
L/Bal. 0 mm L/Bal. 0 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

D.O.A. 31/7/20 D.O.I. 5/8/2020

Est. Repairs: 05 days Res.: Yes or No

Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or 015 RA

Lum Sum: 20 % 3 Val.: Yes or No

The UIC / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>1</u>	<u>Est NOT ready</u>
	<u>11 Day @ 3800</u>

File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: 5  
Resurvey No. of Trip: 2

File Return to? 24/9/20-Typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS. SI	
Fuel	
Others	
TOTAL	

Report Format: Merimen  
Lump Sum H.B.: (\$ 3800)