

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305414586
 REGN NO : SHC7042Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 04.03.2016
 DATE/TIME IN : 02.08.2020 19:35
 ACCIDENT DATE : 02.08.2020

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	de ✓
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	de ✓
0003	04-01-0103-0851-G	REAR BUMPER REFLECTOR LH	1	32.00	20.00	25.60	cur ✓
0004	04-01-0103-0739-G	REAR BUMPER SPONGE	1	119.50	20.00	95.60	7 u7 ✓
0005	04-01-0103-0740-G	REAR BUMPER BEAM	1	428.40	20.00	342.72	7 u7 ✓
0006	04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60	nei ✓
0007	04-01-0103-0785-G	BOOTLID MOULDING	1	85.00	20.00	68.00	de ✓
0008	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	1	27.90	20.00	22.32	nei ✓
0009	04-01-0103-0787-G	BOOTLID EMBLEM-I40	1	27.90	20.00	22.32	nei ✓
0010	04-01-0103-0789-G	BOOTLID EMBLEM-HYUNDAI	1	21.10	20.00	16.88	nei ✓
0011	04-01-0103-0800-G	BOOTLID EMBLEM-H	1	28.70	20.00	22.96	nei ✓
0012	04-01-0103-0581-A	TAILLAMP LH	1	697.80	20.00	558.24	cur ✓
0013	04-01-0103-0584-G	BOOTLID LAMP LH	1	565.60	20.00	452.48	x u7 ✓

TS

REPAIR ESTIMATE

*NTUC-4S
LKK-Tanfah*

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305414586
 REGN NO : SHC7042Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 04.03.2016
 DATE/TIME IN : 02.08.2020 19:3
 ACCIDENT DATE : 02.08.2020

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

0014 28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	30.00	10.00	27.00	<i>res ✓</i>	
0015 28-01-0103-0006-A	BOOTLID 65521111	1	30.00	10.00	27.00	<i>res ✓</i>	<i>1875.12</i>

SUB-TOTAL : 2,765.92

JOB NATURE

0000 PB	PANEL BEATING		600.00		<i>420</i>		
0001 SP	SPRAYPAINT CHARGE		500.00		<i>400</i>		
0002 17-01	CHECK ALL LIGHTING		40.00		<i>30</i>		<i>850</i>
0003 23-01	TOWING FEE		0.00		<i>x n n</i>		

SUB-TOTAL : 1,140.00

*2725.12 #
4/5 \$2200, 2 days*

*Tanfah 97495749
'WP'
Lumpsum 4/8/2020 for
Resurvey after repair
tanfah@lkkauto.com
2-3 days
Haw-bwh*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: