

NTUC - LJS

TS

LKK - Taufik

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305414586  
 REGN NO : SHC7042Y  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 04.03.2016  
 DATE/TIME IN : 02.08.2020 19:35  
 ACCIDENT DATE : 02.08.2020

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                          |    |          |       |        |        |
|------|-------------------|--------------------------|----|----------|-------|--------|--------|
| 0001 | 04-01-0103-0579-G | REAR BUMPER              | 1  | 1,106.00 | 20.00 | 884.80 | de ✓   |
| 0002 | 04-01-0103-0738-G | REAR BUMPER UNDER COVER  | 1  | 228.00   | 20.00 | 182.40 | de ✓   |
| 0003 | 04-01-0103-0851-G | REAR BUMPER REFLECTOR LH | 1  | 32.00    | 20.00 | 25.60  | cur ✓  |
| 0004 | 04-01-0103-0739-G | REAR BUMPER SPONGE       | 1  | 119.50   | 20.00 | 95.60  | 7 u7   |
| 0005 | 04-01-0103-0740-G | REAR BUMPER BEAM         | 1  | 428.40   | 20.00 | 342.72 | 7 u7   |
| 0006 | 04-01-0101-0111-G | REAR BUMPER CLIPS        | 10 | 22.00    | 20.00 | 17.60  | nei ✓  |
| 0007 | 04-01-0103-0785-G | BOOTLID MOULDING         | 1  | 85.00    | 20.00 | 68.00  | de ✓   |
| 0008 | 04-01-0103-0786-G | BOOTLID EMBLEM-CRDI      | 1  | 27.90    | 20.00 | 22.32  | nei ✓  |
| 0009 | 04-01-0103-0787-G | BOOTLID EMBLEM-I40       | 1  | 27.90    | 20.00 | 22.32  | nei ✓  |
| 0010 | 04-01-0103-0789-G | BOOTLID EMBLEM-HYUNDAI   | 1  | 21.10    | 20.00 | 16.88  | nei ✓  |
| 0011 | 04-01-0103-0800-G | BOOTLID EMBLEM-H         | 1  | 28.70    | 20.00 | 22.96  | nei ✓  |
| 0012 | 04-01-0103-0581-A | TAILLAMP LH              | 1  | 697.80   | 20.00 | 558.24 | cur ✓  |
| 0013 | 04-01-0103-0584-G | BOOTLID LAMP LH          | 1  | 565.60   | 20.00 | 452.48 | x u7 ✓ |

TS

REPAIR ESTIMATE

NTUC-4S  
LKK-Tanfah

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305414586  
REGN NO : SHC7042Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 04.03.2016  
DATE/TIME IN : 02.08.2020 19:3  
ACCIDENT DATE : 02.08.2020

| JOB / PARTS DESCRIPTION                      | QTY | IND   | UNIT-PRICE | DISC% | AMOUNT   |
|--|-----|-------|------------|-------|----------|
| 0014 28-01-0103-0005-A BOOTLID COMFORTDELGRO | 1   | 30.00 | 10.00      | 27.00 | 27.00 ✓  |
| 0015 28-01-0103-0006-A BOOTLID 65521111      | 1   | 30.00 | 10.00      | 27.00 | 27.00 ✓  |
|  |     |       |            |       | 1875.12  |
| SUB-TOTAL :                                  |     |       |            |       | 2,765.92 |

JOB NATURE

|             |                    |        |       |  |           |
|-------------|--------------------|--------|-------|--|-----------|
| 0000 PB     | PANEL BEATING      | 600.00 | 420   |  |           |
| 0001 SP     | SPRAYPAINT CHARGE  | 500.00 | 400   |  |           |
| 0002 17-01  | CHECK ALL LIGHTING | 40.00  | 30    |  | 850.      |
| 0003 23-01  | TOWING FEE         | 0.00   | x n n |  |           |
|             |                    |        |       |  | 3,905.92# |
| SUB-TOTAL : |                    |        |       |  | 1,140.00  |

Tanfah 97495749  
'WP'  
Lumpsum 4/8/2004pm  
Resurvey after repair  
Tanfah @ lkkauto.com  
2-3 days  
Haw-bwh

2725.12 #  
4/8/2200, 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: