

C. S. ONG AUTO PTE. LTD.

Company & GST Reg No.: 201408916W
10, Ang Mo Kio Ind. Park 2A, #02-16, AMK AutoPoint, Singapore (568047)
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Date: 11/08/2020

Accident Involving Vehicles GBJ786P & SDY9018L [Your Insured] on 29/07/2020 @
1625Hrs along SIMEI STREET 3

Supplementary Parts For GBJ786P [Nissan NV350]

1Pc	Heater Unit	Gr/ Coolant Unit	JN1MC2E28Z0009477	1500	Pn \$	2,243.40	*?
1Pc	Front Bumper Reinforcement Bar	185			Ry \$	250.30	✓
					Parts Total:	\$	2,243.40

Labour & Special Nett Items

* Labour Charge To Remove And Refit Dashboard To Facilitate Repair	\$	1,200.00	250/
* Labour Charge To Remove And Replace Heater Unit	\$	120.00	50/
Labour & Charges Total:	\$	1,320.00	

Parts Total:	\$	2,243.40
Labour & Charges Total:	\$	1,320.00
Total Cost of Repair:	\$	3,563.40
(Non inclusive of 7% GST)		