

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Aug 2020 Edit Reg		04 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: LIM KIM ENG , ID: S0225359C									
Main Claimant: NGUYEN THI THUY NGAN , ID: S9476634F									
Vehicle Reg. No.: SKB51L		Date of Loss: 29/07/2020 21:00 - :59 [119 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9628627105SG		Policy/Cover Note No.: 1900155292 (Comprehensive)							
Vehicle Reg. No. (Insured): SCP800M		Policy No. (Claimant):							
		Excess:							
Repairer: 28 Auto Werks Pte Ltd (HQ) BLK 1002 BUKIT MERAH LANE 3 #01-83, 159719 Bukit Merah - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 17/08/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB51L (9628627105SG)**
[SCP800M]
TP
NGUYEN THI THUY NGAN
Jul 29 2020 9:00PM
[LIM KIM ENG]
28 Auto Werks Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/08/20 12:10	Video - Accident	 Load MOV	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/20 10:33	Chassis Number	 Load JPG	☒
2	13/08/20 10:33	Odometer Reading	 Load JPG	☒
3	13/08/20 10:33	General View	 Load JPG	☒
4	13/08/20 10:33	General View	 Load JPG	☒
5	13/08/20 10:33	General View	 Load JPG	☒
6	13/08/20 10:33	General View	 Load JPG	☒
7	13/08/20 10:33	General View	 Load JPG	☒
8	13/08/20 10:33	General View	 Load JPG	☒
9	13/08/20 10:33	General View	 Load JPG	☒
10	13/08/20 10:33	General View	 Load JPG	☒
11	13/08/20 10:33	General View	 Load JPG	☒
12	13/08/20 10:33	General View	 Load JPG	☒
13	13/08/20 10:33	General View	 Load JPG	☒
14	13/08/20 10:33	General View	 Load JPG	☒
15	13/08/20 10:33	General View	 Load JPG	☒
16	13/08/20 10:33	General View	 Load JPG	☒
17	13/08/20 10:33	General View	 Load JPG	☒
18	13/08/20 10:33	General View	 Load JPG	☒
19	13/08/20 10:33	General View	 Load JPG	☒
20	13/08/20 10:33	General View	 Load JPG	☒
21	13/08/20 10:33	General View	 Load JPG	☒
22	13/08/20 10:33	General View	 Load JPG	☒
23	13/08/20 10:33	General View	 Load JPG	☒
24	13/08/20 10:33	General View	 Load JPG	☒
25	13/08/20 10:33	General View	 Load JPG	☒
26	13/08/20 10:33	General View	 Load JPG	☒
27	13/08/20 10:33	General View	 Load JPG	☒
28	13/08/20 10:33	General View	 Load JPG	☒
29	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
30	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
31	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
32	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
33	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
34	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
35	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
36	13/08/20 10:38	Dismantled Parts	 Load JPG	☒
37	13/08/20 10:38	Dismantled Parts	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
38	13/08/20 10:38	Dismantled Parts		Load JPG	☒
39	13/08/20 10:38	Dismantled Parts		Load JPG	☒
40	13/08/20 10:38	Dismantled Parts		Load JPG	☒
41	13/08/20 10:38	Dismantled Parts		Load JPG	☒
42	13/08/20 10:39	Dismantled Parts		Load JPG	☒
43	13/08/20 10:39	Dismantled Parts		Load JPG	☒
44	13/08/20 10:39	Dismantled Parts		Load JPG	☒
45	13/08/20 10:39	Dismantled Parts		Load JPG	☒
46	13/08/20 10:39	Dismantled Parts		Load JPG	☒
47	13/08/20 10:39	Dismantled Parts		Load JPG	☒
48	13/08/20 10:39	Dismantled Parts		Load JPG	☒
49	13/08/20 10:39	Dismantled Parts		Load JPG	☒
50	13/08/20 10:39	Dismantled Parts		Load JPG	☒
51	13/08/20 10:39	Dismantled Parts		Load JPG	☒
52	13/08/20 10:39	Dismantled Parts		Load JPG	☒
53	13/08/20 10:39	Dismantled Parts		Load JPG	☒
54	13/08/20 10:39	Dismantled Parts		Load JPG	☒
55	13/08/20 10:39	Dismantled Parts		Load JPG	☒
56	13/08/20 10:39	Dismantled Parts		Load JPG	☒
57	13/08/20 10:39	Dismantled Parts		Load JPG	☒
58	13/08/20 10:39	Dismantled Parts		Load JPG	☒
59	13/08/20 10:39	Dismantled Parts		Load JPG	☒
60	13/08/20 10:39	Dismantled Parts		Load JPG	☒
61	13/08/20 10:39	Dismantled Parts		Load JPG	☒
62	13/08/20 10:39	Dismantled Parts		Load JPG	☒
63	13/08/20 10:39	Dismantled Parts		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	06/08/20 12:09	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20008077/QTF3S2**Date:** 21/08/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900155292
Claimant Vehicle No :	SKB51L	Insured Vehicle No :	SCP800M
Date of Loss:	29/07/2020	Nature of Claim:	TP
		Claim No:	9628627105SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB51L		
Make & Model:	BMW 535i GT, 3.0 D/AB 2WD GAS/D TC HUD SR (A)	Engine No:	16037415N55B30A
Reg. Date:	05/08/2010 (Man. Year: 2010)	Chassis No:	WBASN22040C193400
Colour:	Grey	Odometer:	93962 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40ZR20	Rear Tyre Size:	245/40ZR20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/08/2020		
Date Inspected:	11/08/2020	Inspected At:	28 Auto Werks Pte Ltd (HQ) BLK 1002 BUKIT MERAH LANE 3 #01-83 Singapore 159719
Estimated Period of Repair:	2.0 days		

Adjuster: OI SUN PIN**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Crushed	0.00 F	*- F
3	1		*FRT BUMPER	Crushed	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SPONGE UPPER	Crushed	0.00 F	*- F
6	1		*FRT BUMPER SPONGE LOWER	Crushed	0.00 F	*- F
7	1		*FRT BUMPER TOW COVER	Crushed	0.00 F	*- F
8	1		*FRT BUMPER GRILLE RH SIDE	Crushed	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >