

ASS. REC. BY:

REF:

LPC/20008079/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 15/10/20-Typist

Report Format: Merimen

Lump Sum H.B.± (\$ 24,950)

Days Of Repair: 18

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/20/VC00/107792	Date of Loss:	29/07/2020
Vehicle Reg. No.:	GBJ9759J	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	METALIS PTE LTD		
Driver:	LIM TONG YAM		

Make/Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Vehicle Reg. Date:	15/07/2019
Vehicle Colour:	SILVER	Chassis No:	JTFAT35Y10K213675
Engine No:	1KD2860018		
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

21 18 days

For o/s
Not Authorised
Return by paint

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN
Remarks: VEHICLE IS IN. PLS ARRANGE FOR SURVEY ASAP. THANK YOU - SANDRA
Present Location: K KIM HIN AUTO PTE LTD (HQ)

mv 859K

fax 8 62564315

Ex 860dr

COST OF CLAIMS

	Amount
Parts	35,001.45
Miscellaneous Items	0.00
Labour	4,830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	39,831.45
+ GST 7.00% (\$)	2,788.20
Nett Amount (\$)	42,619.65

This claim is handled by: SANDRA KHONG YEE TENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DETAILS

Source:	(Last Synchronised: 04 Aug 2020)
Parts:	N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ9759J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*240.00 F
2	1		*O/S FRONT BUMPER FOG COVER	0.00	0.00	*50.00 F
3	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*135.00 F
4	1		*FRONT BUMPER INNER CROSS MEMBER	0.00	0.00	*350.00 F
5	1		*FRONT GRILLE AND FRONT GRILLE CENTRE BRACKET	0.00	0.00	*220.00 F
6	1		*FRONT GRILLE LOGO	0.00	0.00	*35.00 F
7	10		*FRONT GRILLE CLIPS -VE	0.00	0.00	*35.00 F
8	10		*FRONT GRILLE CLIPS +VE	0.00	0.00	*620.00 F
9	2		*HEADLAMP ASSY LH/RH	0.00	0.00	*460.00 F
10	1		*FRONT PANEL	0.00	0.00	*35.00 F
11	1		*FRONT PANEL DYNA EMBLEM	0.00	0.00	*160.00 F
12	1		*FRONT WIPER PANEL	0.00	0.00	*30.00 F
13	1		*FRONT WIPER PANEL SIDE BRACKET - RH	0.00	0.00	*60.00 F
14	1		*FRONT WIPER ARM - RH	0.00	0.00	*110.00 F
15	2		*FRONT WIPER BLADES LH/RH	0.00	0.00	*18.00 F
16	1		*FRONT WIPER NOZZLE - RH	0.00	0.00	*390.00 F
17	2		*FRONT WIPER LINKAGE	0.00	0.00	*350.00 F
18	1		*FRONT WIPER MOTOR	0.00	0.00	*115.00 F
19	1		*O/S FRONT CORNER PANEL	0.00	0.00	*30.00 F
20	1		*O/S FRONT CORNER PANEL BRACKET	0.00	0.00	*25.00 F
21	1		*O/S FRONT CORNER PANEL INNER SEAL	0.00	0.00	*30.00 F
22	1		*O/S FRONT CORNER PANEL TOP INNER COVER	0.00	0.00	*480.00 F
23	1		*FRONT WINDSCREEN GLASS	0.00	0.00	*110.00 F
24	1		*FRONT WINDSCREEN GLASS RUBBER	0.00	0.00	*580.00 F
25	1		*O/S FRONT DOOR	0.00	0.00	*110.00 F
26	2		*O/S FRONT DOOR HINGES (TOP/LOWER)	0.00	0.00	*65.00 F
27	1		*O/S FRONT DOOR CHECKER	0.00	0.00	*140.00 F
28	1		*O/S FRONT DOOR LOCK	0.00	0.00	*20.00 F
29	1		*O/S FRONT DOOR LOCK CATCH	0.00	0.00	*120.00 F
30	1		*O/S FRONT DOOR STEP GARNISH	0.00	0.00	*35.00 F
31	1		*O/S FRONT DOOR INNER VERTICAL RUBBER	0.00	0.00	*195.00 F
32	1		*O/S FRONT DOOR GLASS	0.00	0.00	*135.00 F
33	1		*O/S FRONT DOOR REGULATOR	0.00	0.00	*195.00 F
34	1		*O/S FRONT DOOR REGULATOR MOTOR	0.00	0.00	*70.00 F
35	1		*O/S FRONT DOOR OUTER MOULDING	0.00	0.00	*60.00 F
36	1		*O/S FRONT DOOR OUTER VERTICAL GARNISH	0.00	0.00	*285.00 F
37	1		*O/S FRONT DOOR INNER TRIMBOARD	0.00	0.00	*95.00 F
38	1		*O/S FRONT DOOR GLASS RUN CHANNEL	0.00	0.00	*85.00 F
39	1		*O/S FRONT DOOR OUTER PULL HANDLE	0.00	0.00	*85.00 F
40	1		*O/S FRONT DOOR INNER PULL HANDLE	0.00	0.00	*125.00 F
41	1		*O/S FRONT DOOR POWER WINDOW CONTROL SWITCH BUTTON	0.00	0.00	*160.00 F
42	1		*O/S FRONT DOOR FRAME WEATHERSTRIP	0.00	0.00	*80.00 F
43	1		*O/S FRONT DOOR WEATHERSTRIP	0.00	0.00	*75.00 F
44	1		*O/S FRONT DOOR INNER MOULDING	0.00	0.00	*170.00 F
45	1		*O/S FRONT DOOR LOCK ACTUATOR	0.00	0.00	*95.00 F
46	1		*O/S FRONT DOOR WHEEL ARCH GARNISH	0.00	0.00	*185.00 F
47	1		*DOOR FRONT OUTER PILLAR - RH	0.00	0.00	*215.00 F
48	1		*DOOR FRONT INNER PILLAR - RH	0.00	0.00	*45.00 F
49	1		*DOOR FRONT INNER PILLAR TOP BRACKET	0.00	0.00	*30.00 F
50	1		*DOOR FRONT OUTER PILLAR EMBLEM	0.00	0.00	*95.00 F
51	1		*O/S FRONT WINDSCREEN PILLAR INNER GARNISH	0.00	0.00	*440.00 F
52	2		*FRONT CABIN MOUNTING LH/RH	0.00	0.00	*330.00 F
53	2		*FRONT CABIN MOUNTING BRACKET LH/RH	0.00	0.00	*440.00 F
54	2		*REAR CABIN MOUNTING LH/RH	0.00	0.00	*290.00 F
55	2		*REAR CABIN MOUNTING BRACKET LH/RH	0.00	0.00	*235.00 F
56	1		*CABIN LOCK	0.00	0.00	*185.00 F
57	1		*CABIN LOCK PULL LEVER	0.00	0.00	*180.00 F
58	1		*CABIN LOCK PULL LEVER LINK	0.00	0.00	*65.00 F
59	1		*CABIN LOCK SAFETY LOCK CATCH	0.00	0.00	

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Particulars	%Disc	%Depr	Amount	
*TILT CABIN SPRING	0.00	0.00	*145.00 F	?
*TILT CABIN TUBE ASSY	0.00	0.00	*320.00 F	?
*AIR RESONATOR BOX	0.00	0.00	*145.00 F	?
*AIR RESONATOR BOX SWITCH	0.00	0.00	*65.00 F	?
*AIR CON BLOWER, AIR CON COOLING COIL AND AIR CON HEATER UNIT	0.00	0.00	*1,200.00 F	?
*AIR CON HEATER UNIT BYPASS HOSE (INLET)	0.00	0.00	*65.00 F	?
*AIR CON HEATER UNIT BYPASS HOSE (OUTLET)	0.00	0.00	*65.00 F	?
*DASHBOARD ASSY	0.00	0.00	*450.00 F	?
*DASHBOARD REINFORCEMENT	0.00	0.00	*360.00 F	?
*DASHBOARD REINFORCEMENT CENTRE BRACKET	0.00	0.00	*115.00 F	?
*O/S DASHBOARD REINFORCEMENT LOWER SIDE BRACKET	0.00	0.00	*130.00 F	?
*DASHBOARD TOP SPEAKER COVER LH/RH	0.00	0.00	*120.00 F	?
*DASHBOARD PASSENGER AIR BAG	0.00	0.00	*1,500.00 F	?
*O/S DASHBOARD SIDE COVER (FOR BRAKE FLUID)	0.00	0.00	*50.00 F	?
*DASHBOARD METER OUTER GARNISH	0.00	0.00	*145.00 F	?
*DASHBOARD METER	0.00	0.00	*1,250.00 F	?
*O/S DASHBOARD CUP HOLDER	0.00	0.00	*70.00 F	?
*O/S DASHBOARD LOWER GARNISH	0.00	0.00	*145.00 F	?
*STEERING BEVEL GEAR	0.00	0.00	*850.00 F	?
*STEERING WHEEL	0.00	0.00	*1,450.00 F	X
*STEERING AIR BAG CLOCK SPRING	0.00	0.00	*185.00 F	?
*STEERING COLUMN AND STEERING COLUMN SHAFT	0.00	0.00	*680.00 F	?
*STEERING COLUMN COVER - TOP	0.00	0.00	*80.00 F	X
*STEERING COLUMN COVER - LOWER	0.00	0.00	*80.00 F	X
*STEERING AIR BAG	0.00	0.00	*1,000.00 F	?
*AIR BAG CONTROL UNIT	0.00	0.00	*480.00 F	?
*AIR BAG CRASH SENSOR LH/RH	0.00	0.00	*290.00 F	?
*STEERING COUPLING YOKE	0.00	0.00	*380.00 F	?
*STEERING COLUMN UPPER BRACKET ASSY	0.00	0.00	*480.00 F	?
*STEERING IGNITION SWITCH	0.00	0.00	*250.00 F	?
*STEERING IGNITION UNLOCK WARNING SWITCH	0.00	0.00	*60.00 F	?
*STEERING SIGNAL / HEADLAMP INDICATOR	0.00	0.00	*165.00 F	X
*STEERING WIPER CONTROL INDICATOR	0.00	0.00	*145.00 F	X
*DRIVERS SEAT BELT	0.00	0.00	*400.00 F	?
*FRONT PASSENGERS SEAT BELT	0.00	0.00	*400.00 F	?
*O/S BRAKE PIPE - UPPER	0.00	0.00	*95.00 F	?
*O/S CLUTCH PIPE - UPPER	0.00	0.00	*95.00 F	?
*O/S BRAKE PIPE - LOWER	0.00	0.00	*95.00 F	?
*O/S CLUTCH PIPE - LOWER	0.00	0.00	*95.00 F	?
*HAND BRAKE PULL CABLE	0.00	0.00	*105.00 F	?
*GEAR CABLE	0.00	0.00	*490.00 F	?
*BRAKE MASTER PUMP	0.00	0.00	*290.00 F	?
*BRAKE BOOSTER PUMP	0.00	0.00	*620.00 F	?
*BRAKE BOOSTER PUMP BRACKET	0.00	0.00	-	?
*BRAKE TANK RESERVOIR	0.00	0.00	*195.00 F	?
*BRAKE FOOT PEDAL	0.00	0.00	*165.00 F	?
*BRAKE FOOT PEDAL BRACKET	0.00	0.00	*310.00 F	?
*CLUTCH MASTER PUMP	0.00	0.00	*95.00 F	?
*CLUTCH MASTER PUMP BRACKET	0.00	0.00	*80.00 F	?
*CLUTCH FOOT PEDAL	0.00	0.00	*135.00 F	?
*CLUTCH FOOT PEDAL BRACKET	0.00	0.00	*175.00 F	?
*FOOT ACCELERATOR PEDAL	0.00	0.00	*210.00 F	?
*RADIATOR ASSY	0.00	0.00	*580.00 F	?
*RADIATOR FAN BLADE	0.00	0.00	*95.00 F	?
*RADIATOR FAN CLUTCH	0.00	0.00	*195.00 F	?
*RADIATOR FAN COWLING	0.00	0.00	*95.00 F	?
*TURBO COOLER	0.00	0.00	*650.00 F	X
*ENGINE MOUNTING LH/RH	0.00	0.00	*120.00 F	?
*GEAR BOX MOUNTING	0.00	0.00	*55.00 F	?
*FLOOR PANEL	0.00	0.00	*950.00 F	?
*FRONT NUMBER PLATE	0.00	0.00	*35.00 FS	X
*FRONT PANEL HEAT INSULATION	0.00	0.00	*180.00 FS	?
*ERP BRACKET	0.00	0.00	*26.00 FS	?
*ERP UNIT	0.00	0.00	*175.00 FS	?
*O/S FRONT DOOR ROC STICKER	0.00	0.00	*25.00 FS	?
*O/S FRONT DOOR SPEAKER	0.00	0.00	*100.00 FS	?
*DASHBOARD TOP SPEAKER LH/RH	0.00	0.00	*240.00 FS	?
*BRAKE OIL	0.00	0.00	*18.00 FS	?
*RADIATOR COOLANT	0.00	0.00	*48.00 FS	?
*FLOOR PANEL HEAT INSULATION	0.00	0.00	*180.00 FS	?

F=Franchise part. S=Spc/lett.

Sub Total (\$\$) 30,570.00
+ Margin on L,N Items 15.00% (\$\$) 4,431.45

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

on Miscellaneous Items
no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
			2100
Labour Items			
		New	2,400.00
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	100.00 ✓
2	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUM AND RECHARGE GAS	New	100.00 601 ✓
3	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	601 80.00
4	TO REMOVE DOORS FITTINGS	New	601 80.00
5	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	2501 280.00
6	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS	New	80.00 ✓
7	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	80.00 ✓
8	TO REMOVE FRONT BRAKE BOOSTER, BRAKE MASTER PUMP AND STEERING COLUMN	New	1400 1,600.00 ✓
9	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	30.00 ✓
10	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION		
Gross Labour Cost (\$\$)			4,830.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 29/07/2020 16:37
Date Of Accident 29/07/2020 12:30
Exact Location Of Accident BKE(WOODLANDS) FROM PIE(TUAS)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ9759J

Insured/Policyholder

Name Of Registered Owner METALIS PTE LTD
Co Reg No 1XXXXX491R
Email Address RICKYHO@METALIS.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-62667555

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA 150-3.0 D 5MT (M)
Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number Z/20/VC00/107792
Cover Note Number

Driver

Name of Driver LIM TONG YAM
NRIC No SXXXX323I
Date Of Birth 03/07/1960
Occupation INDOOR
Date Of Driving Pass 20/06/1978
Driving Experience 42 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-93684591
Fax Number
Contact Number
Email Address NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions HEAVY RAIN
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : TEE BOON HOCK
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ713G
Vehicle Make/Model/Colour NISSAN
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along BKE (broadlands) from PLE (Tyn). After travelling past the bend, vehicle B was stationary ahead of me. By the time I notice the vehicle, it was too late. I could not brake in time and hit onto its rear. The weather condition at that time was heavy rain with poor road visibility. There was no hazard light on or any warning sign from vehicle B. I wish to add that after the collision, EMS was able to start vehicle B to adjust it away from the safety railing to tow the vehicle. Both our vehicles were towed to Barry Farm road heavy vehicle carport by EMS. After that, vehicle B was also shifted onto a low loader tow truck.

No one was injured.

DECLARATION

I/we declare foregoing particulars are true in every respect.


Police Officer's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

SKETCH PLAN

A = G859759J
B = G27134



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along BKE (WOODLANDS) from PIE (THAS). After travelling past the bend, vehicle B was stationary ahead of me. By the time I notice the vehicle, it was too late. I could not brake in time and hit onto its rear. The weather condition at that time was heavy rain with poor road visibility. There was no hazard light on or any warning sign from vehicle B.

I wish to add that after the collision, EMAS was able to start vehicle B to adjust it away from the safety railing to tow the vehicle. Both our vehicles were towed to Dairy Farm road heavy vehicle carpark by EMAS.

After that, vehicle B was also shifted onto a low loader tow truck.

No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: