

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2020 Edit Reg		05 Aug 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS **[Created by adjuster]**

Insured:	DISHA SINGHVI KHOSLA , ID: G0872401L		
Main Claimant:	-		
Vehicle Reg. No.:	SY800B	Date of Loss:	23/07/2020 00:00 - :59 [113 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9820814538SG	Policy/Cover Note No.:	1800042897 (Comprehensive)
Vehicle Reg. No. (Insured):	SLZ2507M	Policy No. (Claimant):	
		Excess:	
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt, 428586 Joo Chiat - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/08/2020]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SY800B (9820814538SG)
[SLZ2507M]

TP

-

Jul 23 2020 12:00AM
[DISHA SINGHVI KHOSLA]
Asia Motorsports Solution Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	05/08/20 15:10	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	05/08/20 15:10	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
4	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
5	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
6	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
7	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
8	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
9	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
10	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
11	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
12	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
13	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
14	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
15	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
16	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
17	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
18	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
19	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
20	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
21	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
22	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
23	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
24	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
25	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
26	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
27	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
28	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
29	05/08/20 15:10	General View							Load JPG	<input checked="" type="checkbox"/>	
30	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
31	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
32	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
33	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
34	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
35	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
36	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
37	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
38	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
39	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	
40	07/08/20 08:52	After Repair Photo							Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	07/08/20 08:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
42	07/08/20 08:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
43	07/08/20 08:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
44	07/08/20 08:52	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
45	08/08/20 13:31	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
46	08/08/20 13:31	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
47	08/08/20 13:31	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
48	08/08/20 13:31	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/08/20 11:49	OI GIA REPORT	Load PDF	
2	21/08/20 10:50	TP GIA report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20008082/UTF3S2**Date:** 24/08/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800042897
Claimant Vehicle No :	SY800B	Insured Vehicle No :	SLZ2507M
Date of Loss:	23/07/2020	Nature of Claim:	TP
		Claim No:	9820814538SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SY800B		
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Engine No:	27186030163055
Reg. Date:	25/01/2011 (Man. Year: 2010)	Chassis No:	WDD2120472A359178
Colour:	Brown	Odometer:	157296 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/08/2020		
Date Inspected:	05/08/2020	Inspected At:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt Singapore 428586
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	0.00 F	*- F
2	1		*SET FRONT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRONT BUMPER SPONGE	Torn	0.00 F	*- F
4	1		*FRONT BUMPER REINFORCEMENT	Repair	0.00 F	*- F
5	1		*HEADLAMP N/S	Cracked	0.00 F	*- F
6	1		*FRONT FENDER N/S	Repair	0.00 F	*- F
Total Parts (\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >