

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLQ6986J
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090576/YISHUN

Date: 05 Aug 2020

Policy No: 5117866873

Veh Reg No: SLQ6986J

Make/Model: HONDA HONDA HRV
1.5 DX CVT

Chassis No: JHMRU1810GX202624

Engine No: L15B4532625

Reg. Date: 19/07/2017

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 04/08/2020

TP Veh Reg No: SLL6818M

Not Authored

Runway B4paim

18 days

Estimate Repair Cost to Vehicle No :SLQ6986J

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	801.70	1 PC	801.70	✓
2 FRONT BUMPER REINFORCEMENT	321.00	1 PC	321.00	✓
3 FRONT BUMPER REINFORCEMENT TOP GARNISHS	24.20	2 PCS	48.40	✓
4 FRONT BUMPER SIDE RETAINERS	17.00	2 PCS	34.00	✓
5 FRONT BUMPER CLIPS	3.90	6 PCS	23.40	✓
6 FRONT GRILLE BASE	351.80	1 PC	351.80	✓
7 FRONT GRILLE MOULDING	385.00	1 PC	385.00	✓
8 FRONT GRILLE TOP GARNISH	85.00	1 PC	85.00	X
9 FRONT GRILLE LOGO	27.40	1 PC	27.40	✓
10 FRONT GRILLE CLIPS	3.90	6 PCS	23.40	✓
11 AIR-CON CONDENSER	750.00	1 PC	750.00	✓
12 RADIATOR	1,250.70	1 PC	1,250.70	✓
13 BONNET	892.50	1 PC	892.50	✓
14 BONNET INNER RUBBER	24.50	1 PC	24.50	X
15 BONNET INNER LOCK	98.50	1 PC	98.50	✓
16 BONNET INNER LOCK GARNISH	41.80	1 PC	41.80	✓
17 HEADLAMPS	1,840.50	2 PCS	3,681.00	✓
18 HEADLAMP LOWER GARNISHS	35.00	2 PCS	70.00	✓
19 FRONT LH FENDER WHEEL ARP GARNISH	195.00	1 PC	195.00	✓
20 REAR RH FENDER INNER GARNISH	250.90	1 PC	250.90	✓
21 REAR FENDER WHEEL ARC GARNISHS	195.00	2 PCS	390.00	✓
22 REAR BUMPER	518.60	1 PC	518.60	✓
23 REAR BUMPER LH REFLECTOR	148.50	1 PC	148.50	✓
24 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
25 REAR SPARE TYRE PANEL COMPARTMENT	693.90	1 PC	693.90	✓
26 REAR SPARE TYRE PANEL UNDER COVER	190.00	1 PC	190.00	✓
27 REAR SPARE TYRE PANEL TOP BOARD	442.00	1 PC	442.00	✓
28 REAR TOOL BOX	156.00	1 PC	156.00	✓
29 REAR CENTRE PANEL	411.90	1 PC	411.90	✓
30 REAR CENTRE PANEL INNER TOP GARNISH	92.30	1 PC	92.30	✓
31 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓

cls? n/s cm

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 04/08/2020
 TP Veh Reg No: SLL6818M

Estimate No: ES2090576/YISHUN
 Date: 05 Aug 2020
 Policy No: 5117866873
 Veh Reg No: SLQ6986J
 Make/Model: HONDA HONDA HRV
 1.5 DX CVT
 Chassis No: JHMRU1810GX202624
 Engine No: L15B4532625
 Reg. Date: 19/07/2017

Estimate Repair Cost to Vehicle No :SLQ6986J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
32 TAILGATE EMBLEM "HR-V"	24.50	1 PC	24.50	✓
33 TAILGATE EMBLEM "I-VTEC"	18.70	1 PC	18.70	✓
34 TAILGATE INNER LOCK	167.00	1 PC	167.00	✓
35 TAILGATE INNER RUBBER	98.50	1 PC	98.50	✓
36 TAILGATE INNER TRIM BOARD	139.60	1 PC	139.60	✓
37 TAILGATE INNER OPENNER HANDLE	22.70	1 PC	22.70	✓
38 TAILGATE OUTER GARNISH	220.00	1 PC	220.00	?
39 TAILGATE REFLECTORS	276.50	2 PCS	553.00	?
40 REAR WINDSCREEN GLASS MOULDING	181.80	1 PC	181.80	✓
41 TAILLAMPS	419.10	2 PCS	838.20	✓
42 REAR SMART KEY SENSOR	85.40	1 PC	85.40	✓
43 REAR EXHAUST PIPE	520.80	1 PC	520.80	✓
44 REAR EXHAUST PIPE HEAT SHIELD	55.00	1 PC	55.00	✓
45 CENTRE EXHAUST PIPE	599.10	1 PC	599.10	✓
			17,047.80	
		Less 20%	3,409.56	13,638.24
Special Net				
46 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
47 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
48 REVERSE SENSOR (4 PCS)	280.00	1 SET	280.00	200.00
			355.00	355.00
Labour				
49 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
50 REMOVE & REFIX REAR SEAT,CARPET, TOP ROOF LINING,ETC	120.00	1 LA	120.00	✓
51 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR SPOILER, THIRD BRAKE LIGHT, REAR WIPER ASSY, LOCK ASSY, TAILGATE, TO CUT, WELD & RENEW REAR PANEL, REAR SPARE TYRE COMPARTMENT, STRAIGHTEN, KNOCK & REPAIR REAR RH CHASSIS, REAR RH FENDER & REALIGN THE SAME	1,600.00	1 LA	1,600.00	1400
52 REMOVE & REFIX REAR UNDER CARRIAGE, EXHAUST ASSY & CHECK EXHAUST SYSTEM	250.00	1 LA	250.00	220

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 04/08/2020
TP Veh Reg No: SLL6818M

Estimate No: ES2090576/YISHUN
Date: 05 Aug 2020
Policy No: 5117866873
Veh Reg No: SLQ6986J
Make/Model: HONDA HONDA HRV
1.5 DX CVT
Chassis No: JHMRU1810GX202624
Engine No: L15B4532625
Reg. Date: 19/07/2017

Estimate Repair Cost to Vehicle No :SLQ6986J

Description	U/Price	Quantity	List Price S\$	Amount S\$
53 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR BOTH FENDERS,REAR PANEL,TAILGATE,REAR BUMPER,REAR RH CHASSIS & REAR AFFECTED AREAS	1,400.00	1 LA	1,400.00	1200
54 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,BONNET & ATTACHMENT,FRT FENDERS,RADIATOR,GRILLE,TO CUT,WELD & RENEW FRT SUPPORT PANEL & REALIGN THE SAME	800.00	1 LA	800.00	500
55 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	?
56 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,FRT FENDERS,SUPPORT PANEL,BONNET & FRT AFFECTED AREAS	800.00	1 LA	800.00	720
57 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
58 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
59 RUSTPROOFING	90.00	1 LA	90.00	✓
60 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
			5,640.00	5,640.00
Total			S\$ 19,633.24	

Add GST @ 7% 1,374.33

Total Amount Payable S\$ 21,007.57

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE