

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2008-092

DATE : 5-Aug-2020

POLICY NO. : AUTO&GEN P10020676R02

VEHICLE REG. NO. : SKD3363G

VEHICLE MAKE : HYUNDAI ELANTRA 1.6 A

TO Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building, Singapore 049711

Tel: 6347 6100

Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper / CR4	1	\$ 480.00	\$ 480.00
2	Front Bumper Clip / Nec	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH / BR	1	\$ 20.00	\$ 20.00
4	Front Bumper Retainer LH X SVC	1	\$ 20.00	\$ 20.00
5	Front Reinforcement / BT	1	\$ 380.00	\$ 380.00
6	Front Reinforcement Bracket RH ?	1	\$ 80.00	\$ 80.00
7	Front Reinforcement Bracket LH ?	1	\$ 80.00	\$ 80.00
8	Front Sponge / Absorber / CR4	1	\$ 100.00	\$ 100.00
9	Front Grille Assy / CR4	1	\$ 160.00	\$ 160.00
10	Front Lower Grille / CR4	1	\$ 180.00	\$ 180.00
11	Front Headlamp RH / CR4	1	\$ 800.00	\$ 800.00
12	Front Headlamp LH / CR4	1	\$ 800.00	\$ 800.00
13	Front Headlamp / Bumper Bracket RH ?	1	\$ 10.00	\$ 10.00
14	Front Headlamp / Bumper Bracket LH ?	1	\$ 10.00	\$ 10.00
15	Front Fender RH X R	1	\$ 480.00	\$ 480.00
16	Front Fender Shield RH X	1	\$ 80.00	\$ 80.00
17	Front Fender Clip X	10	\$ 5.00	\$ 50.00
18	Front Support Panel / PD	1	\$ 980.00	\$ 980.00
19	Front Bonnet / PD	1	\$ 1,180.00	\$ 1,180.00
20	Front Bonnet Hinge RH / BT	1	\$ 60.00	\$ 60.00
21	Front Bonnet Hinge LH / BT	1	\$ 60.00	\$ 60.00
22	Front Bonnet Lock / Jam	1	\$ 60.00	\$ 60.00
23	Front Bonnet Stay Rod X	1	\$ 20.00	\$ 20.00
24	Radiator ?	1	\$ 480.00	\$ 480.00
25	Radiator Fan Assy ?	1	\$ 580.00	\$ 580.00
26	Radiator Side Air Guide RH ?	1	\$ 20.00	\$ 20.00
27	Radiator Side Air Guide LH ?	1	\$ 20.00	\$ 20.00
28	A/C Condenser ?	1	\$ 680.00	\$ 680.00
29	A/C Hose Discharge ?	1	\$ 100.00	\$ 100.00
30	A/C Suction Tube Assy ?	1	\$ 300.00	\$ 300.00
31	Air Filter Box Assy ?	1	\$ 340.00	\$ 340.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2008-092

DATE : 5-Aug-2020

POLICY NO. : AUTO&GEN P10020676R02

VEHICLE REG. NO. : SKD3363G

VEHICLE MAKE : HYUNDAI ELANTRA 1.6 A

TO Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building, Singapore 049711

Tel: 6347 6100

Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Wiper Tank ?	1	\$ 80.00	\$ 80.00
33	Front Horn X SVC	1	\$ 100.00	\$ 100.00
34	Air Intake Duct ?	1	\$ 150.00	\$ 150.00
35	Air Intake Shield ?	1	\$ 20.00	\$ 20.00
36	Rear Bumper / CRU	1	\$ 480.00	\$ 480.00
37	Rear Bumper Clips / NEC	10	\$ 5.00	\$ 50.00
38	Rear Bumper Under Cover / CRA	1	\$ 80.00	\$ 80.00
39	Rear Bumper Retainer RH / BR	1	\$ 30.00	\$ 30.00
40	Rear Bumper Retainer LH / BR	1	\$ 30.00	\$ 30.00
41	Rear Bumper Reflector RH / CRU	1	\$ 50.00	\$ 50.00
42	Rear Bumper Reflector LH / CRU	1	\$ 50.00	\$ 50.00
43	Rear Reinforcement / CRU	1	\$ 300.00	\$ 300.00
44	Rear Tail Lamp RH / SCR	1	\$ 400.00	\$ 400.00
45	Rear Tail Lamp LH X SVC	1	\$ 400.00	\$ 400.00
46	Rear Tail Lamp Clips / NEC	21	\$ 10.00	\$ 210.00
47	Rear Hyundai Logo Emblem / NEC	1	\$ 50.00	\$ 50.00
48	Rear Hyundai Emblem / NEC	1	\$ 60.00	\$ 60.00
49	Rear Elantra Emblem / NEC	1	\$ 60.00	\$ 60.00
50	Rear GLS Emblem / NEC	1	\$ 40.00	\$ 40.00
51	Rear Boot / db	1	\$ 1,580.00	\$ 1,580.00
52	Rear Boot Hinge RH X SVC	1	\$ 80.00	\$ 80.00
53	Rear Boot Hinge LH X SVC	1	\$ 80.00	\$ 80.00
54	Rear Boot Lower Latch X SVC	1	\$ 30.00	\$ 30.00
55	Rear Boot Lock / Jam	1	\$ 130.00	\$ 130.00
56	Rear Boot Rubber Seal / CRU	1	\$ 180.00	\$ 180.00
57	Rear Boot Lamp RH X SVC	1	\$ 280.00	\$ 280.00
58	Rear Boot Lamp LH X SVC	1	\$ 280.00	\$ 280.00
59	Rear License Plate Boot Lamp X SVC	2	\$ 30.00	\$ 60.00
60	Rear / End Panel Garnish / Def.	1	\$ 100.00	\$ 100.00
61	End Panel / db	1	\$ 380.00	\$ 380.00
62	End Panel Inner Bracket X	1	\$ 80.00	\$ 80.00
63	Rear Spare Tyre Top Board X SVC	1	\$ 120.00	\$ 120.00

210

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2008-092
DATE : 5-Aug-2020
POLICY NO. : AUTO&GEN P10020676R02
VEHICLE REG. NO. : SKD3363G
VEHICLE MAKE : HYUNDAI ELANTRA 1.6 ATO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building, Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
64	Rear Spare Tire Sink / PD	1	\$ 380.00	\$ 380.00
65	Rear Fender Inner Shield RH XSV	1	\$ 120.00	\$ 120.00
66	Rear Fender Inner Shield LH XSV	1	\$ 120.00	\$ 120.00
67	Rear Fender Clip XSV	10	\$ 5.00	\$ 50.00
68	Rear Exhaust Muffler / PD	1	\$ 680.00	\$ 680.00
69	Rear Exhaust Rubber Bush / Nec.	2	\$ 30.00	\$ 60.00
Total Spare Parts				\$ 15,900.00
SPECIAL NETT				
70	Front Rear Number Plate with Frame / CRU.	2	\$ 40.00	\$ 80.00
71	Coolant Fluid 4 Litres 2	1	\$ 30.00	\$ 30.00
72	Reverse Sensor / shoy	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 310.00
LABOUR				
73	Spray Painting Whole Front and Whole Rear	1	\$ 1,800.00	\$ 1,800.00
74	Remove and Refit Front & Rear Affected Area	1	\$ 1,800.00	\$ 1,800.00
75	Remove and Refit A/C Condenser, Radiator Including A/C Gas	1	\$ 100.00	\$ 100.00
76	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
77	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
78	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
79	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 3,990.00
Amount Before Excess				\$ 20,200.00
Add GST @ 7%				1,414.00
Total Amount Payable				\$ 21,614.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Repair day - 10 days

Sun Pin (LKK)

05/08/2020

TP without prejudice.

L/S

After pain photo

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: