

Team AutoPro Pte Ltd 160 Sin Ming Drive #02-12 Autocity Singapore 575722

Tel: 8269-9999 Email: teamautopl@gmail.com / teamautooffice@gmail.com

SJE : _____ Vehicle Nos : **SJT 9816 E**
 Date of Survey : _____ Model : Hyundai i30CW
 Date of ReSurvey : _____ After-Paint: _____ Year : _____
 Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear door RH	1	\$ 1,185.00	\$ 996.30 1,185.00	DDV
2	Rear door black tape RH	1	\$ 106.00	\$ 85.60 106.00	NEC
3	Rear door outer handle RH	1	\$ 109.50	\$ 109.50	✓
4	Rear door weatherstrip RH	1	\$ 142.10	\$ 142.10	TNS
5	Rear door outer moulding RH	1	\$ 58.90	\$ 58.90	NDX
6	Rear door regulator RH	1	\$ 451.00	\$ 345.60 451.00	BT
7	Rear door regulator motor RH	1	\$ 334.50	\$ 334.50	NDX
8	Rear door inner lock RH	1	\$ 328.90	\$ 266.50 328.90	JMV
9	Rear door lock striker RH	1	\$ 86.50	\$ 86.50	NDX
10	Rear door hinge RH	2	\$ 82.00	\$ 164.00	NDX
11	Rear door checker arm RH	1	\$ 102.80	\$ 102.80	NDX
12	Rear door inne trimboard RH	1	\$ 577.00	\$ 359.80 577.00	BR
13	Rear door frame rubber RH	1	\$ 106.90	\$ 106.90	NDX
14	Door centre pillar RH	1	\$ 1,572.00	\$ 1,572.00	NDX
15	Rear fender RH	1	\$ 1,243.00	\$ 980.00 1,243.00	DDV
16	Rear fender inner shield RH	1	\$ 163.60	\$ 163.60	NSX
17	Rear side glass moulding RH	1	\$ 131.00	\$ 131.00	NNX
18	Rear bumper	1	\$ 541.30	\$ 485.00 541.30	CUTV
19	Rear bumper side retanier	2	\$ 58.40	\$ 116.80	NDX
20	Roker panel RH	1	\$ 846.30	\$ 682.80 846.30	DDV
21	Rear shock absorber RH	1	\$ 319.60	\$ 276.30 319.60	BT
22	Rear lower arm RH	1	\$ 394.50	\$ 394.50	NDX
23	Rear knuckle arm RH	1	\$ 365.80	\$ 365.80	BT
24	Rear knuckle arm bearing RH	1	\$ 344.20	\$ 344.20	JMV
25	Rear centre arm RH	1	\$ 251.00	\$ 251.00	BT

Parts Sub Total: \$ 5,690.50 10,042.20

Discount 20%: \$ 1,138.10 2,008.44

PARTS TOTAL: \$ 8,033.76

4,552.40

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Rear door sealant RH	1	\$ 100.00	\$ 30.00	NEC
3	Rear door speaker RH	1	\$ 210.00	\$ 210.00	NDX
4	Rear door inner trimboard clips RH	1	\$ 50.00	\$ 30.00	NEC
5	Door centre pillar sealant	1	\$ 100.00	\$ 100.00	NNX
6	Rear fender sealant	1	\$ 100.00	\$ 100.00	NNX
7	Rear fender inner shield clips RH	1	\$ 50.00	\$ 50.00	NLSX
8	Rear side glass sealant	1	\$ 80.00	\$ 30.00	NEC
9	Rear side glass inner seal	1	\$ 60.00	\$ 60.00	NNX
10	Rear side glass primer and cleaner	1	\$ 100.00	\$ 100.00	NNX
11	Rear bumper clips	1	\$ 50.00	\$ 30.00	NEC
12	Roker panel sealant	1	\$ 100.00	\$ 100.00	NNX
13	Rear alloy rim RH	1	\$ 650.00	\$ 650.00	CUT RX
14	Rear tyre RH	1	\$ 380.00	\$ 380.00	NDX
SPECIAL NETT TOTAL:				\$ 320.00	2,110.00

Nos.	LABOUR	S\$	
1	R&R rear door component	\$ 80.00	180.00
2	R&R rear side glass	\$ 70.00	150.00
3	R&R rear under carriage	\$ 100.00	200.00
4	R&R rear tyre and balancing	\$ 20.00	100.00
5	Wheel alignment.	\$ 60.00	120.00
6	Check wiring	\$ 30.00	80.00
7	Upholstery	\$	300.00
8	Diagnose and reset fault code	\$	300.00
9	Rust proofing	\$ 80.00	200.00
10	Panel beat	\$ 1000.00	1,600.00
11	Spray paint	\$ 1200.00	1,600.00
LABOUR TOTAL:		\$	4,800.00

Survey 5/8/2020 Resurvey 6/8/2020
 TGM Mui TGM Mui
 1330 hrs 1545 hrs

Lump sum repair
 Repair days 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

PARTS TOTAL: \$ 8,033.76
 SPECIAL NETT TOTAL: \$ 2,110.00
 LABOUR TOTAL: \$ 4,800.00
 GRAND TOTAL: \$ 14,943.76

PARTS 4552.40
 S/N 320.80
 LABOUR 2650.80
 7522.40
 @ 20% 1504.48
 6017.92

L/S 6,000/2

TGM Mui
 20/8/2020