

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 3-Aug-20

INSURANCE: AIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC2147L

Description	Qty	List Price	Amount
Boot Lid <i>st</i>			
Boot Lid Rubber <i>deformed</i>	1	\$ 2,480.40	\$ 2,480.40
Boot Lid Hinge (LH/RH) <i>HH</i>	1	\$ 187.40	\$ 187.40
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 71.30	\$ 142.60
Boot Lid Lock Upper <i>Dam</i>	2	\$ 86.70	\$ 173.40
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 224.00	\$ 224.00
Emblem-Hybrid <i>Hec</i>	1	\$ 28.00	\$ 28.00
Emblem-Ioniq <i>Hec</i>	1	\$ 24.30	\$ 24.30
Rear Spoiler <i>HH</i>	1	\$ 31.30	\$ 31.30
Third Brake Light <i>HH</i>	1	\$ 665.40	\$ 665.40
Boot Lid Lamp(LH/RH) <i>Crack / broken</i>	1	\$ 385.60	\$ 385.60
Boot Lid Trimboard <i>HH</i>	2	\$ 794.40	\$ 1,588.80
Boot Lid Trimboard Clips (10pcs) <i>HH</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard, Centre <i>HH</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard SIDE (LH/RH) <i>HH</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard REAR <i>HH</i>	2	\$ 92.50	\$ 185.00
Boot Lid Glass Lower Moulding <i>MS</i>	1	\$ 124.80	\$ 124.80
Rear Bumper <i>Dam</i>	1	\$ 145.20	\$ 145.20
Rear Bumper Reinforcement <i>broken</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement Bracket (LH/RH) <i>st / broken</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Centre Moulding Assy <i>Dam</i>	2	\$ 188.10	\$ 376.20
Rear Bumper Lower Centre Moulding Assy <i>st / mounting broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Stay <i>HH</i>	1	\$ 47.50	\$ 47.50
Rear Bumper Side retainer (LH/RH) <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Cover Clips <i>Hec</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Under Centre <i>mounting broken</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Side Under(LH/RH) <i>HH</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Rear Hook <i>HH</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Reflector Lamp(LH/RH) <i>HH</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Towing Cover <i>cd</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket broken</i>	1	\$ 98.80	\$ 98.80
Licence Lamp (LH/RH) <i>HH</i>	1	\$ 328.60	\$ 328.60
Licence Lamp WIRE <i>HH</i>	2	\$ 85.30	\$ 170.60
Tail Lamp(LH/RH) <i>mounting crack</i>	1	\$ 135.80	\$ 135.80
Tail Lamp Quarter Panel(LH/RH) <i>HH</i>	2	\$ 870.40	\$ 1,740.80
Rear Panel <i>Dam</i>	2	\$ 208.90	\$ 417.80
Antenna Assy - TRUNK <i>mounting broken</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>deformed</i>	1	\$ 689.50	\$ 689.50
Spare Tyre Holder <i>HH</i>	1	\$ 346.80	\$ 346.80
Spare Wheel Lock Nut <i>HH</i>	1	\$ 223.10	\$ 223.10
Spare Tyre Panel <i>Dam</i>	1	\$ 89.50	\$ 89.50
Member Assy-Rear Floor Centre <i>HH</i>	1	\$ 892.50	\$ 892.50
	1	\$ 863.50	\$ 863.50

anel Assy-Rear Floor Side (LH/RH) HH			
Rear tray tools box RH not broken	2	\$ 39.40	\$ 78.80
Rear tray tools box LH detached 1st	1	\$ 675.30	\$ 675.30
REAR TRAY LUGGS CENTER detached	1	\$ 693.20	\$ 693.20
Exhaust Pipe Insulator HH	1	\$ 354.20	\$ 354.20
Exhaust Silencer 1st	1	\$ 235.00	\$ 235.00
Exhaust Pipe Hanger HH	1	\$ 943.50	\$ 943.50
	1	\$ 29.20	\$ 29.20
1374.40	SUB TOTAL		
	LESS 20%		\$ 19,046.30
10987.52	DISCOUNTED TOTAL		\$ 3,809.26
			\$ 15,237.04
Reverse camera ASSY HH	SN	1	\$983.20
Boot Lid Comfort Logo & Tel No. Sticker HH	SN	1	\$ 35.00
Rear No. Plate + Trim Cover detached	SN	1	\$ 45.00
Rear Windscreen Sealant HH	SN	1	\$ 46.00
Rear Bumper Rubber Mat HH detached	SN	1	\$ 50.00
Rear Bumper Reverse Sensor Down	SN	1	\$ 180.00
SPARE TYRE PANEL TOP COVER SILICON HH	SN	1	\$ 250.00
356.00	SUB TOTAL		\$ 1,589.20
Labour Charge			
Panel Beating			
Spray Painting Charge	1	\$1,200.00	\$1,200.00
Wiring Charge	1	\$1,000.00	\$1,000.00
Tuff Kote	1	\$140.00	\$140.00
Towing Charge	1	\$120.00	\$120.00
Remove/Refix Rear Windscreen Glass	1	\$80.00	\$80.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Exhaust Pipe	1	\$120.00	\$120.00
Re-set Frt ABS System	1	\$80.00	\$80.00
Diagnostic & Resetting To Erase Fault Code	1	\$200.00	\$200.00
	1	\$550.00	\$550.00
TOTAL LABOUR			\$3,610.00
ESTIMATE TOTAL			\$ 20,436.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

05/08/2020 2:17:02

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

05/08/2020 @ 1700hrs

Not Attached

Part by Part. 88

8 days

Jan

2KK Auto

Photo after repair
with damaged
parts.

7/P 12993.52