

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008100/KRA3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SHC5808T

Insured Vehicle No : GBG675S

Date of Loss: 29/07/2020

Nature of Claim: TP

Claim No: 7190236372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5808T**

Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C002670

Reg. Date: 03/08/2015 (Man. Year: 2015)

Chassis No: VF1ABL15AUC282209

Colour: Metallic White/Red

Odometer: 555585 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Sailun 8 mm

Rear Left Side:

Giti 8 mm

Front Right Side: Sailun 8 mm

Rear Right Side:

Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,380.79	135.00	10,245.79	98.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,310.00	870.00	4,440.00	83.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,690.79	1,005.00	14,685.79	93.59
+ GST 7.00/7.00% (S\$)	1,098.36	70.35	1,028.01	93.59
Nett Amount (S\$)	16,789.15	1,075.35	15,713.80	93.59
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$81.13/day) (S\$)		162.26		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,345.10		

INSPECTION

Date of Assignment: 03/08/2020

Date Inspected: 03/08/2020 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
2	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
3	1		*DOOR PANEL FRONT RH	Repair	2,844.66 FL	*- FL
4	1		*DOOR LOCK FRT RH	Serviceable	908.75 FL	*- FL
5	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
6	1		*DOOR HANDLE CAP FRT RH	Serviceable	35.52 FL	*- FL
7	1		*DOOR HANDLE SEAL FRT RH	Serviceable	7.89 FL	*- FL
8	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*- FL
9	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
10	1		*DOOR SEAL FRT RH	Serviceable	72.82 FL	*- FL
11	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.27 FL	*- FL
12	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
13	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
14	1		*RH SIDE RENAULT TYRE	Serviceable	300.00 FS	*- FS
15	1		*RH SIDE RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS
16	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
17	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
18	1		*ROCKER PANEL CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,422.54	135.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,041.75	0.00
Total Parts (\$)	10,380.79	135.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,000.00	200.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
4	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	660.00
Gross Labour Cost (\$\$)			5,310.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >