

ASS. REC. BY:

REF:

A/G/ 200081001Kd

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 58087

Yr Regn:

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault

Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

555585

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFIABL15AUC 282209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F: Sailun

215/60R16

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/7/20

D.O.I.

3/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/8 @ 1005h confirm

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Not Authorised
81005/1

Trans-cab Auto Services Pte Ltd

AAD2007-116

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5808T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 AUG 2020

SHC 5808T

VF1ABL15AUC282209

RENAULT

LATITUDE

29.7.2020

AIG

03/08/2015

PART	
1	DOOR PANEL REAR RH
1	ROCKER PANEL OUTER RH
1	DOOR PANEL FRONT RH
1	DOOR LOCK FRT RH
1	DOOR HANDLE OUTER FRT RH
1	DOOR HANDLE CAP FRT RH
1	DOOR HANDLE SEAL FRT RH
1	DOOR HANDLE COVER FRT RH
1	DOOR HANDLE MODULE FRT RH
1	DOOR SEAL FRT RH
1	DOOR WEATHERSTRIP FRT RH
1	DOOR MIRROR ASSY RH

LIST	
\$	11 2,844.66
\$	11 1,184.99
\$	11 2,844.66
\$	11 908.75
\$	11 477.76
\$	11 35.52
\$	11 7.89
\$	11 13.22
\$	11 133.60
\$	11 72.82
\$	11 410.27
\$	11 1,483.40
TOTAL	\$ 10,417.54
10%	\$ 1,041.75
	\$ 9,375.79

Special Nett	
1	REAR DOOR STICKER '6555-3333'
1	RH SIDE RENAULT TYRE
1	RH SIDE RENAULT TYRE RIM
1	FRONT DOOR STICKER "Trans-Cab"
1	FRONT DOOR STICKER "Classic"
1	ROCKER PANEL CLIP

\$	11 100.00	60511
\$	11 300.00	X
\$	11 380.00	X
\$	11 80.00	60511
\$	11 80.00	15511
\$	11 65.00	X
TOTAL	\$ 1,005.00	

TOTAL PARTS \$ 10,380.79

Trans-cab Auto Services Pte Ltd**AAD2007-116**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5808T**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	2001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To rust-proofing and apply undercoat of the affected areas.	\$	nn 250.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
Putty and spray painting of the affected portion.	\$	2,000.00	6601
TOTAL	\$	5,310.00	
Over All Total	\$	15,690.79	

LUMP SUM (REPAIR DAY)**20 DAYS**
2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5808T

AAD2007-116

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5808T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Jul 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002670
Chassis No.:	VF1ABL15AUC282209
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Aug 2015
First Registration Date:	03 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Aug 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	02 Aug 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,236.00
COE Rebate Amount:	\$18,889.00
Total Rebate Amount:	\$33,887.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Jul 2020

OK