

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20008102/R1BS3Q2

**Date:** 14/09/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMP6137L	<b>Insured Vehicle No :</b>	SHD4652B
Date of Loss: 01/08/2020	Nature of Claim: TP	Claim No: MCT20080280

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6137L		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHT2294
Reg. Date:	02/10/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH001917
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,038.00	2,588.00	450.00	14.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,185.00	4,005.00	1,180.00	22.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>8,223.00</b>	<b>6,593.00</b>	<b>1,630.00</b>	<b>19.82</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	575.61	461.51	114.10	19.82
<b>Nett Amount (\$\$)</b>	<b>8,798.61</b>	<b>7,054.51</b>	<b>1,744.10</b>	<b>19.82</b>
<b>+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (\$\$)</b>		1,070.00		
<b>Nett Liability (\$\$)</b>		<b>8,124.51</b>		

### INSPECTION

Date of Assignment:	05/08/2020	
Date Inspected:	05/08/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

**Adjuster:** MOHD RASUL

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 02 Sep 2020)	
<b>Parts:</b>	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP6137L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE ,FR BUMPER	Scratched	703.00 FS	*703.00 FS
3	1		*BRACKET ,FR BUMPER LH	Necessary	13.00 FS	*13.00 FS
4	1		*FENDER ,FR LH	Bent	497.00 FS	*497.00 FS
5	1		*GARNISH ,FR PILLAR ,LH	Scratched	30.00 FS	*30.00 FS
6	1		*MIRROR ASSY ,DOOR ,LH	Scratched	638.00 FS	*638.00 FS
7	1		*COVER ,DOOR MIRROR ,OTR LH	Repair	114.00 FS	*- FS
8	1		*WHEEL DISC	Scratched	687.00 FS	*687.00 FS
9	1		*HUB ASSY ,FR WHEEL	Serviceable	215.00 FS	*- FS
10	1		*BEARING ,FR WHEEL HUB	Serviceable	121.00 FS	*- FS
<b>Total Parts (\$)</b>					<b>3,038.00</b>	<b>2,588.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	ACCIDENT TOWED IN FROM AIRPORT RD TO CNC PG	New	85.00	85.00
2	RENEW FRT BUMPER ,FRT FENDER ,LH ,WINDMIRROR LH ,REPAIR FRT DOOR LH ,REAR DOOR LH	New	2,200.00	1,650.00
3	SPRAY PAINT FOR FRT BUMPER ,FRT FENDER LH ,FRT DOOR LH REAR DOOR LH ,WINDMIRROR LH	New	2,520.00	1,890.00
4	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
5	TRANSFER NEW RIM	New	30.00	30.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,185.00</b>	<b>4,005.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >