



Exceptional Journeys

Surveyor : Rasul - LKK
Company : India
DOA : 01/08/2020
CSE : Coco
Date of Survey : 05/08/2020

VEHICLE NO : SMP6137L
MODEL : MIT/19MY ATTRAGE 1.2 CVT
WIP : 55673

Material	:	\$	2,568.00
Labour	:	\$	4,025.00
Sub-Total	:	\$	6,593.00
Less Excess	:	\$	-
Total	:	\$	6,593.00
GST 7%	:	\$	461.51
Grand Total	:	\$	7,054.51
Finalise By/Date	:	JoJo dtd	17/08/2020

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 7 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
+ 1 Survey - 05/08/2020 - Wed
TOTAL DAYS REPAIR TOOK = 10

☒ TP Claim India - SHD4652B

☐ Claim GIA / LTA fee

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CYCLE & CARRIAGE LEASING PTE LTD	Cust No/Name KC000162/ CYCLE & CARRIAGE LEASING PTE L
239 ALEXANDRA ROAD	Reg No/Reg Date SMP6137L / 02/10/201
SINGAPORE 159930	Date In/Mileage / 0
Contact No Mobile: 85188668	Chassis No MMBSTA13AKH001917
	Engine No 3A92UHT2294
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	04/08/2020/ 17:51	TLC	442 / CocoLu	55673

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER LH, WINDMIRROR LH, REPAIR FRT DOOR LH, REAR DOOR LH				1650 2280.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH REAR DOOR LH, WINDMIRROR LH				1890 2520.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TRANSFER NEW RIM				30.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY Sundry				20.00
M FACE,FR BUMPER	1.00	703.00	00.00	703.00
M BRACKET,FR BUMPER,LH	1.00	13.00	00.00	13.00
M FENDER,FR LH	1.00	497.00	00.00	497.00
M GARNISH,FR PILLAR,LH	1.00	30.00	00.00	30.00
M MIRROR ASSY,DOOR,LH	1.00	638.00	00.00	638.00
M COVER,DOOR MIRROR,OTR LH	1.00	114.00	00.00	114.00
M WHEEL,DISC	1.00	687.00	00.00	687.00
M HUB ASSY,FR WHEEL	1.00	215.00	00.00	215.00
M BEARING,FR WHEEL HUB	1.00	121.00	00.00	121.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:


REMARKS:

Confirm & accepted by

Nett 8,138.00
7% GST on 8138.00 569.66
Total Payable 8,707.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04-05 IOB BUILDING SINGAPORE 049711 Contact No 06/08/2020	Cust No/Name KC000162/ CYCLE & CARRIAGE LEASING PTE L Reg No/Reg Date SMP6137L / 02/10/2019 Date In/Mileage 06/08/2020/ 21352 Chassis/Package MMBSTA13AKH001917 Engine No 3A92UHT2294 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	17/08/2020/ 11:01	TLC	881 / Jojo Cheng	55673		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, LH FRONT FENDER, LH WINDMIRROR, REPAIR LH FRONT DOOR, LH REAR DOOR							✓ 1650.00
E PNT98000 SPRAY PAINT FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR LH REAR DOOR, LH WINDMIRROR							✓ 1890.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							✓ 120.00
M SUNDRY TRANSFER NEW RIM							✓ 30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							✓ 200.00
M SUNDRY SUNDRY							✓ 20.00
S SPECIALISTJOB WO:1239271 ACCIDENT TOWED IN FROM AIRPORT RD TO CNC PG - <i>Supp</i>							85.00
X	FACE,FR BUMPER			1.00	703.00	00.00	✓ 703.00
X	BRACKET,FR BUMPER,LH			1.00	13.00	00.00	✓ 13.00
X	FENDER,FR LH			1.00	497.00	00.00	✓ 497.00
X	GARNISH,FR PILLAR,LH			1.00	30.00	00.00	✓ 30.00
X	MIRROR ASSY,DOOR,LH			1.00	638.00	00.00	✓ 638.00
X	WHEEL,DISC			1.00	687.00	00.00	✓ 687.00
Z	TEXT INDIA TP CLAIM SHD4652B DOA: 01/08/2020 SURVEYOR: RASUL LKK 05/08/2020						
Guarantee Your Warranty, Maintain with Cycle & Carriage!							
Parts	2,568.00					Nett	6,593.00
Labour	3,890.00				7% GST on	6593.00	461.51
Standard Menu	0.00						
Specialist Job	85.00					Total Payable	7,054.51
Diagnostics Job	0.00						
Sundry/Others	50.00						
Total(w/o GST)	6,593.00						

This is not an official tax invoice.
This is a computer generated document, no signature is required.

Work Order: R001127
 License: SMP 6137 L
 Technician: 106 WENG SOON
 Mileage: 29534
 Date: 12.8.20 17:01

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°39'	-0°41'*	-0°40' 0°50'
3°51'	3°48'	3°15' 4°45'
0°00'	0°12'*	-0°07' 0°07'
13°22'*	13°01'	10°05' 13°05'
12°43'	12°21'	9°25' 13°55'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°37'	-0°36'	-0°40' 0°50'
4°15'	4°19'	3°15' 4°45'
0°00'	0°03'	-0°07' 0°07'
13°28'*	13°19'*	10°05' 13°05'
12°50'	12°44'	9°25' 13°55'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°02'	-0°05'	-0°30' 0°30'
-0°26'	-0°31'*	-0°30' 0°30'
-0°06'	-0°18'	
0°00'	0°15'*	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°58'	-0°58'	-1°45' -0°15'
0°09'	0°09'	-0°01' 0°13'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°53'	-0°53'	-1°45' -0°15'
0°01'	0°01'	-0°01' 0°13'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°05'	-0°05'	-0°30' 0°30'
0°11'	0°10'	-0°02' 0°26'
0°04'	0°04'	

* This value is not within specification. Tire wear, handling and safety problems may result.