

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PARK CHUL
 BLK 261C SENGKANG EAST WAY
 #04-506
 SINGAPORE 543261

Estimate No: MC1901321
 Date: 04 Aug 2020
 Policy No: P10386857R00
 Veh Reg No: SJR2463X
 Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 31/07/2020
 TP Veh Reg No: SMF8976X

Not Notion
11/8
Repair After Paint 2 days

Estimate Repair Cost to Vehicle No :SJR2463X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 HEADLAMP RH	1 PC	<i>Sm</i> 608.70	X
2 FRONT BUMPER	1 PC	<i>CM</i> 581.70	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	<i>Di?</i> 63.40	—
4 FRONT BUMPER CLIPS	10 PC	<i>na</i> 45.00	—
5 FRONT BUMPER REINFORCEMENT	1 PC	<i>R</i> 334.50	X
6 FOGLAMP RH	1 PC	<i>Sm</i> 298.60	X
7 FOGLAMP COVER RH	1 PC	<i>Sm</i> 105.67	✓
8 FRONT FENDER RH	1 PC	<i>R</i> 712.10	✓
9 FRONT FENDER COWLING RH	1 PC	<i>Sm</i> 196.50	✓
10 FRONT FENDER COWLING CLIPS	8 PC	<i>na</i> 25.68	X
		2,971.85	
	Less 25%	742.96	2,228.89
Special Nett			
11 SPORT RIM RHR -CHECK PRICE	1 PC	<i>Sm</i> 0.0000	X
		0.00	0.00
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
13 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	<i>na</i> 80.00	X
14 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	200/
15 TO SPRAY FRONT BUMPER, FRONT FENDER RH, RADIATOR SUPPORT PANEL	1 PC	500.00	200/
		1,120.00	1,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : PARK CHUL
BLK 261C SENGKANG EAST WAY
#04-506
SINGAPORE 543261

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF8976X

Estimate No: MC1901321
Date: 04 Aug 2020
Policy No: P10386857R00
Veh Reg No: SJR2463X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Estimate Repair Cost to Vehicle No :SJR2463X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 3,348.89
		Add GST @ 7%	234.42
		Total Amount Payable	<u>S\$ 3,583.31</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS THIRTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

