

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: PARK CHUL
 BLK 261C SENGKANG EAST WAY
 #04-506
 SINGAPORE 543261

Estimate No: MC1901321
 Date: 04 Aug 2020
 Policy No: P10386857R00
 Veh Reg No: SJR2463X
 Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 31/07/2020
 TP Veh Reg No: SMF8976X

Not Authorized
11 Aug 8
Returning After Paint 2 days

Estimate Repair Cost to Vehicle No :SJR2463X

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	608.70	7
2 FRONT BUMPER	1 PC	581.70	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	63.40	✓
4 FRONT BUMPER CLIPS	10 PC	45.00	✓
5 FRONT BUMPER REINFORCEMENT	1 PC	334.50	X
6 FOGLAMP RH	1 PC	298.60	X
7 FOGLAMP COVER RH	1 PC	105.67	X
8 FRONT FENDER RH	1 PC	712.10	X
9 FRONT FENDER COWLING RH	1 PC	196.50	X
10 FRONT FENDER COWLING CLIPS	8 PC	25.68	X
		2,971.85	
	Less 25%	742.96	2,228.89
Special Nett			
11 SPORT RIM RHR -CHECK PRICE	1 PC	0.0000	X
		0.00	0.00
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
13 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
14 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	200/
15 TO SPRAY FRONT BUMPER, FRONT FENDER RH, RADIATOR SUPPORT PANEL	1 PC	500.00	200/
		1,120.00	1,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: