

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PARK CHUL
BLK 261C SENGKANG EAST WAY
#04-506
SINGAPORE 543261

Estimate No: MC1901321
Date: 04 Aug 2020
Policy No: P10386857R00
Veh Reg No: SJR2463X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF8976X

Estimate Repair Cost to Vehicle No :SJR2463X

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	608.70	
2 FRONT BUMPER	1 PC	581.70	
3 FRONT BUMPER SIDE RETAINER RH	1 PC	63.40	
4 FRONT BUMPER CLIPS	10 PC	45.00	
5 FRONT BUMPER REINFORCEMENT	1 PC	334.50	
6 FOGLAMP RH	1 PC	298.60	
7 FOGLAMP COVER RH	1 PC	105.67	
8 FRONT FENDER RH	1 PC	712.10	
9 FRONT FENDER COWLING RH	1 PC	196.50	
10 FRONT FENDER COWLING CLIPS	8 PC	25.68	
		2,971.85	
	Less 25%	742.96	2,228.89
Special Nett			
11 SPORT RIM RHR -CHECK PRICE	1 PC	0.0000	
		0.00	0.00
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
13 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
14 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
15 TO SPRAY FRONT BUMPER, FRONT FENDER RH, RADIATOR SUPPORT PANEL	1 PC	500.00	
		1,120.00	1,120.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : PARK CHUL
BLK 261C SENGKANG EAST WAY
#04-506
SINGAPORE 543261

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 31/07/2020
TP Veh Reg No: SMF8976X

Estimate No: MC1901321
Date: 04 Aug 2020
Policy No: P10386857R00
Veh Reg No: SJR2463X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Estimate Repair Cost to Vehicle No :SJR2463X

Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 3,348.89
Add GST @ 7%			234.42
Total Amount Payable			S\$ 3,583.31

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FIVE HUNDRED EIGHTY THREE AND CENTS THIRTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

