

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008107/R1VF3E2

Date: 08/09/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00030232000

Claimant Vehicle  
No : SMQ6079RInsured Vehicle  
No : GBH3277H

Date of Loss: 02/08/2020

Nature of Claim: TP

Claim  
No: SNM20D202733C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ6079R**

Make &amp; Model: TOYOTA PRIUS PLUS, 1.8 (A)

Engine No: 2ZR2F75565

Reg. Date: 26/11/2019 (Man. Year: 2019)

Chassis No: JTDZS3EU80J051934

Colour: Grey

Odometer: 28440 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	50.00	30.00	20.00	40.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,817.50	1,490.00	327.50	18.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,867.50</b>	<b>1,520.00</b>	<b>347.50</b>	<b>18.61</b>
<b>+ GST 7.00/7.00% (S\$)</b>	130.73	106.40	24.33	18.61
<b>Nett Amount (S\$)</b>	<b>1,998.23</b>	<b>1,626.40</b>	<b>371.83</b>	<b>18.61</b>

### INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 06/08/2020 Inspected At:

Borneo Motors (S) Pte Ltd (Leng Kee)  
33 Leng Kee Road  
Singapore 159096

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 08 Sep 2020)

**Parts:** M1-MPV      TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMQ6079R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>50.00</b>	<b>30.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RESET AND REPROGRAMME ECU	New	180.00	180.00
2	REMOVE AND REALIGN FRT BUMPER	New	900.00	720.00
3	RESPRAY FRT BUMPER	New	737.50	590.00
<b>Gross Labour Cost (S\$)</b>			<b>1,817.50</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >