

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Shawn Ngo Sau Wei

Date: 07 Aug 2020

Preliminary Advice

Insured Vehicle No	: SMC1702G	Accident Date	: 03/08/2020
TP Vehicle No	: SJY5616R	Assignment Date	: 05/08/2020
Make	: AUDI A4	Est. Duration of Repair	: 5
Date of Inspection	: 07/08/2020		
Inspection At	: AUBURN AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,903.00
Revised Amount	:S\$	5,500.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,500.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- () The above survey was conducted on a 'without prejudice' basis.