

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLR 4448D

Vehicle Model : KIA CERATO K3 SUNROOF

Accident Date : 02.08.2020

Original Reg Date : 16.08.2017

Date : 11.08.2020

Chassis : KNAFZ411MH5720550

TP Ins. CHINA

ESTIMATE

1	1 pc	Front Bumper	920	?
2	1 pc	Front Bumper Badge	50	ni ✓
3	2 pcs	Front Bumper Side Retainers	78	LH ✓, RH ✓
4	1 set	Front Bumper Clips	40	ni ✓
5	1 pc	Front Bumper Reinforcement	420	?
6	1 pc	Front Bumper Sponge	172	?
7	1 pc	Front Bumper Lower Grille	169	X
8	1 pc	Front Bumper Number Plate Base	112	?
9	2 pcs	Front Bumper Sensor	370	LH ✓, RH ✓
10	2 pcs	Front Bumper Sensor Holder	70	X
11	1 pc	Front Bumper Fog Lamp RH	356	X
12	1 pc	Front Grille	478	?
13	1 pc	Front Grille Chrome Moulding	136	?
14	1 set	Front Grille Clips	30	ni ✓
15	1 pc	Headlamp LED LH	2,209	?
16	1 pc	Headlamps Bottom Retainers LH	72	?

Less 10%

Special Nett

1	1 pc	Front Bumper Lower Spoiler	?	1,000.00
2	1 pc	Front Number Plate with Cover	bt ✓ 45	70.00

Labour charge

Panel Beating		300.	600.00
Spray painting		400.	600.00
Check Wiring		20.	30.00
Anti rust		X	30.00
Remove and install front sensor.		30	70.00

2,400.00

Less 20%

480.00

1,920.00

Taufik 97495749
- WP 12/8/2020 1115.

3 days - 4 days tafik @ 1/10/2020
Lump sum
Resolving after repair

920
52
39
40
420
172

112
185

xx
xx

478
136
30
2209
72

xx
45
xx
30

300
400
20

30

Total List Price	\$	4,865.00
Discount		10%
List Price (after Discount)	\$	4,378.50
Total Nett Price	\$	-
Discount		10%
Nett Price (after Discount)	\$	-
Total Special Nett	\$	45.00
Total Labour	\$	750.00
Grand Total	\$	5,173.50
Discount 20%		20%
Lump Sum Repair Cost	\$	4,138.80

\$ 4,150.00

Vehicle no: SLR 4448D DOA: 02.08.2020

Model: KIA CERATO K3 SUNROOF

TP Ins: CHINA

Columns			
A	List Price		
B	Nett Price		
C	Special Nett		
D	Labour		